

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 08/27/90	DATE OPENED 09/06/90	DATE CODE LW 2-72	SERIAL NUMBER 6520090	MODEL AND GRADE 700 25-06 ADL		ORDER R 90-23260	
ACCESSORIES W/STUDS		SCOPE BASE					

FROM:

VALLEY GUNS INC.
RT 2 BOX 341
BUNKER HILL WV 25413

SHIP TO:

VALLEY GUNS INC.
RT 2 BOX 341
BUNKER HILL

WV
25413

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-------------------

REPAIR CHARGE						TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	--	--	--	--	--	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"i.e. rifle fired when safety was released from on-safe to off-safe"

MAIN FAULT

no fault found - trigger assembly operate properly. Trigger has been adjusted outside factory as indicated by red indicator all 3 adjustment screws. Trigger pull 3#, near-tight, ok"
cannot duplicate complaint.

PARTS

Offer to return rifle as-is or, as a gesture of good-will offer to replace the trigger assembly at normal price, ~~if it will restore confidence in the rifle.~~

Rifle is 18 years old

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

PS06434