## Remington Arms Co., Inc. Product Service Legal Case #:2361

Case Information
------------------

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

144847 4/24/2008 4/25/2008 4/25/2008

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Joseph Leon- 4915 Sherlyn Ave Port WA 98367 H 360-876-0591 E ursula@leon-guerrero.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4015 Improper Maintenance

S fires on safe release Concern:1007 Fired on Safe Release Unknown

C

4/29/08-correspondence from repair-firearm would sometimes accidentally fire while moving the safety from safe to fire. lw

## Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/7MM RM
 20000
 B6603856
 OE 7/1/1984

Date
Purchased Where Purchased Accessories Original
Owner

UWNER
SOUTHERN GUN OPALI OCKA TWO PIECE SCOPE

SOUTHERN GUN OPA-LOCKA TWO PIECE SCOPE FL BASE

## CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

## Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Replace TA at discount

Repair/Replacement Cost Repair/Replacement Date

4/29/08-quote sent to replace ta at discount.lw


Examination[Remington|CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		4/25/2008	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2361&Type=Case

4/30/2008

	Assigned To	j	F.SUPRY
Cause	4015	Improper Maintenance	
	Description		24" 7MM RM
	Date Code		OE
	Bore Plugged	False	
Dame1	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	]
	Stop	Slightly Worn; Functioning	]
	Condition	Slightly Worn; Functioning	]
Extractor	Cut Condition	Slightly Worn; Functioning	]
	Ext/Eject Test	False	]
	Block Condition	Select	]
Locking	Lug Condition	Slightly Worn; Functioning	]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	]
Overall	Stock Condition	Slightly Worn; Functioning	]
	Fore End Condition	Select	]
Receiver	Condition	Slightly Worn; Functioning	]
Receiver	Bulged	False	
	Description	]	STANDARD M/700 SAFETY
Safety	Function	Slightly Worn; Functioning	]
	Sub-Assembly	Non-ISS	]
	Lift	Select	.015
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	10303	False	]
	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTED HARD OFF SAFE
Trigger	Pull	Select	6#
	Altered	False	]
	Sub-Assembly	M/700 Non-Bolt Lock	]
Non-Remington Components	Description		TWO PIECE SCOPE BASE



April 19, 2008

Remmington Arms Co. 14 Hoefler Avenue Ilion, NY 13357

RE:

7mm Magnum Model #700 Serial #B6603856

To Whom It May Concern:

In 1984, I purchased this rifle. When in lock and load and <u>not</u> touching the trigger, this firearm would sometimes accidentally fire while moving the safety switch from "S" position the "F" position. Because of this, I have not fired the rifle more than 50 rounds.

I understand there may be a recall on this model. If so, please repair/replace as necessary. If there is no recall, I would like to have my rifle repaired. Please contact me as to the cost and I can give you billing information.

Please contact me with any questions or further information at 360.876.0591 or we sula @lean-querrer

Thank you for your help.

Sincerely,

Joseph Leon-Guerrero 4915 Sherlyn Avenue SE Port Orchard, WA 98367

B6603856

Model: 700

MILLIANT TO THE PARTY OF THE PARTY

Tity ASSM DIRTY, Triq. + Tili Pin Rusted & Binding. Ruplace TRA, check own, clean At 1/2 Normal chang Quote