

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2004

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
139765	1/14/2008	1/15/2008	1/22/2008				

## Customer Information

Type	Business First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bryan	Lovelace	2288 East Stewart Road	Midland	MI	48640		H 989-631-5894 C 989-430-2066 E BSLovelace@chartermi.net

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD shot truck tailgate	Cause:4038	Could Not Duplicate Concern		Unknown
S fired with safety on	Concern:1005	Unexplained Discharge Safe ON		
C				

correspondence from repair-rifle fired with safety on. Shot tailgate.lw

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM RUM	26269	E6767955	WV	8/16/2001 7:04:42 PM

Date Purchased	Where Purchased	Accessories	Original Owner
	JERRY S SPORT INC		U

CONCERN:WENT OFF ON IT'S OWN

## Ammunition Information - None Defined

## Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace in exchange w/ 84300						

Repair/Replacement Cost	Repair/Replacement Date
245	1/22/2008

1/22/08-offered replacement TPA. Cust asked about damage to truck, offered to replace firearm instead as compensation. Customer agreed.lw

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/15/2008
	Product Type		RF
	Action Type		A

	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 7MM RUM
	Date Code		WV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	LIGHT RUST
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.014
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

LAURA  
We tried to get this gun to malfunction and could not. The TA is clean and works good. No jar-off, no slam fire, no follow downs. The safety works. Customer thinks he had the safety-on.

OFFER TO INSTALL the new X-mark Pro  
if that fails we can exchange the  
rifle - good luck

Fled

139765

X  
Serial Number: E6767955

Model: 700



RE00139765

MM Ultra Mag. I contacted one of your customer  
y told me to send this to you at this address  
understand. This rifle has a MAJOR flaw

somewhere in the safety - When I was unloading it **WITH THE SAFETY ON** the gun fired!!

Let me explain what happened. I had just came out of the woods and was talking to a couple of guys about the days sightings when I place (not dropped, not slammed but placed) the barrel on the back of the tailgate of the truck and the gun discharged. I had 3 people (myself included) that can verify that my hands weren't even close to the trigger for me to fire it. Now luckily **NO ONE** was hurt or god forbid killed in this incident - just some sheet metal damage to a tailgate and truck (which I have since paid for the repair costs....which by the way weren't cheap for a Ford F-250), regardless this rifle has a major flaw in the safety somewhere. This gun was purchased by me 5 years ago and has never had the trigger worked on - everything is the way that it came to me from the factory. But I can tell you this - this gun is unsafe and once the defect is found should be destroyed!!

I am a lifelong Remington man - I have owned and currently do own many rifles and shotguns manufactured by Remington and one reason for this is because you stand behind your products and I trust in that!! I am not sure what to expect for the damages done by this rifle (probably nothing) but I would hope that you would replace this rifle - from what I see that this is the **LEAST** that you should do considering this circumstances.

I have always considered myself a safe hunter and sportsman - but let me tell you this messed me up!! Not only mentally of having something like this happen but for almost 3 weeks my ears rang!! I am VERY grateful that nobody was hurt or even killed in this accident. I am interested in hearing what exactly happened and what the fix was. From what I have heard I would assume that I will **NEVER** receive an answer regarding this - but I tell you this.....If you send me the same exact gun back saying that you couldn't find anything wrong with it you better be ready for some bad press because I **CAN GUARANTEE** you this.....**THERE IS SOMETHING MAJOR WRONG SOMEWHERE WITH THIS RIFLE!!**

If for find the need to contact me regarding this problem - I can be reached a couple of ways - Email (at the top of the letter), home phone is the first number listed and I can pretty much be reached 24/7 with the last number (my cell phone). Again I know you as Remington stand behind your products - show me that you do!!

Thanks for your time and I will be looking forward to hearing from you -

Bryan Jarman

Stainless  
7mm UM  
54W.  
\$1200

