

Remington Arms Co., Inc.
Product Service
Legal Case #:3567

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
169994	6/24/2009	6/25/2009	6/25/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Gerald	McCabe	321 Carey Ave	Salisbury	MD	21804		H 410-749-4732 E gtmccabe1943@comcast.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fires on safe release	Concern:1007 Fired on Safe Release	Unknown	
C				

6/26/09 Per letter with rifle, discharges (not always) when you push the safety off. 1st time was in early 80's on hunting trip. He had a local gunsmith clean trigger assm and it worked fine for a few years. It started discharging again when you pushed the safety off. He had a local gunsmith clean and set trigger pull. It worked fine for a few years again. This past hunting season it started discharging again. Wants repaired.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	B6275419	LB	2/17/1981
Date Purchased	Where Purchased	Accessories	Original Owner			
	ANDERSON IRELAND BALTIMORE MD		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
replace TPA at BLSP price of \$20 + S&H						
	Repair/Replacement Cost	Repair/Replacement Date				
	78.03	6/26/2009				

6/26/09 Per Supry, could not duplicate concern. Trig adjusting screws altered. Replace TPA, check over under BLSP for \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/25/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	

Barrel	Description		22" 3006 SPR
	Date Code		LB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00169994** Serial: 86276419 Model: 700 Center Fire Caliber: 3006 SPRG Produced: 02/17/1981 Repairman: Robert Fink Status: ApprovalHold 6/24/2009 8:14:30 AM

Verify Repair

Address Information

Customer: **GERALD MC CABE** Received From: **GERALD MC CABE** Return To: **GERALD MC CABE** Received From:

Name: **GERALD MC CABE** Address 1: **321 CAREY AVE** Address 2: **PO Box** City: **SALISBURY** State: **MD** Zip Code: **21804** Country: **US**

FFL: **MD** Zip Code: **21804** Country: **US**

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	User ID	Desc1	Desc2	Current Status
6/23/2009 12:05	ArmEmail	Receipt	GTMCCABE1943@CI	ApprovalHold
6/24/2009 5:33 E	finkie	Estimate Update	Status: Estimating	6/24/2009 8:14:30 AM
6/24/2009 6:08 E	Travisbw	Repair Maintenance	Status: Estimating	finkie
6/24/2009 8:10:4	finkie	Estimate Update	Status: ApprovalHold	ApproveRack
6/24/2009 8:12:0	System	Immediate SAP Allocation		Repair Location
6/24/2009 8:14:3	finkie	Estimate Update	Status: ApprovalHold	ILN
6/24/2009 8:16:0	System	Immediate SAP Allocation		Current Location
6/24/2009 8:24:2	pencerl	From: Repair Bench	To: ApproveRack	ILN
				Transfer Number

Shipping Hold ☐ InterFace Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair ☐

Repair Search Refresh Close

\$20.53

15.

35.

17.50

12.-

15.

115.03

-37.-

78.03

RECEIVED
JUN 25 2009
BY:

3561

22"
2.5#
LB 2/81
007

Remington

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: 700		Serial Number: B6275419	
Name: Gerald McCabe		Date of Purchase: N/A	
Address (no PO Boxes): 321 Carey Ave.			
City: Salisbury		State: MD	Zip: 21804
Phone (Daytime): 410-749-4732		Fax:	
E-mail Address: gtmccabe1943@comcast.net			
<p>Please describe your problem:</p> <p>Discharges (not always) when you push the safety off. First time was in early 80's on hunting trip. I had a local gunsmith clean trigger assly and it worked fine for a few years. It started discharging again when you pushed the safety off, I had a local gunsmith clean and set trigger pull. It worked fine for few years. This past hunting season it started discharging again. Please repair.</p> <p>Thanks, Gerald McCabe</p> <p>36 characters left</p>			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>			

© 2009 Remington Arms Company, Inc. All Rights Reserved.
Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Websites

Other Sites

Remington

B6275419

Model: 700



RE00169994

could not duplicate concern.
Trig. Adjusting screws altered.
Replace TPA, check over, under
Bolt Lock program for 20.00
+ S&H.

Quote

http://www.remington.com/support/repair_services/general_repair... 6/18/2009

PS 09873