Remington Arms Co., Inc. Product Service Legal Case #:2293

Case Inform	nation										
RE# 143594	Date C 4/1/2	-	Date Opened(PS 4/2/2008		Closed I 2008	nciden	t Date	Pı	re Lit I	lit	Obsolete
Customer I	nformation										
Туре	Business	First Name	Last Name	Street	(City	State	Zip	Age	Co	ntact
Reporter		Ray	McIntyre	277 Blythewood	i Road Col	umbus	MS	39701		H 662-	327-1710
Incident In	formation										
	Clair	ns		Codes		Repa	ir Est. M	ledical	Treatme	it Me	lical Status
С			Cause:4038 aged Concern:10 earm has disengage	07 Fired on Safe I		ged.W	ants trigg		known nged.lw		
Firearm Inf	formation	*** ····		n fan de fan de fille skie en men en en en en ekk				 .			
Mf	<u>e</u> .	Ту	pe	Mod	el/Ga.		SKU		Serial	Bbl	DOM
Remin	gton	CF/	-	700/27	70 WIN		2000)	6731593	B AY	3/1/1974
Date Pur	chased	Where P	urchased	Acces	ssories	0	riginal C)wner			
CONCERN		S S KRESGE F	T WAYNE IN	SCOPE BASE	E,RECOIL PAD		U				
Ammunitio	on Informatio	on - None Defir	ned							40-35.000 F -4 4 4	the discount in conf
Other Prod	ucts Informa	ation - None De	fined								
Settlement											
				Remington/700)/CF/BA						
Settle	ment	Release of C	laims R	lelease Date	Reimbursem	ent g	Cash Settleme		Reim. Da APV	te (Cash Date APV
Replace T SN											
		Repair/Repla Cost	cement Repa	ir/Replacement Date							
4/3/08-Quo	ote sent to re	place TA under	smp.lw								

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		4/2/2008
Examination	Product Type		RF
	Action Type		A
	Assigned To]	F.SUPRY
Cause	4038	Could Not Duplicate Concern]
	Description		22" 270 WIN
	Date Code		AY
	Bore Plugged	False]
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed	7	-

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2293&Type=Case

4/3/2008

. .

۲


	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	FINISH WEAR
	Shroud	Slightly Worn; Functioning]
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning]
	Condition	Slightly Worn; Functioning]
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Worn; Functioning	MANY MARS/SCRATCHES
	Fore End Condition	Select]
Receiver	Condition	Slightly Worn; Functioning]
	Bulged	False	
Safety	Description]	STANDARD M/700 BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	.012
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Functioning	MIN TRIG RETURN
Trigger	Pull	Select	3#
TIERCI	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock]
Non-Remington Components	Description		SCOPE BASE, RECOIL PAD

4/3/2008

RepairNumber RE00143594 Senat 673 270.WIN Venty Repair	1593 Model 700 Center Fire Caliber: Repairman Status	×
	Received From C. Received From C. Received From RAY MCINTYRE	
State MS Zip Code [3970] C Contact / Condition Problems Date User ID Desc1 3/25/2008/3021 valentds Repair Added 4/1/2008/12:565 valentds Repair information char	nge	
4/1/2008-12.57 valentds From Check In 4/22/2009/7/33-25 supryft Returned to AS for rep	To: Valentus Valentus Valentus Valentus	
Repair Search	<u>Refresh</u> <u>Close</u>	

.

١



	292	
	Y/	at l
	nington	A13/1 22,
	ry Repair Instructions Nete this form, and then include it with your firearm.)	DI
Model Number: MoDEl 700	Serial Number: 6731593	1*
Are you the original owner?:	NO	
Name: RAY MCINTURE	Date of Purchase: OcT. 1975	
Address (no PO Boxes):		
277 BINTHEWOOD	ROAD	
city: Colum Bus	State: MS Zip: 39701	
Phone (Daytime): 1-662-327-		
E-mail Address:	lates from Remington.	
Please describe your problem: Fine An	2m HAS DISCHARGED (FIRED)	
THICE WHEN SAFETY	WAS DISENGAGED (MOVED TO	
FIRE POSITION) TO UN	VICAD	
	server a ser	
IF POSSIBLE PLEASE MODIN OPENED WITH SAFTEN	EN SO THAT BOTT CAN BE IN SAFE POSITION	
PLEASE ADVISE ON NEW	TRIDGER ASSEMBIN	
Ammunition Information:		
Manufacturer: REMINGTON	Type: 130 GA: CORE-LOKT ATD SOFT PT	
Other (i.e. bullet weight/type, shot size, pow	der):	
·		
Handload Information:		
Powder Used:	Powder Weight:	
Case/Hull Used:	Primer Used:	
Bullet Type/Shot Size:	Reloader Used:	
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: $H_0 P F_{E}$		ļ
How often do you clean the bore? (Months or	<u> </u>	1
How often do you clean the action? (Months of		1
How often do you clean the trigger assembly		ł
· · · · · · · · · · · · · · · · · · ·	? (Months or Number of rounds) HAS NEVER	1
BEEN CLEANED		
Brand of lubricant used: BROWNING O	KI & REA-OIL	1
v		

.

.

. .

V

How often do you lubricate the bore? (Months or Number of rounds) 20 Round How often do you lubricate the action? (Months or Number of rounds) How often do you lubricate the trigger assembly? (Months or Number of rounds) NEVER. REFAL Lu K Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? X. YES NC Comments: AND MAI ENANCE ECOMMEN EARM When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? What were the services performed? Ship your INSURED firearm by either UPS or Parcel Post to: **REMINGTON ARMS CO., INC ATTN: Arms Service Divison** 14 Hoefler Ave Ilion, NY 13357 W warning: Do not send live or spent shells in your firearm or in the same box with the FIREARM. THIS IS A VIOLATION OF FEDERAL LAW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. . Record the serial number of your firearm before sending it. je in shipping and handling. Preferably, - ----turned.) 159 or damage. ie box. Shipments without a proper Remington is not responsible for Model: /00 chase insurance from your carrier. nes: I to you C.O.D. (To avoid C.O.D. Charges, please our gun) ate detailing the nature of the repair, applicable taxes and shipping. You will have at days to approve the report stimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. could not duplicate concern TRIP. Set Schews Altered. Replace TPA, check over, clean under 10014 Locik program for \$ 20:00 + StH Quote