

Remington Arms Co., Inc.
Product Service
Legal Case #:2146

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
141087	2/15/2008	2/18/2008	2/18/2008	11/14/2007			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Barry	Taylor	35 Doctors Creek Rd	Clendenin	WV	25045		H 304-548-6316

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fires on safe release	Concern:1007 Fired on Safe Release	Unknown	
C				

2/20/08-correspondence from repair-fired on safe release.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	25803	C6756214	RM	11/17/1992
Date Purchased	Where Purchased	Accessories	Original Owner			
	ANGLERS ROOST SPORT SHOP	SYN REM STOCK	Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	35	2/20/2008				

2/20/08-replace TA at n/c.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/18/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	HAS EXCESSIVE SEAR LIFT
Barrel	Description		24" 7MM REM MAG
	Date Code		RM
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Like new; Functioning	SYN REM STK
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.018
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SEAR LIFT .018
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

① 1-28-2008 2146
SENDING REM 700 SERIAL NUMBER
C 6756214-7mm REM MAG
SERIAL# 6214-BOLT BODY
BACK TO FACTORY FOR REPAIR

BOUGHT NEW ABOUT 1991-1992
AT ANGLER'S ROOST, CHARLESTON, W.V.

GUN NEVER MESSED WITH;
ACTION, BOLT ASSEMBLY, TRIGGER
ASSEMBLY, NOTHING. ONLY FACTORY
REMINGTON CORE-LOK AMMO USED!

DID PUT ON XCR COMPOSITE
STOCK, - ORIGINAL WALNUT
STOCK - WARPED - BOUGHT AT
CABELA'S - TYPE REM 700 MAG

BARRY, L. TAYLOR - OWNER
85 DOCTORS CREEK ROAD
CLENDENIN, W.V. 25045

PHONE NUMBER - 304-548-6316
DESCRIPTION OF PROBLEM:

SET-UP TO SIGHT IN NEW
SCOPE ON GUN FOR DEER SEASON!
11-14-07 - SAFETY WOULDN'T GO
TO SAFE POSITION, IT FINALLY DID,
PUSHING SAFETY TO FIRE MADE
FIRING PIN SNAP! (HAD ALREADY
UNLOADED GUN WHEN SAFETY WOULDN'T
WORK!) WORKED BOLT AND SAFETY
BACK AND FORTH MORE THAN ONCE, SAFETY
GOING TO FIRE POSITION MADE FIRING
PIN SNAP AGAIN! BUT NOT EVERY TIME!!

②

SAFETY LEVER VERY HARD TO MOVE.

INSPECTED BOLT, SAW BOLT PLUG BACKED OFF ABOUT $\frac{1}{8}$ INCH-.125, SCREWED BOLT PLUG BACK IN TO LINE-UP WITH COCKING NOTCH ON REAR EDGE OF BOLT. GUN, SAFETY AND TRIGGER SEEMS TO WORK FINE. NOT SAFE!!!

QUESTION: DID THE BOLT PLUG BEING BACKED OFF $\frac{1}{8}$ " CAUSE PROBLEM? AND HOW DID BOLT PLUG GET BACKED OFF? POSSIBLE BAD THREADS?

PLEASE CHECK WHOLE GUN REPAIR OR REPLACE ANYTHING THAT NEEDS FIXED, VERY CONCERNED ABOUT COMPLETE BOLT ASSEMBLY!!!
AND SAFETY!!!

PLEASE REPLACE - TRIGGER GUARD
FLOOR PLATE - BOLT-HINGES WORN BAD!

PLEASE CHECK OUT ACCURACY, NOT WHAT IT WAS. PLEASE FIRE FOR GROUP.

PLEASE REPLY! THANK YOU!

TELEPHONE NO#

BARRY L. TAYLOR

304-548-6316 35 DOCTOR'S CREEK ROAD

HOME PHONE CLENDENIN, W. V.

ANYTIME

25045

.018
Rm 0/92
4.5#
24"

could not duplicate concern.
HAS EXCESSIVE SEAR lift.
replace TPA, check over clean
AT N/C

#230145

Serial
Number:

C6756214

Model: 700



RE00141087