

Remington Arms Co., Inc.
Product Service
Legal Case #:3328

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
162664	2/24/2009	3/16/2009					

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Richard L.	Moore	691 Reese Drive	Danville	VA	24540		H 434-203-0956 F 434-836-6883 E Rich@mooreinsuranceagency.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	shot hole in roof of the shooting shelter	Cause:4038 Could Not Duplicate Concern		Unknown
S		Concern:1020 Fired on Bolt Opening		
C				

Sighting gun in & after the 4th shot the gun started to malfunction. The gun delay fired once. Then the next round did not fire at all. When he went to remove the round, the gun fired & shot a hole in the roof of the shooting shelter. He paid out of his pocket to repair the damages. Feels the gun is a liability and safety hazard. He spoke with someone at Remington & was told that he could get another model. dmf

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	710/7MM REM MA	27412	71313697	OA	7/12/2006 11:58:47 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
11/2/2008	WAL-MART SUPERCENTER 5191	SCOPE,RINGS,BASE	Y			

CONCERN:DELAY FIRED ONCE - PROPERTY DAMAGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date	Cash Date
					APV	APV

Remington/710/CF/BA

29484, 29018, 27918
7mm Ultra Mag
Wants 84152 & bxx each of Ultra Mag
Elijah said he'd send him the Ultra Mag.

Examination[Remington/CF/BA]

3/23 Left message to call re. m

Part	Sub-Part	Code	Comment
Examination	Examiner	Burris Disc coupon	B.TRAVIS
	Exam Date		3/16/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		OA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	

Extractor	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Magazine	Notch Condition	---Select---	
	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	Other Remington	

Requestor/Approver Provided Information

Requestor Name Christy Mitchell Date of Request 4/27/2009
 Requestor Phone 8684 Purchase Order # _____

Agency _____
 Principal _____
 Approval: _____ Date of Approval _____

Director of _____
 Sales Approval: _____ Date of Approval _____

TO: CUSTOMER SERVICE / SNC Rep**Customer Service Comments**

Only to be completed by Cust Service

Date Received _____

Date Processed _____

Rem Order # _____

COPY

Ship To: Richard L Moore
691 Reese Dr
Danville, VA 24540

Customer Service Notations

Mark For: _____

Requested Delivery Date: _____

Special Instructions (processing, shipping, notification, other etc.)

FFL # _____

FFL Expiration Date _____

Shipping Approval if Required _____

QUANTITY	RAMAC NUMBER	UNIT OF MEASURE	DESCRIPTION	MSP-(Discount) / Unit	Extension
1 box	29484		7 UM ammo	\$ 27.97	\$ 29.97
1 box	29018		7 UM ammo	\$ 38.86	\$ 38.86
1 box	27918		7 UM ammo	\$ 41.81	\$ 41.84
				\$ -	\$ -
				\$ -	\$ -
				\$ -	\$ -
				\$ -	\$ -
				\$ -	\$ -
				\$ -	\$ -
				\$ -	\$ -
Grand Total				\$ -	\$ 110.67

SNC Reason / Customer:

Case 3328, Rep 162664: Goodwill gesture.

Must be completed for Processing to Occur

Reasons for SNC	Check One	Charge Code	Check - One
Advertising/Promotion		Product Service	230145-8850050
Country Store			x
Donation to IRC Sec 501 (c) (3) org			
Field/Pro Staff			
Gifts			
Outdoor Writer			
Product Testing			
Replacement Goods for Defective Product			
Sample Allowance for Reps			
Tournament/Shoot			
Gallery			
Employee Stores			
Other - _____ Goodwill	x		

3328

Remington

0A7/06
24"
5#

Factory Repair Form

Return to Previous Page

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 710		Serial Number: 71313697	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: Richard L. Moore		Date of Purchase: 11/02/2008	
Address (no PO Boxes): 691 Reese Drive			
City: Danville		State: VA	Zip: 24540
Phone (Daytime): 434-203-0956		Fax: 434-836-6883	
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent) Rich@mooreinsuranceagency.net			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: Upon getting gun, I went to the target range attempting to sight it in. After the 4th shot the gun started to malfunction. The gun delay fired once. I thought it could be a bad round so I tried another. This time it did not fire at all-but when I went to remove the bullet, it fired and in doing so shot a hole in the roof of the shooting shelter- fortunately no one was injured. I have already paid out of my pocket to repair the damages. I feel this firearm is a liability issue & safety hazzard. Un happy with 710 model. I spoke with someone at Remington in November about gun, but had a death in family and had delay in sending. She stated probably would replace with different model- please call me to discuss. Thank you for your help in this matter.			
0 characters left			
Ammunition Information:			
Manufacturer: Remington		Type: Core Lok	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Prim. Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: Rem Oil			
How often do you clean the bore? (Months or Number of rounds) have not shot enough			
How often do you clean the action? (Months or Number of rounds) n/a			
How often do you clean the trigger assembly? (Months or Number of rounds) n/a			
Brand of lubricant used:			
How often do you lubricate the bore? (Months or Number of rounds) n/a			
How often do you lubricate the action? (Months or Number of rounds) n/a			

How often do you lubricate the trigger assembly? (Months or Number of rounds) n/a
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) n/a
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to: Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
<p>Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> <p>Charge repairs will be processed using the following guidelines:</p> <p>:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)</p> <p>:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.</p>

© 2009 Remington Arms Company, Inc. All Rights Reserved.
Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Websites
Other Sites

Serial Number: **71313697**

Model: **710**



RE00162664

could not duplicate concern