

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2627

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 149518 | 8/21/2008   | 8/22/2008       | 8/22/2008   |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street            | City       | State | Zip   | Age | Contact                                     |
|----------|----------|------------|-----------|-------------------|------------|-------|-------|-----|---|
| Incident |          | Robert     | Wayman    | 9170 E. 600 South | Zionsville | IN    | 46077 |     | C 317-439-2188<br>E bobwayman1638@yahoo.com |

## Incident Information

| Claims | Codes                 | Repair Est.          | Medical Treatment     | Medical Status |
|--------|-----------------------|----------------------|-----------------------|----------------|
| PI     |                       |                      |                       |                |
| PD     | Cause:4015            | Improper Maintenance |                       |                |
| S      | Fired on bolt closing | Concern:1008         | Fired on Bolt Closing | Unknown        |
| C      |                       |                      |                       |                |

8/22/2008 Model 600 produced in March 1966 - trigger assembly movement sluggish due to build up of sticky residue fls.

## Firearm Information

| Mfg.           | Type            | Model/Ga.      | SKU            | Serial | Bbl. | DOM      |
|----------------|-----------------|----------------|----------------|--------|------|----------|
| Remington      | CF/BA           | 600/350 REM MA |                | 64088  | AN   | 3/1/1966 |
| Date Purchased | Where Purchased | Accessories    | Original Owner |        |      |          |
|                |                 | SCOPE BASE     | U              |        |      |          |

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/600/CF/BA

| Settlement  | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| BLM Program |                         |                         |               |                 |                |               |
|             | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|             | 65.00                   | 8/22/2008               |               |                 |                |               |

8/22/2008 returned to AS for bolt lock modification program fls.

Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                 | Comment   |
|-------------|--------------|----------------------|---|
| Examination | Examiner     |                      | B.TRAVIS  |
|             | Exam Date    |                      | 8/22/2008   |
|             | Product Type |                      | RF  |
|             | Action Type  |                      | A   |
|             | Assigned To  |                      | F.SUPRY   |
| Cause       | 4015         | Improper Maintenance | Sear movement and trigger movement sluggish due to build up of lubrication residue. |
|             | Description  |                      | 18.5" 350 REM MAG   |

|                          |                        |                            |                 |
|--------------------------|------------------------|----------------------------|-----------------|
| Barrel                   | Date Code              | AN                         |                 |
|                          | Bore Plugged           | False                      |                 |
|                          | Bulged                 | False                      |                 |
|                          | Fired                  | False                      |                 |
|                          | Fired while Obstructed |                            |                 |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning |                 |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning |                 |
|                          | Shroud                 | Slightly Worn; Functioning |                 |
|                          | Face                   | Slightly Worn; Functioning |                 |
|                          | Handle                 | Slightly Worn; Functioning |                 |
|                          | Stop                   | Slightly Worn; Functioning |                 |
| Extractor                | Condition              | Slightly Worn; Functioning |                 |
|                          | Cut Condition          | Slightly Worn; Functioning |                 |
|                          | Ext/Eject Test         | False                      |                 |
| Locking                  | Block Condition        | ---Select---               |                 |
|                          | Lug Condition          | Slightly Worn; Functioning |                 |
|                          | Notch Condition        | ---Select---               |                 |
| Overall                  | Exterior Condition     | Slightly Worn; Functioning |                 |
|                          | Stock Condition        | Slightly Worn; Functioning |                 |
|                          | Fore End Condition     | ---Select---               |                 |
| Receiver                 | Condition              | Slightly Worn; Functioning |                 |
|                          | Bulged                 | False                      |                 |
| Safety                   | Description            | STANDARD M/600 SAFETY      |                 |
|                          | Function               | Like new; Functioning      |                 |
| Sear                     | Lift                   | ---Select---               | .004            |
|                          | Notch                  | ---Select---               | STICKY/SLUGGISH |
|                          | Tests                  | Test Fired                 | False           |
| Feeding Test             | Tests                  | False                      |                 |
| Trigger                  | Condition              | Slightly Worn; Functioning | STICKY/SLUGGISH |
|                          | Pull                   | ---Select---               | 4#              |
|                          | Altered                | False                      |                 |
|                          | Sub-Assembly           | Other Remington            |                 |
| Non-Remington Components | Description            | SCOPE BASE                 |                 |



2627  
AN 3/66  
18.5"  
4#  
.004

**REMINGTON ARMS COMPANY, INC.  
ILLION FIREARMS PLANT  
ATTENTION: BL SAFETY PROGRAM  
14 HOFELER AVENUE  
ILLION, NY. 13357**

**ATT: REMINGTON ARMS:**

**I AM SENDING YOU THIS REM. MODEL 600 .350 MAG  
SS# 64088**

**I PURCHASED THIS GUN SEVERAL YEARS AGO FROM A  
GUN SHOP IN WYOMING. I HAVE HUNTED ELK WITH IT IN  
IDAHO FOR 2 YEARS. HUNTED DEER IN OKLAHOMA AND IN  
WYOMING WITH SAME. AND....I HAVE NEVER HAD ANY  
PROBLEMS...UNTIL LAST SEASON ON OK!!!!!!!!!!!!**

**I SHOT A DEER AND JUST WOUNDED THE DEER. WHEN I  
INJECTED A SECOND BULLET INTO THE CHAMBER AND  
CLOSED THE BOLT.....THE GUN WENT OFF!!!!!!!!!!  
I WAS VERY LUCKY THAT I DID NOT "KILL" ANOTHER MAN  
SETTING IN A DEER STAND RIGHT IN FRONT OF ME...150  
YDS AWAY.**

**THUS, IN DOING RESEARCH, AFTER TELLING THIS STORY  
TO MANY PEOPLE, I FIND THAT THIS GUN WAS ON RECALL  
IN 1979!!**

**PLEASE, FIX THIS GUN SO THIS WILL NEVER HAPPEN  
AGAIN.**

**I HAVE 4 OTHER 600'S....AND I WILL BE SENDING THEM  
BACK TO YOU IN DUE ORDER...AFTER SEEING WHAT**

*Tt19. assm. parts sluggish from a sticky lubrication  
residue. replace TPA, check over, clean under  
bolt lock program for \$20.00 + S&H*

**HAPPENS TO THIS DEAL. I WILL BE USING THIS GUN IN  
LATE NOVEMBER TO DEER HUNT IN OK.  
WILL YOU BE ABLE TO GET IT BACK TO ME IN DUE  
TIME?????**

**THANKS MUCH.**

**WILL LOOK FOR YOUR REPLY.**

**EMAIL: bobwayman1638@yahoo.com**

**CELL PHONE: 317-439-2188**

**NAME: ROBERT WAYMAN**

**SINCERELY,**

**BOB**



Serial  
Number: **64088**

Model: **600**



**RE00149518**

**NOTE!!!!**

**WHEN YOU SEND THE GUN BACK,  
WILL YOU PLEASE SEND THE  
CARDBOARD BOX THAT THE CASE  
IS IN.....BACK WITH THE GUN...**

**I HAVE BORROWED THIS CASE  
AND BOX FROM A FRIEND AND  
HE WANTS IT ALL BACK...**

**IF THERE IS A PROBLEM WITH  
THIS, PLEASE GIVE ME A CALL AS  
TO WHAT MUST HAPPEN...**

**317-439-2188**

**bobwayman1638@yahoo.com**

**THANKS MUCH,  
BOB WAYMAN**

A handwritten signature in black ink, appearing to read 'Bob', with a stylized flourish underneath.


# Remington®

Thank you for your participation in the Safety Modification Program. We sincerely appreciate your continued support of Remington products, as well as your continuing participation in the hunting and shooting sports.

Insuring that our customers are familiar with proper firearms care and maintenance, along with safe gun handling practices remains a continual focus point at Remington. Visit [www.remington.com](http://www.remington.com) where you will find firearms care and safety tips including our interactive guides to shooting and hunting safety, centerfire rifle basics and shotgun basics.

As a result of your participation in the Safety Modification Program you are eligible to receive a Remington blaze orange hat. In order to receive your hat, please complete this form and enclose a copy of your repair order or invoice.

## Send My Hat To:

First Name  Robert Wayman Last Name \_\_\_\_\_  
Street \_\_\_\_\_ 9170 E 600 S P.O. Box \_\_\_\_\_  
City \_\_\_\_\_ Zionsville, IN 46077 Zip \_\_\_\_\_  
Phone (\_\_\_\_\_) \_\_\_\_\_  
Warranty Center Name \_\_\_\_\_  
Warranty Center Number \_\_\_\_\_  
Model Number 600 Serial Number 64088

## Mail To:

**Remington Safety Center  
P.O. Box 700  
Madison, NC 27025**

Requests must be received by January 31, 2009. Allow 4 weeks for delivery. Offer good only in the USA. Call 1-800-243-9700 for inquiries regarding the status of your hat.

*Thank you  
Bob*