

Remington Arms Co., Inc.
Product Service
Legal Case #:4216

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
185452	1/8/2010	1/11/2010	1/11/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Van's Deer Processing	*	Van's Deer Proc	777 Hwy 468	Brandon	MS	39042		W 601-825-9087

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1007	Fired on Safe Release	Unknown	
C	Fired on Safe release			

Dealer reported in a note - Gun fires when Safety is pushed to Fire position. dmf

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WSM	27173	S6574607	RA	11/28/2006 10:30:07 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Could not duplicate - replace trigger to restore confidence						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$48.42	1/15/2010				

1/15/10:Per Fred S. - Could not duplicate concern. Replace trigger assembly, check over, clean to restore confidence in rifle. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/11/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 270 WSM XCR
	Date Code		RA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00185452** Serial: 56574607 Model 700 Center Fire with 24 inch barrel Caliber: 270 WSM Produced: 11/29/2005 Repairman: Bruce Travis Status: Repairing 1/11/2010 10:48:03 AM

Address Information

Customer: ☐ Received From Return To: ☐ Received From
 Name: VANS DEER PROCESSING AND SPTG GDS VANS DEER PROCESSING AND SPTG GDS
 Address 1: 777 HIGHWAY 468 777 HIGHWAY 468
 Address 2: PO Box PO Box
 City: BRANDON BRANDON
 State: MS Zip Code: 39042 Country: US State: MS Zip Code: 39042 Country: US
 FFL: ☐ ☐ ☐ ☐ ☐ ☐

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Desc1	Desc2
1/8/2010 4:19:52	New	baileyrl	Repair Added	Status: New
1/8/2010 4:21:45	Maint	baileyrl	Repair Maintenance	To:
1/8/2010 4:21:55	Expedite	baileyrl	From: Check In	Status: Estimating
1/11/2010 10:26	Maint	Travisbw	Repair Maintenance	Status: PartsHold
1/11/2010 10:47	Estimate	Travisbw	Estimate Update	
1/11/2010 10:48	Repairing	System	Immediate SAP Allocation	

- ☐ Shipping Hold
- ☐ Interface Hold
- ☐ Estimate Sent
- ☒ Parts Received
- ☐ Passed Inspection
- ☐ Return As Received
- ☐ Has been Approved
- ☐ Internal Repair

Current Status
 Repairing
 1/11/2010 10:48:03 AM
 System
 Repair Bench
 Repair Location
 ILN
 Current Location
 ILN
 Transfer Number

Repair Search

Refresh

Close

supyrl 1/11/2010 12:51 PM C:\PS NUM INS CRL

start [Icons] Arms Services Re. [Icons] 12:51 PM

RECEIVED
 JAN 13 2010

BY:



Specialty - Smoked Link Sausage

Van's Deer Processing & Sporting Goods

777 Hwy 468 • Brandon, MS 39042 • Ph. 601-825-9087

Name: STOCK Date: 11-30-09

Phone: (Home) _____ (Work) _____

24"
RA 11/06
5.5#
.011

QTY.	ITEMS	PRICE
1	Rem 700 XCR	
	270 WSM	
	# 5657 4607	
	2048-12	
Warranty		
Gun fire when		
Safety is pushed		
to Fire Position		

could not duplicate concern.
replace TPA, check over, clean
to restore confidence in rifle.

230145

12/20/09
Rem 700

RETURNED RIFLE FROM

WINDY GREEBS BROS

MSDL 801819541

STOCK# 2048-12

BRAND NAME REMINGTON

MODEL 700 XCR

GAUGE 270 WSM

OTHER XCR

SER# 56574607

CODE

RETAIL PRICE

...S WHEN SAFETY IS DIS-
ENGAGED INSTANTLY.

86574607

Model: 700



RE00185452