Remington Arms Co., Inc. Product Service Legal Case #:5499

Case Information

Obsolete Date Opened(PS) **Date Closed Incident Date** Pre Lit RE# **Date Opened** Lit 12/17/2010 12/28/2010 12/28/2010 X 215584

Customer Information

Business Street City Zip Contact Type First Name **Last Name** State Age H 620-663-5276 8913 S Mohawk Rd Hutchinson Ben Nolan KS 67501 Incident E tdburges@hotmail.com

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

PΙ

PD Cause:4023 Needs Updated Parts Unknown Concern:1007 Fired on Safe Release S Fires when safety is released

1/10/11 Per letter with the rifle, fires occassionally when turning safety off. Gun was recently inherited and misfired twice during the 11 shots that have been put through it.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. **DOM** CF/BA 660/243 WIN n/a 111980 CR 4/1/1968 Remington

**Date Purchased** Where Purchased Accessories **Original Owner** 

U

CONCERN:FSR

Ammunition Information

Mfg. Cal./Ga. SKU **UPC DOM** Mfg. Code Type CL/100 243 Remington Concern Other **Factory** Reload Y N 0:

Other Products Information - None Defined

Settlement

Remington/660/CF/BA

Cash Reim. Release of Claims Settlement Release Date Reimbursement Date Settlement Date APV APV

Per Ilion, replace trigger assm, clean, test under recall at no charge

Repair/Replacement Repair/Replacement Cost Date

45.06 1/10/2011

1/10/11 Per Ilion, replace TPA under trigger assm recall at no charge, clean and test fire.cm

Examination[Remington/CF/BA]

Part	Sub-Part_	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/28/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4023	Needs Updated Parts	
	Description		20" 243 WIN

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5499&Type=Case

1/10/2011

Cash

	Date Code		CR
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	<del></del>
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/660 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.005
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	O/S NOT UPDATED
Tricon	Pull	Select	3#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	

	<499 -
Print	And the same of th

Reset

Model Number: 660	So Number: 111980	erial
Are you the original ow	ner?: 🗆 YES 🗀 I	NO
Name: Ben Nolan	Date of Purchase:	
Address (no 8913 S. Mohawk Rd	PO Boxes):	
City: Hutchinson	State: KS	<b>Zip:</b> 67501
Phone (Daytime): 620-663-5276	Fax:	ay i yanina andi ay i ayan iyo kini ba galan adala ay ay i ay
E-mail Address:(if e-mail address is provided be sent) tdburges@hotmail.com	ed, notification of rec	eipt and shipment will
E-mail A		emington.
have any markings showing that to manufactured after defect was continued inherited and misfired twice during have been put through it.  Replace TPA under T.A clean + Test fire.	rrected. Gun was ring the 11 shots to	recently nat that
•		
187 cha	racters left	
187 cha Ammunition I	racters left	
Ammunition I	racters left	ster
Ammunition I	racters left  nformation:  Type: 243 Winches  ght/type, shot size,	ster
Ammunition I  Manufacturer: Remington  Other (i.e. bullet wei	racters left  nformation:  Type: 243 Winches ght/type, shot size,	ster
Ammunition I  Manufacturer: Remington  Other (i.e. bullet wei  powder): 100 grain bullet core-lo	racters left  nformation:  Type: 243 Winches ght/type, shot size,	ster
Ammunition I Manufacturer: Remington Other (i.e. bullet wei powder): 100 grain bullet core-lo	racters left  nformation:  Type: 243 Winches ght/type, shot size, ok  formation:	ster
Ammunition I  Manufacturer: Remington  Other (i.e. bullet wei powder): 100 grain bullet core-lo  Handload In  Powder Used:	racters left  nformation:  Type: 243 Winches ght/type, shot size, ok  formation:  Powder Weight:	ster
Ammunition I  Manufacturer: Remington  Other (i.e. bullet wei powder): 100 grain bullet core-lo  Handload In  Powder Used:  Case/Hull Used:	racters left  nformation:  Type: 243 Winches ght/type, shot size, ok  formation:  Powder Weight:  Primer Used:  Reloader Used:	

Brand of cleaning solution used: Hopps
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Remington
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES □ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) never
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
) Arms Co. Inc

RE00215584

→ Arms Co., Inc. Service Division ofler Avenue NY 13357

PENT SHELLS IN YOUR FIREARM OR IN IS IS A VIOLATION OF FEDERAL LAW. IF **TSHELLS PLEASE SEND THEM IN A** ENAME, ADDRESS (WITH ZIP CODE),

TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

:: Record the serial number of your firearm before sending it.

:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,

ship in a firearm box. (Note: Original boxes may not be returned.)

:: Remove all accessories from your firearm to prevent loss or damage.

:: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory repair form.asp

3/9/2010

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.