Remington Arms Co., Inc. Product Service Legal Case #:4896

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

10/29/2010

Customer Information

Last Type Business First Name Street City State Zip Age Contact Name

Carl Incident

Ayers (Shannon)

17771 Wells North Fort Rd

FL 33917

H 239-872-1292

Ε

csalandclearing@aol.com

Incident Information

Medical Medical Repair Claims Codes Est. Treatment Status

Myers

ΡI

PD Cause:4079 Other - Unexamined

Unexplained Discharge Safe Unknown Fired with safety on when he Concern: 1005

touched bolt

C

10/29/10 Per call from Ayers, he was shooting his Ultra Mag caliber 700 Sunday before last and had fired one shot, chambered a 2nd and put his hand on the bolt at it fired. The safety was on. He has had the barrel magna-ported.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial

Bbl. DOM

Remington

CF/BA

700/

n/a

G450491

Date Purchased

Where Purchased

Accessories

Original Owner Y

Told him he was one number short or either the G is a 6.

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash Settlement Reim. Date APV

Cash Date APV

Repair/Replacement

Repair/Replacement

Cost

Date

10/29/10 Emailing ARS and letter.cm

Examination[Remington/CF/BA]

Part Sub-Part Code Comment





Remington Arms Company, Inc. 870 Remington Drive P.O. Box 700 Madison, NC 27025-0700 _

ARS LABEL REQUEST FORM

DATE:	10/29/2010	REQUESTED BY:	christy
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE OHEOK ONE:			
MEDIA	Email to him at:		
COORDINATOR	csalandclearing@aol.com		
TO MAIL		I WILL MAIL	
DESCRIPTION:			
· ·	700		
			•

LABEL INFORMATION

MAIL LABEL TO:	Carl Ayers 17771 Wells Rd N. Fort Myers, FL 33917	Email to him at: csalandclearing@aol.com	
RETURN ITEM TO	: Remington Product Servic	ce	

PLEASE COMPLETE AND PARTIS OF THIS FORM MANDISEND TO MHE MEDIA COORDINATION

4XX596 OCT 29, 2010 ALL CURR USD SVC GNDCOM
TRACKINGH 1Z4XX5969065201682
REF 1:CARL AYERS/CD/CN 1 05 1 REF 2:700 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHROS: RS 1.00 COD ଉ ଉଚ୍ଚ DV 0.00 DC 9.00 RH 0.00 TOT PUB CHG 9 99 SD 0.00 0.00 DGD SP 0.00 PR 00 0 9 93

PUB+HAMPL ING

csalandclearing@aol.com

Remington Arms Co., Inc. Product Service Legal Case #:4822

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 10/22/2010

10/22/2010

Customer Information

Business **First Name Last Name** Street City Type State Contact Zip Age Incident D. Bailey Frankfort KY H 502-875-4564 40601

Incident Information

Claims Codes **Medical Treatment Medical Status** Repair Est.

Unknown

Y

ΡĮ

PD Cause:4079 Other - Unexamined

Concern: 1007 Fired on Safe Release S FSR

C

10/22/10 Per call from Bailey, he bought his .270 BDL in the '70's and has had it fire on safe release. It was fine for the first year or two and then it happened several times. He has sent it to our RARC in Louisville for the BLSM program and had the BL removed. He has not shot it since. He wanted to have a X-Mark Pro trigger installed after viewing the CNBC broadcast. He will contact our RARC for a quote to replace the trigger.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. **DOM**

CF/BA 700/270 WIN Remington n/a **Date Purchased** Where Purchased Accessories Original Owner

Purchased in the 1970's.

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV

He will contact our RARC for a quote to replace the trigger

> Repair/Replacement Repair/Replacement Cost

10/22/10 He will contact our RARC for a quote to replace the trigger.cm

Examination[Remington/CF/BA]

Sub-Part Part Code Comment