PrintDisplay Page 1 of 2

Remington Arms Co., Inc.

Product Service Legal Case #:5231

Case Information

Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit RE# **Date Opened** Obsolete 1/3/2011

11/29/2010 215421 12/19/2010

Customer Information

Street City Contact **Business** First Name Last Name State Zip Age W 423-593-3056 PO Box 41 Soddy Daisy Incident Raymond Hixson TN 37384 C 423-364-3749

Incident Information

Repair Est. **Medical Status** Claims Codes Medical Treatment

ΡI

S

PD Cause: 4038 Could Not Duplicate Concern

Unknown Concern: 1007 Fired on Safe Release

C FSR

11/29/10: Customer called in. He stated he had FSR 2 yrs ago. No damage, No injury. df

Firearm Information

Model/Ga. **SKU** Serial Bbl. DOM Mfg. Type CF/BA 700/3006 SPRG n/a 6724475 AY 3/1/1974 Remington

Where Purchased Accessories Original Owner **Date Purchased**

ROSKIN BROS MIDDLETOWN NY TWO PIECE BASE U

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Per Ilion - Quote to repair under BLM program

> Repair/Replacement Repair/Replacement Cost Date \$60.40 1/14/2011

11/29/10: Sending ARS, ltr, form. df 1/14/11: Per Ilion - Could not duplicate concern. TA very dirty & sticky. Parts work sluggish. Replace TA, clean & test fire under BLM program - quote. I called cust. & he has mailed a check for payment. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5231&Type=Case

1/14/2011

Cause	4038	Could Not Duplicate Concern]
	Description		22" 3006 SPR
	Date Code		AY
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACT DIRTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False]
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
<u> </u>	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
Trigger	Pull	Select	6#
1115561	Altered	False	
,	Sub-Assembly	M/700 Bolt Lock]
Non-Remington Components	Description		TWO PIECE BASE

CS 12 18:10

CODY

November 29, 2010

Raymond Hixson PO Box 41 Soddy Daisy, TN 37384 Ph: 423-593-3056

Ref: #5231

Dear Mr. Hixson,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product **Service**". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872

enclosure

couldnot duplicate concerp. T.A. Uszydinty + Sticky parts work & luggish. Rephace TPA, clean & Yest Rive under BCP for \$ 20.00 + Shy JAN 05 2011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

300'Y

Print	Reset				
Model Number: 700	Serial Number: 6724475				
Are you the original owner?: XYES NO Ay Company					
Name: RAYMOND HIXSON	Date of Purchase:				
Address (no PO Boxes): 8593 DERRY BERRY LN					
City: HIXSON	State: 7N Zip: 37343				
(Daytime) (H) 5 93-3056	Fax:				
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) Hixsoniaxes of a ol-com					
E-mail A					
☐ I would like to receive future e					
Please describe your problem and date of occurrence: 7yrs ago the rifle files while being 10 ADED TOWN THE RIFLE AWAY IN 2007 I got the Rifle out t it all it agan: FIRED while being loaded.					
500 cha	racters left				
Ammunition I	nformation:				
Manufacturer: Reminstow	Type: 30.06 ISD GRAND				
Other (i.e. bullet weight/type, shot size, powder):					
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					

Brand of cleaning solution used: Reming tow					
How often do you clean the bore? (Months or Number of rounds) At each use - once					
How often do you clean the action? (Months or Number of rounds) 1 time per day after use					
How often do you clean the trigger assembly? (Months or Number of rounds) / hme κ ρος γεακ					
Brand of lubricant used:					
How often do you lubricate the bore? (Months or Number of rounds) 5 Rouges 1 time per dry luse					
How often do you lubricate the action? (Months or Number of rounds) EACH USC - 1x por day Scounds					
How often do you lubricate the trigger assembly? (Months or Number of rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES NO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)					
What were the services performed?)					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
 □ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. 					
Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/29/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
RUEASEICHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5231 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Raymond Hixson
PO Box 41
Soddy Daisy, TN 37384
Ph: 423-593-3056

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTISIOF THIS FORM AND SEND TO THE MEDIA COORDINATOR

AXX596 NOV 30, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969066080347
REF 1:RAYMOND HIXSON/CD/DMF
REF 2:5231/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 8.74 PUB+HANDLING 8.74







