

Remington Arms Co., Inc.  
Product Service  
Legal Case #:5171

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
214987 - 214983	12/16/2010	11/22/2010	12/17/2010				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Wendelin	Scheck	634 S. High PO Box 873	Dighton	KS	67839		H 785-650-2001 E wscheck50@hotmail.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

11/22/10: Customer called in. He stated that he had a FBC 3 years ago. No damage, No injury. He stated that it was really cold when FBC happened. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	6808794	RY	11/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE SCOPE BASE	N			

CONCERN:FBC

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	25771	E6232637	BQ	1/1/1996
Date Purchased	Where Purchased	Accessories	Original Owner			
	GO SPORTSMENS SUPPLY INC	TWO PIECE BASE,LEATHER STK COVERS	Y			

CONCERN:CHECK SAFETY

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair 1 gun under BLM program & 1 gun @ 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$54.60	12/28/2010				

11/22/10: Sending ARS, ltr, form. df 12/28/10: Customer sent in 2 rifles. Per Ilion - Serial # 6808794 - Could not duplicate concern. Replace TA, clean & test fire under BLM program - Quote. Serial # E6232637 - Could not duplicate concern. TA very dirty & rusty. Replace TA, clean & test fire at 1/2 normal cost - Quote. df 12/28/10: Emailed quotes to customer. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/17/2010

Examination	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4038	Could Not Duplicate Concern		
Barrel	Description		22" 270 WIN	
	Date Code		RY	
	Bore Plugged	False		
	Bulged	False		
	Fired	False		
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		
Bolt	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning		
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
Extractor	Condition	Slightly Worn; Functioning		
	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
Locking	Block Condition	---Select---		
	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	---Select---		
Overall	Exterior Condition	Slightly Worn; Functioning		
	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	---Select---		
Receiver	Condition	Slightly Worn; Functioning		
	Bulged	False		
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY	
	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	---Select---	.008	
	Notch	Slightly Worn; Functioning		
	Trigger	Condition	Slightly Worn; Functioning	APPEARS A TRIGGER SHOE WAS BEING USED
		---	---	
Pull	Trigger	---	4.5#	
Altered		False		
Sub-Assembly		M/700 Bolt Lock		
Non-Remington Components	Description		TWO PIECE SCOPE BASE	

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/17/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		BQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Like new; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	METAL RUSTY/DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	RUSTY/DIRTY
	Pull	---Select---	8.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, LEATHER STK COVERS

**QUOTATION**

Parts/Repairs 800-243-9700  
Fax 336-548-7801

**Remington Arms Company, Inc.**

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

[www.remington.com](http://www.remington.com) [info@remington.com](mailto:info@remington.com)**ESTIMATING****REPORT****ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.**

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

<b>Repair Order Number</b> RE00214987 <b>Account # - R-</b>	<b>Description/Serial Number</b> 6808794	<b>Date Received -</b> 12/16/2010 <b>Estimate Date -</b> 12/17/2010 <b>Current Date -</b> 12/28/2010
<b>Customer</b> WENDELIN SCHECK 634 S HIGH  DIGHTON. KS 67839 US		<b>Return To</b> WENDELIN SCHECK 634 S HIGH  DIGHTON. KS 67839 US
<b>Phone (H)</b> (785)-650-2001 <b>Phone (W)</b>	<b>Fax</b>	<b>Email</b> wscheck50@hotmail.com

Please Circle One  
VISA MC AMEX DISCOVER Card No. \_\_\_\_\_ Exp. Date \_\_\_\_\_  
PO Number \_\_\_\_\_  
Daytime Phone (\_\_\_\_) \_\_\_\_\_ Time To Call \_\_\_\_\_ Open Acct. R \_\_\_\_\_  
Approval: Customer Signature \_\_\_\_\_ Date \_\_\_\_\_  
☐ If You Desire Any Change Please Use The Reverse Side For Your Comments And Mark This Box  
**Notice: We process checks electronically through Check 21**

<b>Reported</b>		<b>Problems Found</b>	
M100	SEE CUSTOMERS LETTER	M123	FORWARD TO PRODUCT SERVICE F
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTIO		

**Technician's Comments**

ProblemNotes could not duplicate concern.replace trigger plate assm, clean and test fire under bolt lock program for \$20.00 + shipping.

Estimate **C.O.D./Shipping and Handling Charges are NOT Included in this Quote							
Material #	Material Description	Qty	Warranty Y/N	Price/ Unit	Discount Percent	Extended Amt	
<b>Part</b>							
F306373B	700 XMP EA TRIG ASSB LH BLACK (OS)	1	Y	\$94.00	0%	\$0.00	
<b>Service</b>							
4000114	GR-SHIPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00	
4000116	GR-LABOR	1	N	\$20.00	0%	\$20.00	
4000119	GR-TEST	1	Y	\$23.00	0%	\$0.00	
<b>Sub Total:</b>						<b>\$37.00</b>	
<b>Est. Sales Tax:</b>						<b>\$1.81</b>	
<b>Grand Total:</b>						<b>\$38.81</b>	

**QUOTATION**Parts/Repairs  
Fax800-243-9700  
336-548-7801**Remington Arms Company, Inc.**870 Remington Dr. P.O. Box 700  
Madison, NC 27025-0700[www.remington.com](http://www.remington.com) [info@remington.com](mailto:info@remington.com)**ESTIMATING  
REPORT****ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.**

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

<b>Repair Order Number</b> RE00214983 <b>Account # - R-</b>	<b>Description/Serial Number</b> E6232637	<b>Date Received -</b> 12/16/2010 <b>Estimate Date -</b> 12/17/2010 <b>Current Date -</b> 12/28/2010
<b>Customer</b> WENDELIN SCHECK 634 S HIGH  DIGHTON, KS 67839 US		<b>Return To</b> WENDELIN SCHECK 634 S HIGH  DIGHTON, KS 67839 US
<b>Phone (H)</b> (785)-650-2001 <b>Phone (W)</b>	<b>Fax</b> <b>Email</b> WSCHECK50@HOTMAIL.COM	

Please Circle One  
VISA MC AMEX DISCOVER Card No. \_\_\_\_\_ Exp. Date \_\_\_\_\_  
PO Number \_\_\_\_\_  
Daytime Phone (\_\_\_\_) \_\_\_\_\_ Time To Call \_\_\_\_\_ Open Acct. R \_\_\_\_\_  
Approval: Customer Signature \_\_\_\_\_ Date \_\_\_\_\_  
☐ If You Desire Any Change Please Use The Reverse Side For Your Comments And Mark This Box  
**Notice: We process checks electronically through Check 21**

Reported		Problems Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTIO	M123	FORWARD TO PRODUCT SERVICE F

Technician's Comments	
ProblemNotes	could not duplicate concern.trigger assm very dierty and rusty.replace trigger plate assm,clean and test fire at 1/2 normal cost.

Estimate **C.O.D./Shipping and Handling Charges are NOT Included in this Quote						
Material #	Material Description	Qty	Warranty Y/N	Price/Unit	Discount Percent	Extended Amt
<b>Part</b>						
F305570B	X-MARK PRO 700 TRIG ASSB RH BLACK (O	1	N	\$94.00	50%	\$47.00
<b>Service</b>						
4000114	GR-SHIPING & HANDLING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000119	GR-TEST	1	N	\$23.00	50%	\$11.50
Sub Total:						\$75.50
Est. Sales Tax:						\$3.70
Grand Total:						\$79.20

# Remington®

22"  
BY 11/74  
4.5#  
008

5171

November 22, 2010

Wendelin Scheck  
PO Box 873  
Dighton, KS 67839  
Ph: ~~828-645-4078~~

785-650-221

Ref: # 5171

Dear Mr. Scheck,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

**Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service".** Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,  
D. Fulcher  
Consumer Affairs Administrator  
Remington, H&R, Marlin  
Phone: 1-800-243-9700  
Fax: 336-548-7872

RECEIVED  
DEC 22 2010

BY: .....

enclosure

6808794  
Model: 700



RE00214987

could not duplicate concern.  
replace TPA, clean & test fire  
under BLP for \$20.00 + ship

Quote

12-7-10

Wendelin Scheck

PO Box 873

634 S. High

Dighton, KS 67839

785-650-2001

I have had a trigger malfunction with the rifle. In 2000 or 2001 I was deer hunting. I pulled the trigger on my 700 and nothing happened. I ejected the round and chambered another. When I closed the bolt the gun went off.

I have read some articles on the gun misfiring. I have also seen a video on it. I would like to see about having the trigger replaced with a trigger with a different design. I was thinking of the Xmark pro.

I hunted deer this year, but used a different rifle. I will not use a rifle that might be unsafe.

Thanks for your time

Wendelin

Print

Reset

<b>Model</b> Number: 700 LH		<b>Serial</b> Number: 6808794	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: Wendelin Schick		Date of Purchase: 1991	
Address (no PO Boxes): 634 S. High			
City: Dighton		State: KS	Zip: 67839
Phone (Daytime): 785-650-2001		Fax:	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) wschick50@hotmail.com			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: See Attach			
500 characters left			
<b>Ammunition Information:</b>			
Manufacturer: Remington		Type: Core Load	
Other (i.e. bullet weight/type, shot size, powder): 130			
<b>Handload Information:</b>			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
<b>Firearms Care (Cleaning and Lubrication):</b>			



Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) <u>after every shooting</u>
How often do you clean the action? (Months or Number of rounds) <u>after every shooting</u>
How often do you clean the trigger assembly? (Months or Number of rounds) <u>2, maybe once</u>
Brand of lubricant used: <u>2</u>
How often do you lubricate the bore? (Months or Number of rounds) <u>before long term storage</u>
How often do you lubricate the action? (Months or Number of rounds) <u>after every cleaning</u>
How often do you lubricate the trigger assembly? (Months or Number of rounds) <u>2 don't think I even have</u>
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <u>2004</u>
What were the services performed? <u>The trigger was locked up</u>
Ship your INSURED firearm by either UPS or Parcel Post to:
<p style="text-align: center;">Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357</p>
<p><input type="checkbox"/> <b>WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</b></p> <p style="text-align: center;">:: Record the serial number of your firearm before sending it.</p> <p style="text-align: center;">:: Pack your firearm for safety and to prevent further damage in shipping and handling.</p> <p style="text-align: center;">Preferably,</p> <p style="text-align: center;">ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p style="text-align: center;">:: Remove all accessories from your firearm to prevent loss or damage.</p> <p style="text-align: center;">:: Provide a return address on both the outside and inside the box. Shipments without a proper</p>

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

5171  
November 22, 2010

Wendelin Scheck  
PO Box 873  
Dighton, KS 67839  
Ph: ~~828-645-4078~~

785-650-2001

Ref: # 5171

Dear Mr. Scheck,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

**Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service".** Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,  
D. Fulcher  
Consumer Affairs Administrator  
Remington, H&R, Marlin  
Phone: 1-800-243-9700  
Fax: 336-548-7872

RECEIVED  
DEC 22 2010

BY: .....

E6232637

Model: 700



RE00214983

could not duplicate concern.  
T.A. very dirty + rusty.  
Replace TPA, clean + test fire  
at 1/2 normal cost.

Quote

Wendelin Scheck  
PO Box 873  
634 S. High  
Dighton, MS 67839  
785-650-2001

12-7-10

I am sending in this Remington 700  
for inspection/repair.

I have read a few articles and watch  
a video on Remington 700 trigger  
problems. I am concerned about this  
rifle being safe. I do not want to  
wait until I have a problem with  
this rifle. I do not want this rifle  
going off on its own.

I would like to know if I can replace  
the trigger.

Is the Xmark a different design?

thanks for your time

Wendelin

Print

Reset

Model Number: 100		Serial Number: E 6232637	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: Wendelin Schreck		Date of Purchase: May 1998	
Address (no PO Boxes): 634 S. High			
City: Dighton		State: KS	Zip: 67839
Phone (Daytime): 785-650-2001		Fax:	
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent) wschreck50@hotmail.com			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <del>See</del> See attach			
500 characters left			
Ammunition Information:			
Manufacturer: Remington		Type: Corelock	
Other (i.e. bullet weight/type, shot size, powder): 130 gr			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) <u>1 year</u>
How often do you clean the action? (Months or Number of rounds) <u>1 year</u>
How often do you clean the trigger assembly? (Months or Number of rounds) <u>never</u>
Brand of lubricant used: <u>2</u>
How often do you lubricate the bore? (Months or Number of rounds) <u>never</u>
How often do you lubricate the action? (Months or Number of rounds) <u>when cleaning</u>
How often do you lubricate the trigger assembly? (Months or Number of rounds) <u>never</u>
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <u>never</u>
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
<p style="text-align: center;"><b>Remington Arms Co., Inc.</b>  <b>Attn: Arms Service Division</b>  <b>14 Hoefler Avenue</b>  <b>Ilion, NY 13357</b></p>
<p><input type="checkbox"/> <b>WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</b></p> <p style="text-align: center;">:: Record the serial number of your firearm before sending it.</p> <p style="text-align: center;">:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,</p> <p style="text-align: center;">ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p style="text-align: center;">:: Remove all accessories from your firearm to prevent loss or damage.</p> <p style="text-align: center;">:: Provide a return address on both the outside and inside the box. Shipments without a proper</p>

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



www.remington.com

Remington Arms Company, Inc.  
870 Remington Drive  
P. O. Box 700  
Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	11/22/2010	REQUESTED BY:	Dell
QUANTITY:	2	WEIGHT PER PKG:	10 lbs ea.
<del>PLEASE CHECK ONE</del> MEDIA COORDINATOR TO MAIL		I WILL MAIL	XXXXXX
DESCRIPTION: Ref # 5171 Rifles			

## LABEL INFORMATION

MAIL LABEL TO: Wendelin Scheck PO Box 873 Dighton, KS 67839 Ph: 828-645-4078
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

**PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR**

4XX596 NOV 23, 2010 ALL CURR USD 1 OF 2  
SVC GNDCOM ACT WT 10.0 LBS  
TRACKING# 1Z4XX5969067552139  
REF 1:WENDELIN SCHECK/CD/DMF  
REF 2:5171/RIFLE

HANDLING CHARGE 0.00  
SINGLE-PIECE PUB RATE CHRGs: SVC T/P USD  
DV 0.00 COD 0.00 RS 0.50  
DC 0.00 DGD 0.00 SD 0.00  
AH 0.00 PR 0.00 SP 0.00  
TOT PUB CHG 9.45 PUB+HANDLING 9.45

4XX596 NOV 23, 2010 ALL CURR USD 2 OF 2  
SVC GNDCOM ACT WT 10.0 LBS  
TRACKING# 1Z4XX5969066647342  
REF 1:WENDELIN SCHECK/CD/DMF  
REF 2:5171/RIFLE

HANDLING CHARGE 0.00  
SINGLE-PIECE PUB RATE CHRGs: SVC T/P USD  
DV 0.00 COD 0.00 RS 0.50  
DC 0.00 DGD 0.00 SD 0.00  
AH 0.00 PR 0.00 SP 0.00  
TOT PUB CHG 9.45 PUB+HANDLING 9.45



















