Remington Arms Co., Inc. Product Service Legal Case #:5403

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

213928 12/10/2010 12/10/2010 12/13/2010

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact
Reporter Sportsmans Haven --- Sportsmans Have 14595 E. Pike Rd. Cambridge OH 43725 W n/a

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

S

PD Cause: 4054 As received Follows Down

Concern:1008 Fired on Bolt Closing

Unknown

C FBC

Dealer sent gun into factory. Customer stated rifle fires when bolt is closed. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/280 REM
 25632
 B6869524
 PH
 6/13/1987

Date PurchasedWhere PurchasedAccessoriesOriginal OwnerWAMMES CORPSCOPE BASEU

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date APV APV

Per Ilion - Quote to repair

Repair/Replacement Repair/Replacement Cost Date


Per Ilion - Will follow down. TA has a partially dried & sticky lubrication residue causing the sear to work sluggish: Replace TA, clean & test fire @ 1/2 normal cost - quote. RARC apprvd & put charges on their acct. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/13/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	
	Description		22" 280 REM

	Date Code	j	PH
	Bore Plugged	False	
	Bulged	False	Ī
Barrel	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	=
	Stop	Slightly Worn; Functioning	·
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description]	STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	ing
	Functioning Functioning Bulged False Description STANDARD M/700 SAFETY Function Like new; Functioning Sub-Assembly Non-ISS		
Sear	Lift	Select	.011
	Notch	Slightly Worn; Not Functioning	
	Tests	Test Fired	False
Feeding Test	1 €313	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY. SEAR SLUGGISH WILL FOLLOW DOWN
Trigger	Pull	Select	10+#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	·
Non-Remington Components	Description		SCOPE BASE

14/14/14 14.14.44



DEC 1 7 2010 BY:

PURCHASE ORDER

P.O. #	4	4	4	2	
P.O. #	-	-	•		

Date 12-02 -/0

Rem

Address

DATE REQUIRED HOW SHIP QUANTITY PLEASE SUPPLY ITEMS LISTED BELOW PRICE B6869524 Modification

SPORTSMAN'S HAVEN INC. 14695 EAST PIKE RD. **CAMBRIDGE, OHIO 43725**

Please Send

Copies of Your Invoice

Purchasing Agent

6869524

Model:



all Collow down. Trig. Assm. Ehrs A partially dried + sticky lubrication residue causing the cept to work stuggishe Rephree TRA clean+ Test fine at 1/2 Nonmal vost.

Quole

