rage I of Z rnntulsplay

> Remington Arms Co., Inc. **Product Service** Legal Case #:4586

Case Information

RE# Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete **Date Opened**

6/21/2010 5/26/2010 6/22/2010 197607

Customer Information

First Name Last Name **Business** Street City State Zip Age Contact Type

809 State St LaPorte IN 46350 Incident LaPorte Cty Sheriff's Office Waltz C 219-363-0136 Keith

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

PΙ

PD Altered Adjustments or Cause:4006

Components Unknown fires on closing down bolt, S

Concern: 1008 Fired on Bolt Closing trigger pull fluctuates

C

5/26/10 Per call from Waltz, this is a department issued rifle that was originally purchased new around 1994. Recently he has had it fire when closing the bolt. The trigger pull is not consistent either.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

CF/BA 700/308 WIN 25711 D6813279 DO 9/21/1994 Remington

Date Purchased Where Purchased Accessories Original Owner Y

LAPORTE COUNTY SHERIFFS DEPT

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Per Ilion, repair at 1/2 normal charges as gesture of goodwill

> Repair/Replacement Repair/Replacement Date

Cost

5/26/10 Sending ARS.cm 6/23/10 Per Ilion inspection, trigger set screws altered. Will follow down. Bolt stop binds. Replace TPA, check over, clean at 1/2 normal charges, function test.cm


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
-	Exam Date		6/22/2010
Examination	Product Type		RF
	Action Type		A

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4586&Type=Case

6/23/2010

-	Assigned To	j	F.SUPRY	
Cause	4006	Altered Adjustments or Components	·	
	Description		26" 308 WIN	
	Date Code		DO	
Barrel	Bore Plugged	False		
	Bulged	False		
	Fired	False		
	Fired while Obstructed		_	
	Muzzle/Crown Condition	Slightly Worn; Functioning		
	Firing Pin	Slightly Worn; Functioning		
	Shroud Slightly Worn; Functioning			
Bolt	Face	Slightly Worn; Functioning	· ·	
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Not Functioning	BINDS/SLUGGISH	
	Condition	Slightly Worn; Functioning		
Extractor	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
	Block Condition	Select		
Locking	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select		
	Exterior Condition	Slightly Worn; Functioning	METAL AND STK PAINTED	
Overall	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	Select		
n .	Condition	Slightly Worn; Functioning		
Receiver	Bulged	False		
	Description		STANDARD M/700 SAFETY	
Safety	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
	Lift	Select	.014	
Sear	Notch	Slightly Worn; Functioning		
	m. 4	Test Fired	False	
Feeding Test	Tests	False		
	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN	
Trigger	Pull	Select	3#	
	Altered	True	SET SCREWS ALTERED	



6/23/10 Mailed estimate.

ECEIVE JUN 2 3 2010 BY:----

4546

2017 2017 314

May 26, 2010

Keith Waltz LaPorte County Sheriff's Office 809 State St. LaPorte, IN 46350

Subject: Case 4586, Model 700

Dear Mr. Waltz,

I am sorry to learn of the incident with your Remington Model 700. Enclosed is a UPS prepaid shipping label for shipment of the firearm to our factory. Please include the enclosed copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator

Phone: 800-243-9700 ext 8684

E-mail: christy.mitchell@remington.com

D6813279

Model: 700



Trig. Set Screws Herered. Will follow down. BOLT STOP BINDS. Replace TPA, check over, clean At 1/2 NORMAL Emilyes, FULCTION TXST.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com Print

Reset

Model	Serial Serial					
Number: 700 PSS Number: 06813279						
Are you the original own	ner?: 🛛 YES 🗆 N	0				
Name: LaBarta County Shariff Office	Date of Purchase:					
Name: LaPorte County Sheriff Office CAPT. RETTERDER ITEITH WALTZ 1994?						
Address (no	PO Boxes):					
809 State Street						
City: LaPorte	State: IN Zip: 46350					
Phone (Daytime): 219-326-7700	Lav.					
E-mail Address:(if e-mail address is provid be sent) kwaltz@lcso.in.gov	ed, notification of recei	pt and shipment will				
E-mail A						
☑ I would like to receive future e	e-mail updates from Re	mington.				
On May 20, 2010 during Emergency Responce Team Sniper Training one round discharged immediately when the bolt was closed. The rifle was immediately taken off line. When the bolt is worked up and down the firing pig goes forward and back with the bolt does not lock back every time. It seems the triger pull gets lighter and harder on it's own.						
157 cha	racters left Information:					
Manufacturer: Federal	Type: NEW Match E	3THP				
Other (i.e. bullet weight/type, shot size, powder): 168 Grain Hollow Point						
Handload Ir	nformation:					
Powder Used: Powder Weight:						
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	e: Reloader Used:					
Firearms Care (Cleaning and Lubrication):						

Reference Remington 700 PSS Serial #D6813279 Case #4586

Please return rifle to: Deputy /Armorer Keith Waltz
LaPorte County Sheriffs Office
809 State Street, LaPorte Indiana 46350

So payment can be arranged, please contact Captain George Ritter at 219-326-7700 Ext. 2312 or, mail the estimate to: Captain George Ritter Deputy/Armorer Keith Waltz LaPorte County Sheriffs Office, 809 State Street, LaPorte Indiana 46350

	Case #	4586	Date of Call	826/10	Date of			Lit	OI	os si	
	Reporter name address contact #'s				Incident Name/Age address contact #'s	Ke, 809 Lay 46. 219	:42 5/a; norte 350 -36:	Wal 6 5% IN 3-013	t2 86	laport	-e (4 9 5, 0
	Injury Medical Treatment										
	Alleged cause Firearm	Ser# D613279	Cal	DOM 929	Orig owner?	When/W	here pur	chased			
)		Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Addition	al info			
	Other Product Push both forward it will fire. depth issued-										
	Notes:										
)	Request My actions/ offers	ARS									

May 26, 2010

Keith Waltz LaPorte County Sheriff's Office 809 State St. LaPorte, IN 46350

Subject: Case 4586, Model 700

Dear Mr. Waltz,

I am sorry to learn of the incident with your Remington Model 700. Enclosed is a UPS prepaid shipping label for shipment of the firearm to our factory. Please include the enclosed copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Supry".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator

Phone: 800-243-9700 ext 8684

E-mail: christy.mitchell@remington.com

enclosure



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE: 5/26/2010	REQUESTED BY:	christy
QUANTITY:	WEIGHT PER PACKAGE:	10
PLEASE CHECKONES. MEDIA		
COORDINATOR		xx
TO MAIL	I WILL MAIL	
DESCRIPTION:		
700		
D6813279		
·		

LABEL INFORMATION

MAIL LABEL TO:	LaPorte Cty Sheriff's Office Attn: Keith Waltz 809 State St LaPorte, IN 46350	, , , , , , , , , , , , , , , , , , ,
RETURN ITEM TO:	Rem Product Service	

PLEASE COMPLEME ALL PARKS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 MAY 26, 2010 ALL CURR USD 1 OF 1 SERVICE GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969066612601
REF 1:LAPORTE CSO/KEITH WALTZ/CD/CM
REF 2:REF#700/D6813279

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG B.74 PUB+HANDLING 8.74