Remington Arms Co., Inc. **Product Service** Legal Case #:5051

000	Inform	21122
LANC	1 1 2 1 4 7 1 1 4 1	ationi

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit L	it Obsolete
212058	12/2/2010	11/10/2010	1/14/2011	11/8/2010		

Customer Information

Type **Business First Name Last Name** Street City Contact State Zip Age 3007 Peavine Fire Tower Rd Crossville TN 38571 Incident Ronnie Smith 3401 Manassas Rd Reporter James Harris Cookville TN 38506 C 931-260-3598

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD shot truck engine Cause: 4038 Could Not Duplicate Concern Fires on safety

Unknown

Concern:1007 Fired on Safe Release release C

11/10/10 Rec'd voice mail from Harris stating that he had a VTR .308 and he has just returned from a trip and it fired when safety was released 3 times. On the 3rd time it shot through the floorboard of the truck. 11/10 2:50: Spoke with Harris, a couple of the officers where he works bought VTR's since they use LTR's on the job. Was going to shoot at a deer, took the safety off and it fired. He thought he made the mistake so he and his friend go to another area, a doe comes up and he gives his rifle to his friend to shoot. His friend takes that safety off and it fires. He takes it back to the truck, pulled out the fired shell and put another round in the chamber and it fired and put a hole through the engine. He stated that it has a "hair trigger" and he hasn't adjusted it. It came from the factory that way. He's been a cop for 17 years.cm

tormation

Mfg. Remington Date Purchased	Remington CF/BA ate Purchased Where Purchased		Model/Ga. SKU 700/308 WIN 84371 C Accessories Original Owner		Serial G6901554	Bbl.	<b>DOM</b> 9/15/2009 8:51:31 PM	
r	SPORTS SOUTH LLC			Y				
Ammunition Inform  Mfg.  Winchester	nation <b>Type</b> /150	Cal.	/Ga.	SKU	UPC	DO	M Mfg. Code	
Concern 0:	Other Supreme SilverTip	Factor N	•	<b>Reload</b> N				

Other Products Information - None Defined

Settlement

#### Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Refund for truck repair and repair 700 at no charge			910.95		1/14/2011	
	Repair/Replacement	Repair/Replacement				

Date Cost

62.40 1/14/2011

11/10/10 Mailing ARS and letter.cm 12/7/10 D. Evans said ok to refund for truck repairs. Called Harris and let him know we

would refund for repairs and repair 700 no charge. Awaiting receipt for repairs.cm 12/21/10 Mailing release to truck owner, Ronnie Smith.cm 1/14/11 Rec'd signed release. Processed G408 for refund of \$910.95.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		supry
	Exam Date		12/3/2010
Examination	Product Type	j	RF
	Action Type		A
·	Assigned To		Supry
Cause	4038	Could Not Duplicate Concern	Could not get this to fire without pulling the trigger
	Description		22 inch Model 700 VTR 308 caliber
	Date Code		DD
	Bore Plugged	False	
Barrel	Bulged	False	
Barrei	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
Bolt	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	True	
	Block Condition	Select	
Locking	Lug Condition	Like new; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Like new; Functioning	
	Exterior Condition	Like new; Functioning	·
Overall		Like new; Functioning	
	Fore End		

<u>'</u>	Condition	Select		
Receiver	Condition	Like new; Functioning		
	Bulged	False		·
	Description		Model 700	
Safety	Function	Like new; Functioning		
	Lift	Select	.013"	
Sear	Notch	Like new; Functioning		
Sear		Condition	Like new; Functioning	With the safe arm in the null position and repeated pulling of the trigger the safe would move to th
Pull	Trigger	Select	2.5 lbs	
Altered		False		
Sub- Assembly		X-Mark Pro		

12/08/2010 at 10:24 AM 30161

Job Number:

JULIAN'S AUTO BODY AND FRAME

Family Owned and Operated 1702 South Jefferson Ave. Cookeville, TN 38506 (931)372-0102

#### PRELIMINARY ESTIMATE

Written By: Matt Julian Adjuster:

Insured: Ronnie Smith Owner: Ronnie Smith

Claim # Policy #

Address: 3007 peavine fire tower rd.

Deductible:

crossville, TN 38571

Date of Loss: Type of Loss:

Day: Evening:

Point of Impact:

Inspect Location:

Insurance

Company:

Days to Repair

2005 FORD F250 4X4 SUPERCAB 8-6.0L-TD 4D LONG Int:

VIN: UNK

FM Radio

Lic:

Prod Date:

Odometer:

Intermittent Wipers

Power Steering

Dual Mirrors Power Brakes

Clear Coat Paint AM Radio

Anti-Lock Brakes (4) 4 Wheel Disc Brakes

Stereo Driver Air Bag Rear Step Bumper Search/Seek Passenger Air Bag Trailering Package

6 Speed Transmission 4 Wheel Drive

Overdrive

Styled Steel Wheels

NO.	OP.	D	ESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINŤ
1#	Repl	CARPET CAB		1	532	. 53	4.0	
3*	Rpr	Floor pan	assy manual trans				1.0	0.0
		<b></b>	Subtotals ==>		532.	. 53	5.0	0.0

Parts Body Labor	5.0	hrs @ \$	40.00/hr	532.53
SUBTOTAL Sales Tax	\$	732.53 @	\$ ! 9.7500%	732.53 71.42
GRAND TOTAL			s	803.95

ADJUSTMENTS:

Deductible

0.00

	QÙAN	PART NO	NAME OF PART	AR	E JNT		(1) t		LEROY'S SERVICE STATION  184 S. Roy Montal Blvd.  LAKE ONLY, SC 205200 01 4327
					محر		•	10 (0) / 1 (0) 5	LAKE 677, SC 20560 014327
·	7			1	1	No. 1	٠		)
.L			·		7		.!	₩ K	DATE RECEIVED \$11-08-15
			•		71	1	**************************************	RAME -	DATE PRODUCTION
				<del></del>			水	HOORESS	DATE RETURNED 11 - 09 - 10
					1		-34		A Property of the Control of the Con
\$ C		<del>:</del>		<del></del>	++;		**	CITY	STATE ZIP
<b>a</b>		·:	· · · · · · · · · · · · · · · · · · ·				-	Cx/.	70 8868 LIFTSY21PSSF @ 3/USS
ADDITIONAL		· · ·		<b>-</b>			1	MAKE	NODEL PHONE STATE
<u> </u>			- 1: LAW					1.05	Facul 44766 Penn
<u> </u>		<del> (. )</del>	- # \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ļ			<u>'</u>	l ''' [	AMOUNT AMOUNT
			110		<u> </u>			LUBRI-	CHANGE CHANGE WASH POLISH
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			<u>/(o                                    </u>			f		CATE	OIL TRANS DIFF. WASH POLISH
١			1	NO		7		Hook	IDs to Check No-Start
			11091	7	:I			Condi	100
Ę.			1110						
				. 1	***	4		A ROLL OF THE AREA	more Shap to Harney and Sideal
	. te 2.		<del></del>	7	<u> </u>	-		危	aria Tanta Card So ari
ě	$\neg \neg$				<del></del>	Ţ		18	yearre that the source
		<del></del>	<del>!</del>		<del></del>	1	—	· / *	
		SUBLET			- 1				yes yes terms
2 -		<del></del>	<del></del>			<del>  - i </del>			
o∴l•		ACCESS.	<del></del>	:			:	1	
į L		ACCESS.					نيا		
				· •				i hereby author	the repair work herein set forth to be done by TOTAL LABOR (2.3)
		.70	OTAL PARTS			34		and other magi	rial for such repair, and egree: that you are not TOTAL PARTS
	<i>.</i>	GALS GAS .	. i ::.		•	i		availability of te	any delays caused by unavariability of delayed GAS, Oil, GREASE
		QTS. OIL 6	}			3. 71	::::	assume nor est bability in conti	Inorize any other person to assume for you any ACCESSORIES ACCESSORIES
		LBS. GREASE @						responsible kar articles left their	loss of or damage to the above vehicle, or TIRES, TUBES
ĝ.		TOTAL GAS - OIL	GREASE		<u> </u>		· · · ·	your control lie	tes the repair work herein set forth to be done by the funishing by you of the necessary parts rial for such repair, and agree: that you are not any delays caused by unavailability or delayed any delays caused by unavailability or delayed arts or material for any reason; that you neither thorize any other person to assume for you any ection with such repair; that you shall not be loss of or damage to the above vehicle, or right, in case of fire, theft or other cause beyond at an express mechanic's fien is hereby acknowly above vehicle to secure the amount of repairs are employees may operate the above vehicle on so or elsewhere for the purpose of testing and/or
إَ	THE	DIS SELLER HEAFBY	CLAIMER OF WARRANTIES EXPRESSLY DISCLAIMS IMPLIED, INCLUDING ANY OR FITNESS FOR A PAR IS NOR AUTHORIZES ANY	ÅLL	PAW	HANT	IES.	theretor that you	are employees may operate the above vehicle on TOTAL
ğ.	OF M	REXPRESSED OF	OR FITNESS FOR A PAR	MPL!	EDW.	ARRA	NTY	jusbecing anci-	the amplyyees may operate the above venicle on total 67 07 07 07 so or elsewhere for the purpose of testing and/or vehicle.
\$	AND	NEITHER ASSUME	S NOR AUTHORIZES ANY LABILITY IN CONNECTION	OTHE	RPE	RSON	to		
8	MOOU	REFORM ANY I	LIABILIT IN CUNICCION	AATEM	INE.	BALL	<b>₩</b>	[xx	TOTAL AMOUNT 07 02

4803.95

Ø 003

### **ORIGINAL**

# Remington Arms Company, Inc.

Madison, NC 27025

				Seller's Invoice			
Purchase Order No.	<del></del>	Seller's Invoice No.					
Christy Mitchell							
Name of Person Originating	APV	Pay To:	Ronnie Smith	1			
Consumer Ext 8684							
Location/Extension of Origina	ator	Street and No.	3007 Peavin	e Fire Tower Rd			
1/14/2011							
Date Prepared		City Crossville		State TN		Zip Code	38571
<u> </u>				Vendor Code	106248		
% Days; Net	Days or			_			
	Desired P	ay Date		Pmt Method			
					7,5		
		_			ļ	Total	····
Descripti	on	refund for repair of	truck	<del></del>	<u> </u>	Dollars	Cents
							ì
Reimbursement for truc	k repair per C. Mitchell		····		<b> </b>	910	.95
Ref# 38571SmithRonni		Repair#	212050				
Rei# 303/ (SiliulKorini		Repail#	212058		-		
		Case #	5051				
				*****	<b> </b>		
			·		<u> </u>		
					ŀ		
Wire Transfer Information	<del></del>			<del></del>	<b></b>		
Bank:							
				-			
ABA:					ļ		
Pay to:							
ray to.		<del></del>			╂		
Acct #:					<u> </u>		
Distribution		The approval signature(	s) shown below at	test that all required	Gross		
		verifications and extens	ions have been pro	operly made and that	1		ļ
8850050-230145	Cost Element/Cost Center	Accounts Payable Secti	ion can make payn	nents without further	<b></b>	910	.95
	Tax	checks as to correctnes	is.		Discount		1
							ŀ
		Signed:					
					Net		
		Signed:			[		
		-					
		Date:	1/14/2011			910	.95
		Daic.	1714/2011	<u> </u>	<u> </u>	310	1.90
<b>.</b>							
For Treasury Use Only							
Date Paid							
Reference No.							
Bank Apat							
Bank Acct							
USD Amt							
(If in Foreign Currency)							

### GENERAL RELEASE

#### KNOW ALL PERSONS BY THESE PRESENTS:

That I Ronnie Smith , having an address at 3007 Peavine Fire Tower Rd, Crossville, TN 38571 , being of full age, in consideration of and upon receipt of a check in the amount of \$910.95 for repair of the 2005 Ford F250 sent as a gesture of goodwill ("Consideration"), do hereby release and forever discharge REMINGTON ARMS COMPANY, INC., its parent and affiliated companies and its/their predecessors, successors, assigns, employees, officers, agents and directors ("Releasees") from all debts, claims, demands, damages, costs, expenses, actions and causes of action what-so-ever nature or kind, known and unknown, on account of, resulting, or which may result from an incident occurring on or about November 8, 2010 which I have alleged was caused while using products manufactured and/or sold by Releasees.

I further state that receipt by me of the Consideration described above constitutes a full and complete settlement of the claims described above, that this release is a compromise and is not to be construed in any way as an admission by the Releasees of any responsibility for the incident, or for an alleged defect in said products or that any such defect exists.

I acknowledge that I have carefully read and understand the contents of this release and sign the same as my own free act.

Notary signature: 100000

**Print Name** 

Signature (Ronnie Smith)

Products (serial numbers):

G6901554 VIN1FTSX21P55EC31099

Social Security Number or Driver's License #

Response Vale:

PS 15605

	Case #	5051	Date of Call	11/10	Date of signification	11/8	PreLit Lit	Öbs	
`   	Reporter name address				Incident Name/Age address	Ja. 340	mes Ha I Manossa Ville, TN 1-260-2	rrist Co	op to
	contact #'s	-			contact #'s	Cook 93	(Ville, TN 1-260-2	38506 N	<i>,</i>
	email				email				
	Injury								
	Medical Treatment								
	Alleged cause								
	Firearm	Ser# (-690/554	Cal	DOM	Orig owner?	When/W	here purchased	VTR	
c dia		Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info		
	1200		TO STATE OF THE ST	- Canson	150gr.		<del>                                     </del>	e Silvert	D-
	Other Product								V
		Couple of for hun he made	fus	use to	Le LTO	ler,	They bough	+ UTRS	
		for hun	lag. W	ker fus	ned to	area	, doe	4//	
	ļ	ne had	safety	off s	1+ A	ed.	fulled voled a	11 back	
		1 2 40	uck, 1	ulled	shell		-7 -		- ,
	Notes:	1 + H	red. I	to yet	ahai	ir fr	lager in it	t pull	
,	Customer's Request							<i>J. J. J. J. J. J. J. J.</i>	
	My actions/								



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		11/10/2010 REQUE	STED BY:	christy	
QUANTITY:		1 WEIGH	T PER PACKAG	E:	10
Prevale Check One					
MEDIA					
COORDINATOR				XXXXXXXXXXXX	
TO MAIL		I WILL	MAIL		
DESCRIPTION:	<del></del>				
}		700			
	G6901554				
				3	
		LABEL INFO	RMATION		

	James Harris 3401 Manassas Rd Cookville, TN 38506	
RETURN ITEM TO:	Rem Prod Serv Ilion, NY	

## PLEASE COMPLETE ALL PARTS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION

4XX596 SVC GNDCOM TRACKINGH 1Z4 REF 1:JAMES H REF 2:700/G69	XX59690 HARRIS/C	ACT 67113	UT 10.0	CURR USD LBS	1 OF	•
HANDLING CHAP SINGLE-PTECE DV 0 00 DC 0.00 AH 0.00 TOT PUB CHG 1	PUB RA	OF CHR COD DGD PR	0 .00 0 .00 0 .00		T/P USD 0.50 0.00 0.00 8.74	

AHNO CHRISTY MITCHELL

FAX: 336-548-7872

FROM & JAMES HORRIS

3401 Manasias RD

Cookeville, TN 38506

ph# 931-260-3598

OfrmRepairMain - FGI Repairs  File Add Repair Estimate Repair Expedite Repair Inc	quiry Repair Tools CSR Tools Reports	Table Maintenance System L	ocation	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
File Add Repair Estimate Repair Expedite Repair Inc	quiry Repair tools Car roots Reports	S radio Wallerance System C	OCERION	
Repair Number: RE00212058 Serial: 06901554 : Model 700 CC 308 WIN Produced: 03/15/2009	ISKU 84371			
ADDRESS INFORMATION		2010 B:56:13 AM		
Curtomer Fleceve Name JAMES HARRIS	JAMES HARRIS	Received from		
Address 1. 3401 MANASSAS RIDAD  Address 2. PO Box	3401 MANASSAS ROAD PO Box:			
City COOKEVILLE  State TN Zip Code: 08506 Country US	COOKEVILLE  TN Zip Code: 39506 Countr	y. US		
	FL			
Contact / Condition   Problems   Estimate   History / Status   Shipping / B  Date   Code   User   D   Desc1	<u> </u>	Current Status		
12/1/2010 9:3: New valentds Repair Added 12/1/2010 9:4 Update valentds Repair Information char	☐ Interface Hold 12	2/3/2010 8:56:13 AM supryl		
12/1/2010 12: EmailSent ArmEmail Repair Received 12/1/2010 12: EmailVerified ArmEmail Receipt	JHARRIS201 Parts Received  JHARRIS201 Passed Inspection	Check In Repair Location ILN		
12/3/2010 8:5 ParkedExt supryfl Placed in PS Back Rac	ck Holding for d Has Been Approved / Internal Repair	Current Location  Transfer Number		
	F Exclude TATC		O Secretaria	
Repair Search		lefresh Close		
	A STATE OF THE STA	The state of the s		
The state of the s		·		
	The second secon			
	. Changada and the many of the same specific	ing parties of the second seco		
supryfi - ILN/Prod frmRepairM	TO CONTROL OF THE SECOND CONTROL OF THE SECOND SECO	DI LO2R7XPIL	Friday, Dec 3 2010	10:28 AM

12/7 He's saying return it.
12/7 Danny of a reimbursing for truck.
He will fox receipt for truck repair.

	EC	رَقَ	ي ا	W I	
皿	DEC	**		2010	
В	Y:				

4.0 lbs

from null position safety walks forward until discharge with repeated pulling of the trigger,

Could not get the gon to fire unless the trigger was polled.

November 10, 2010

we should offer to settle this with customer - replace trigger assembly and pay damages

James Harris 3401 Manassas Rd Cookville, TN 38506

Subject: #5051, Model 700

Dear Mr. Phillips, 7

Per our phone conversation, enclosed is the prepaid UPS ground shipping label for shipment of the firearm to our factory for inspection. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mit Consumer A Phone: 800christy.mite <sup>2</sup>G6901554

Model: 700

RE00212058

enclosure

DEAR REMINGTON,

As I mentioned on one phone conversation, I DO HAVE DAMAGES TO A VEHICLE DUE TO THE DEFECT of my Rifie. Plage consider the damages of \$1,075 of that occurred when my Rifie Ducharano. Lucker NO ONE WAS HURT!

SINCERRLY, JAMES HARRIS


Ph# 931-260-3598

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

	Model Number: 700 VTR	Serial Number: G 69	01554				
	Are you the original owner?: YES NO						
	Name: JAMES HARRIS ->	Date of Purchase: NO	VEMBER 2009				
	Address (no PO Boxes): 3401 MANASCAS ROAD						
	City: COOKEVILLE	State: 70	zip: 38506				
	Phone (Daytime): 931 - 260-3598	Fax:					
	E-mail Address:(if e-mail address is provided, notification		De :				
	sent) Sharris 205@ hotmail.com =						
	I would like to receive future e-mail updates from Re	mington.					
	Please describe your problem and date of occurrence	9;					
	THE GUN DISCHAIGED THREE 7	THE TRIBLER.	<u></u>				
	THE THIRD TIME THE GUN	WENT OFF, IT	- DISCHARGEA				
,	when A swell was chambered THEN Fines on It's ON Sho	4 THE BOLT LOCK	$\epsilon \nu - \epsilon$				
	board of she truck.	B)(() C)					
			X				
	500 characters left						
	Ammunition Information: WINCHESTER	-					
	Manufacturer: WIN CHESTER	Type: Supreme					
	Other (i.e. bullet weight/type, shot size, powder):	0.6nx12					
rear rear		Powder Weight:					
<b>₫</b> G69(	01554	T X					
Model:	700 -	Primer Used:					
1.10515	Reloader Used:						

PS 15611





Trig Waiver? Warning Ltr if they won't Roth sign. Documenting Mayle / supry
Balic.
Nick.

Evans dus