

Remington Arms Co., Inc.

Product Service

Legal Case #:5738

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
220245	1/21/2011	1/24/2011	1/24/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Clydes Sport Shop		Clydes Sport Sh	2307 Hammonds Ferry Rd.	Baltimore	MD	21227		W 410-242-6108

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent gun in for customer. Dealer stated that gun fires when safety is taken off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/2506 SPR	n/a	A6634397	OQ	7/13/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	OUTDOOR SPT HQ WILLOWBROOK IL		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$38.40	2/9/2011				

Per Ilion - TA dirty & sticky. Sear will bind and work sluggish. Replace TA, clean & test fire under BLM - quote. Dealer apprvd quote & pd. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/24/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4054	As received Follows Down	POOR MAINTENENCE
Barrel	Description		24" 2506 REM
	Date Code		OQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	ACTION ONLY
	Stock Condition	--Select--	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.010
	Notch	Slightly Worn; Not Functioning	DIRTY, STICKY, BINDS
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	SEAR STICKS TO SIDE PLATES WILL FOLLOW DOWN
	Pull	--Select--	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

FROM:
CLYDE BLAMBERG
(410) 242-6108
CLYDE'S SPORT SHOP INC
2307 HAMMONDS FERRY RD
BALTIMORE MD 21227

7 LBS 1 OF 1 ATNO 0NID

SHIP TO:

REPAIR DEPT.
REMINGTON ARMS CO.
14 HOEFLER AVE.
ILION NY 13357

REPAIR
TAG



F

456665


FIRE 1/1 TAKEN SAFETY OFF
RETURNING FOR REPAIR

CLYDE'S SPORT SHOP INC.
2307 Hammonds Ferry Road
BALTIMORE, MARYLAND 21227
Phone (410) 242-6108

22

A6634397

Model: 700



RE00220245

JAN 25 2011

BY:

T.A. DIRTY & STICKY. SEAR WILL BIND AND
WORK SLUGGISH. Replace TPA, clean &
test fire under BLP for 2000 + 546

Quote

