

Remington Arms Co., Inc.

Product Service

Legal Case #:5925

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
223934	2/22/2011	2/23/2011	2/23/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Arthur J	Dyer	300 Garfield St	McMinnville	TN	37110		H 931-607-2629 E jimdyer@blomand.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fires on safe release	Cause:4015 Improper Maintenance Concern:1007 Fired on Safe Release	Unknown	
C				

3/8/11 Per letter with rifle, if he pulls the trigger with the safety on and pull hard the gun will discharge when I release the safety. This has caused no damage but needs to be fixed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	n/a	A6414275	LO	2/11/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMMONS GUN OLATHE KS		N			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV

Per Ilion,
replace TPA,

clean, test fire
at BLSM
program price

Repair/Replacement Cost	Repair/Replacement Date
30.40	3/8/2011

3/8/11 Per Ilion, trigger assm dirty & rusty, sear working sluggish. Replace TPA, clean, test fire at BLSM program price at \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/23/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPR
	Date Code		LO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	

	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,RUSTY SEAR WORKING SLUGGISH
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Factory Repair Form

Print

Reset

5925


22"
LO2/7
5.50
1,007

Model Number: 700		Serial Number: A6414275	
Are you the original owner?: ☐ YES ☒ NO			
Name: Arthur J. Dyer		Date of Purchase: approx 2007	
Address (no PO Boxes): 300 Garfield Street			
City: McMinnville		State: TN	Zip: 37110
Phone (Daytime): 931 607 2629		Fax: 931 473 5516	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) jimdyer@blomand.net			
E-mail Address: ☒ I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: If I pull the trigger with the safety on, and pull hard, the gun will discharge when I release the safety. This has caused no damage but needs to be fixed. The previous owner may have tampered with the trigger and gotten it out of factory specs. Please repair or reset the trigger and safety mechanism so they are working properly. I think the previous owner left it in a case too long also. If you can reblue the barrel, let me know what that costs. See anything else to do? Let me know. Thanks.			
4 characters left			
Ammunition Information: Manufacturer: Type: Other (i.e. bullet weight/type, shot size, powder):			
BY: FEB 25 2011			

Email me for credit card info.

T.A. dirty, sticky & rusty, SEAR WORKING sluggish. Repaired TFA, CLEAN & Test Fire under BLP, COIL & 20.00 + ship.

Serial Number: A6414275
Model: 700



RE00223934

Information:
Powder Weight:
Primer Used:
Reloader Used:
ing and Lubrication):

27
20
20.40
67.40
37. —
30.40



