

Remington Arms Co., Inc.
Product Service
Legal Case #:5818

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
221929	2/3/2011	2/4/2011	2/4/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mtn.	---	Gander Mtn.	1500 West Chestnut St.	Washington	PA	15301		W 724-229-9800

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

Dealer sent gun in for consumer. Consumer stated rifle had a slam fire. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl. DOM
Remington	CF/BA	700/22-250 REM	n/a	6832823 LZ 2/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner	
	JERRYS SPORT CTR OLYPHANT PA	TWO PIECE BASE,BOTTOM HALF RINGS	U	

CONCERN:SLAM FIRED

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM program						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	2/17/2011				

2/17/11: Per Ilion - TA dirty & rusty. Replace TA, clean & test fire under BLM program - quote. Quote fixed to Roy Christensen. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		2/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	MAINTENANCE AND ALTERATIONS
Barrel	Description		24" 22-250 REM
	Date Code		LZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, RUSTY
	Pull	---Select---	4.5#
	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, BOTTOM HALF RINGS



Service Request
Service Order # 4472

5818

24"
L23
455
004

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726
14 Hoefler Ave

Illon, NY 13357

Attn:

Date Shipped: 01/27/2011

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 8-25-125-01-7B-01346
Attn: Gun Parts Dept.
1500 West Chestnut St.
Washington, PA 15301

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type: Rifle

Serial Number: 6832823

Model: 700

Cal/Ga: 22-250

Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

700 22-250 with old trigger (can't open on safe)

REASON FOR RETURN:

Customer had it slam fire on him

ATTENTION VENDOR

Please contact me with any questions or concerns.

Michael Boyza


(724) 229-9800

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence.

SHIP TO ABOVE ADDRESS


Forward all invoices to: Gander Mountain
Attn: Cindy Kilbride
180 E. Fifth Street Suite 1300
St. Paul, MN 55101



BY:

6832823

Model: 700



RE00221929

T.A. dirty + rusty. Repla TPA,
clean + Test fire under RLP
for \$20.00 + ship

Quote

