

Remington Arms Co., Inc.
Product Service
Legal Case #:5847

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
222406	2/8/2011	2/9/2011	2/9/2011				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Robert	Mele	740 Fairgrounds Rd	West Kingston	RI	02892		H 401-782-1224 C 401-639-4631

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired when safety was removed Concern:1007 Fired on Safe Release			
C				

2/28/11 Per note with rifle, one time this rifle dry fired when he removed the safe. He was cleaning the rifle at the time. He has heard there was a recall and wants fixed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	660/222 REM	n/a	6209334	BS	1/1/1969
Date Purchased	Where Purchased	Accessories	Original Owner			
	BERNARD GITLIN HARTFORD CONN	SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at no charge under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	45.06	2/28/2011				

2/28/11 Per Ilion, could not duplicate concern. Trigger assm very dirty, has excess lube and debris stuck to bottom of sear. Replace TPA, clean, test fire at no charge under recall.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/9/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 222 REM
	Date Code		BS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	MAG SPACER MISSASSM
	Bulged	False	
Safety	Description		M/660 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY, STICKY, EXCESS LUBE, DEBRIS STUCK TO BOTTOM OF SEAR
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE


5847

7011
851/69
311
-009

Serial Number

6209334

Model: 660



RE00222406

could not duplicate concern
T.A. very dirty, was excess lube
+ debris stuck to bottom of seal.
replace T.A., clean & test fire at
N/c under NUAL.

_____ #230145 _____

27 -
18.06
45.06

RECEIVED
FEB 15 2011

BY: _____

ROBERT MELE
740 FAIRGROUNDS RD
WEST KINGSTON, R.I. 02892

RE: REMINGTON MOD #660 .222 CAL
#6209334

DEAR REMINGTON,
I LOVE MY REMINGTON RIFLES
AND SHOT GUNS.

1 MOD 660 .222

1 MOD 700 300 WIN MAG

1 MOD 700 7mm MAG

2 MOD 700 MUZZLE LOADERS

2 MOD 1187 12 GA

1 MOD 870 12 GA

1 MOD 5 .22 CAL

ONE TIME THIS MODEL [#]660 DRY FIRED
WHEN I REMOVED THE SAFE. I WAS
CLEANING THE RIFLE AT THE TIME.

PLEASE FIX, UP GRADE AND
WHAT EVER. I WAS TOLD THAT
THERE WAS A "RECALL"

CELL 401-639-4631

HOME 401-782-1224

THANKS,
Bob

