

Remington Arms Co., Inc.
Product Service
Legal Case #:5937

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
224268	2/24/2011	2/25/2011	2/25/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sportsman's Warehouse	----	Sportsman's War	6640 Lonetree Blvd.	Rocklin	CA	95765		W 916-782-9900

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Unexplained discharge			

Dealer sent rifle in for customer. Dealer stated gun fired without trigger pull. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CP/BA	700/7MM REM MA	27271	S6607482	AB	3/26/2007 10:00:21 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	PACIFIC FLYWAY WHOLESALE	SCOPE,RINGS,TWO PIECE BASE,HARD CASE	U			

CONCERN:FIRED WITHOUT TRIG PULL

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Uion - Repair @ n/c - goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$52.75	3/9/2011				

3/9/11: Per Uion - Could not duplicate concern. TA dirty. As goodwill gesture & to restore confidence in rifle - will replace TA, clean & test fire at n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		2/25/2011
	Product Type		RF
	Action Type		A
	Assigned To		J. NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		26" 7MM REM MAG SS
	Date Code		AB
	Bore Plugged	False	

Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; functioning	ACT DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	



Repair Facility: REMINGTON
 Address: 14 HOEFLE AVE
 City: ILLION State: NY Zip: 13357
 RA/RMA Number: NA
 Insured Value: \$\$ 4

5937

2011
3/3/07
4.5a

Store Information: (Use Store Address Stamp Here)

Sportsman's Warehouse #149
 6640 Lonevue Blvd
 Rocklin, CA 95765

Store Phone Number: 916-782-9988 782-9900

Firearm Information:

Manufacturer / Importer: Remington

Common Model: 700 Caliber/Gauge: 7mm

Serial Number: S6607482 Type: Bolt Action

Log Number: 4926-0827 (i.e. Store number (XX) followed by book (25) and log # - XX26-XXXX)

Shipped with the following: ☐ Magazine(s) ☐ Scope ☐ Rings ☐ Bolt
☐ Chokes ☐ Other

Problem: (Be as specific as possible)

Gun fired without trigger pull.

Customer Name: Dennis Hembree

Customer Phone: (530) 713-0620


RECEIVED
MAR 2 2011

BY: _____

rent by year.
Rev. 4/08

S6607482

Model: 700



RE00224268

could not duplicate concern.
 TPA dirty. AS A Good Will Gesture
 no restore confidence in rifle
 will replace TPA, clean & test fire
 AT W/L.

