

Remington Arms Co., Inc.  
Product Service  
Legal Case #:1138

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 127016 | 3/20/2007   | 3/21/2007       | 3/21/2007   |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street           | City       | State | Zip   | Age | Contact                          |
|----------|----------|------------|-----------|------------------|------------|-------|-------|-----|----------------------------------|
| Reporter |          | Will       | Lee       | 31 Sally Burr Rd | Litchfield | CT    | 06759 |     | H 860-567-4005<br>C 203-509-2969 |

## Incident Information

| Claims | Codes                                                    | Repair Est. | Medical Treatment | Medical Status |
|--------|----------------------------------------------------------|-------------|-------------------|----------------|
| PI     |                                                          |             |                   |                |
| PD     | Cause:4038 Could Not Duplicate Concern                   |             | Unknown           |                |
| S      | Fired on bolt closing Concern:1008 Fired on Bolt Closing |             |                   |                |
| C      |                                                          |             |                   |                |

3/26/07--correspondence from repair-Cust was having trouble with the bolt and safety on this rifle. On several occasions, it was very hard to close the bolt with a bullet in the chamber twice firing while closing the bolt while safety was engaged.lw

## Firearm Information

| Mfg.           | Type                    | Model/Ga.            | SKU            | Serial   | Bbl. | DOM        |
|----------------|-------------------------|----------------------|----------------|----------|------|------------|
| Remington      | CF/BA                   | 700/308 WIN          | 25711          | D6830136 | RO   | 11/15/1994 |
| Date Purchased | Where Purchased         | Accessories          | Original Owner |          |      |            |
|                | JERRYS SPORT CENTER INC | TWO PIECE SCOPE BASE | U              |          |      |            |

## CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

| Settlement                     | Release of Claims       | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|--------------------------------|-------------------------|--------------|---------------|-----------------|----------------|---------------|
| Quote to replace TA at 1/2 msp |                         |              |               |                 |                |               |
| Repair/Replacement Cost        | Repair/Replacement Date |              |               |                 |                |               |

3/26/07-quote sent to replace TA at 1/2 msp due to trig set screws altered.lw

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                        | Comment                                 |
|-------------|--------------|-----------------------------|-----------------------------------------|
| Examination | Examiner     |                             | B.TRAVIS                                |
|             | Exam Date    |                             | 3/21/2007                               |
|             | Product Type |                             | RF                                      |
|             | Action Type  |                             | A                                       |
|             | Assigned To  |                             | F.SUPRY                                 |
| Cause       | 4038         | Could Not Duplicate Concern |                                         |
| Barrel      | Description  |                             | 18" 308 WIN HB (ALTERED) W/MUZZLE BRAKE |
|             | Date Code    |                             | RO                                      |
|             | Bore Plugged | False                       |                                         |
|             | Bulged       | False                       |                                         |
|             | Fired        | False                       |                                         |

|           |                        |                            |                       |
|-----------|------------------------|----------------------------|-----------------------|
|           | Fired while Obstructed |                            |                       |
|           | Muzzle/Crown Condition | Worn; Functioning          |                       |
| Bolt      | Firing Pin             | Slightly Worn; Functioning |                       |
|           | Stroud                 | Slightly Worn; Functioning |                       |
|           | Face                   | Slightly Worn; Functioning |                       |
|           | Handle                 | Slightly Worn; Functioning |                       |
|           | Stop                   | Slightly Worn; Functioning |                       |
| Extractor | Condition              | Slightly Worn; Functioning |                       |
|           | Out Condition          | Slightly Worn; Functioning |                       |
|           | Ext/Eject Test         | False                      |                       |
| Locking   | Block Condition        | --Select--                 |                       |
|           | Lug Condition          | Slightly Worn; Functioning |                       |
|           | Notch Condition        | --Select--                 |                       |
| Overall   | Exterior Condition     | Slightly Worn; Functioning |                       |
|           | Stock Condition        | Slightly Worn; Functioning |                       |
|           | Fore End Condition     | --Select--                 |                       |
| Receiver  | Condition              | Slightly Worn; Functioning |                       |
|           | Bulged                 | False                      |                       |
| Safety    | Description            |                            | STANDARD M/700 SAFETY |
|           | Function               | Like new; Functioning      |                       |
| Sear      | Lift                   | --Select--                 | 017                   |
|           | Notch                  | Like new; Functioning      |                       |
| Tests     | Test Fired             | False                      |                       |
|           | Feeding Test           | False                      |                       |
| Trigger   | Condition              | Slightly Worn; Functioning |                       |
|           | Pull                   | --Select--                 | 3#                    |
|           | Altered                | True                       | SET SCREWS ALTERED    |

1138

20 11/94 18" 2nd

RECEIVED

MAR 26 2007

BY: *[Signature]*

To Whom it may Concern

I was recently having  
trouble with the bolt

and the safety on this  
rifle, on several occasions

it was very hard to

close the bolt with a

bullet in the chamber

twice firing while closing

the bolt while safety  
was engaged

~~TPH~~ TPH ASSM. SET SCREWS  
ALIGNED. REMOVE TPH, check over,  
clean. 4T 1/2 msp. Quote

if you need to  
reach me my name

is Will Lee  
31 Sally Burr Rd.  
Litchfield Ct,  
06759

~~860 560~~

H. 860 567-4005

C 203 509 2969


Please do not tighten  
muzzle brake. I use an  
advance arm. Suppressor.  
Thank you.

Will Lee  
31 Sally Burr Rd.  
Litchfield Connecticut  
06759

Serial  
Number:

D6830136

Model: 700



RE00127016

