

Remington Arms Co., Inc.
Product Service
Legal Case #:6211

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
230013	4/28/2011	5/18/2011	5/18/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	AccuFlite Arms Inc		AccuFlite Arms	PO Box 484 5120 Old WM Penn Hwy	Export	PA	15632		W 724-733-3666
Incident		Larry	Ruffner Latrobe			PA			H 412-779-2369

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	May have fired without trigger being depressed	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

6/2/11 Per note with rifle, the customer claims the gun may have fired without the trigger being depressed. Also, at times the bolt release assm allows inadvertent bolt release when the rifle is moved to a vertical position. This usually happens after the bolt has been reinstalled in the action.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 RUM	25971	S6426898	RV	11/6/2001 6:59:46 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT (OH) CORPORATION		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, offer to replace TPA, clean, test fire at 1/2 price						
Repair/Replacement Cost	Repair/Replacement Date					

6/2/11 Per Ilion, could not duplicate concern. Trigger assm very dirty. Can offer to replace TPA, clean, test fire at 1/2 price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/18/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 300 RUM SS
	Date Code		RV
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	ACT VERY DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY
	Pull	---Select---	4#
	Altered	True	PULL SCREW ADJUSTED
	Sub-Assembly	M/700 Non-Bolt Lock	

6214

2611
4#
RVH/0
.013

INVOICE NO

AA19871



ACCUFLITE ARMS INC.

WHERE TOP VALUE IS CUSTOM!

5120 OLD WM PENN HWY

PO BOX 484

EXPORT, PA 15632-0484

SYNONYMOUS WITH QUALITY!

WEB SITE:

www.accuflite.com

E-mail

accuflite@earthlink.net

Phone Fax

724 733-7033

TECHNICAL:

724-327-0100

ORDERS:

800-666-SAKO(7256)

SERVICE:

724-733-3666

CUSTOMER APPRECIATION

1335701 42011

NO.

NAME:
ADDRESS

REMINGTON ARMS CO.

#14 HOEFLER AVENUE

ILION, NY 13357

PHONE:

800-243-9700

E-MAIL

Attention: Warranty Repair Dept.

QUANTITY
DESCRIPTION

PRICE /UNIT

TOTAL(\$)

1

REMINGTON 700 LAMINATE 300 REM ULTRA MAG

S/N S6426898

*CUSTOMER CLAIMS GUN MAY HAVE FIRED WITHOUT
THE TRIGGER BEING DEPRESSED.

ALSO, AT TIMES THE BOLT RELEASE ASSEMBLY ALLOWS
INADVERTENT BOLT RELEASE WHEN THE RIFLE IS MOVED
TO A VERTICAL POSITION. (This usually happens after the bolt
has been reinstalled in the action.)

Name and phone number of firearms owner is as followsL

Mr. Larry Ruffner Latrobe, Pennsylvania 412-779-2369

could not duplicate concern.
T.A. very dirty. can offer to
replace TPA, clean + test rifle
at 1/2 normal cost. Quote

Thank You For Your Order!

ACCUFLITE ARMS, INC. PROVIDES CUSTOM BOLT
ACTION RIFLES TO CREATE RAVING RIFLEMEN!

SUBTOTAL

\$PREPAID

CREDIT

\$

TAX

\$

INS, SH.

\$

TOTAL

\$

loss, injury, damage, or liability of any nature caused by any failure, defect,
firm, corporation, or any other entity. Accuflite Arms Inc. relies solely

S6426898

Model: 700



RE00230013

RECEIVED
MAY 23 2011

BY:









