

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6198

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
231316	5/12/2011	5/13/2011	5/13/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Patrick	D'Antoni	8345 Twin Rock Trail	Reno	NV	89523		H 650-464-7858 E dantonip@gmail.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4006 Fired when bolt closed	Altered Adjustments or Components Concern:1008 Fired on Bolt Closing	Unknown	
C				

5/26/11 Per note with rifle, bolt will not close. Has the "J" lock and he does not have a key to unlock. On two occasions he closed the bolt without touching the trigger and when the bolt closed the round went off. The trigger is set so light that if you just touch it the round will go off.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	27512	G6385192	KY	5/14/2004 8:10:19 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	MT SPORTS, LLC		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

5/26/11 Per Ilion, trigger assm dirty and set screws altered. Spent primer in action preventing bolt from closing. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/13/2011
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	SPENT PRIMER IN ACTION PREVENTING BOLT FROM CLOSING
Barrel	Description		24" 22-250 REM
	Date Code		KY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.015
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

24"  
145/04  
2#  
1015

6198

To: Remington

From : Patrick D'Antoni  
8345 Twin Rock Trail  
Reno, Nevada 89523

R: Model 700  
Serial # G6385192

Problems :

- 1) Bolt will not close. This model has a j slot security system. However I do not have a key for the slot and have never used this system. In any case the red dot is showing from the rear.
- 2) When using the rifle, on two occasions I have closed the bolt without touching the trigger and when the bolt closed the round went off.
- 3) The trigger is set so lite that that if you just touch it, the round will go off.

Thank You for your attention to my issues. I own 2 other Remington Rifles ( 700 BDL and 700P ) and 2 Remington Shotguns ( 2 -1100's ) and love the products.

Patrick D'Antoni  
650-464-7858  
dantonip@gmail.com

RECEIVED  
MAY 20 2011

BY:.....

Serial Number:  
**G6385192**

Model: **700**



**RE00231316**

T.A. dirty & set screws altered.  
spent primer in action preventing  
bolt from closing. Can offer to  
replace TPA, clean & test Rine at  
1/2 normal cost.

Quote









