

Remington Arms Co., Inc.
Product Service
Legal Case #:6276

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
233321	6/8/2011	6/10/2011	6/10/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Vince	Diez	1406 Coontrap Rd.	Gonzales	LA	70737		H 225-647-3608 C 225-907-4045

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Customer sent rifle in w/a note - stated gun fires when safety is turned off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30069 SPRG	n/a	A6773927	PV	6/5/1979
Date Purchased	Where Purchased	Accessories	Original Owner			
	KEI K MART FAIRLESS HLS PA		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	6/24/2011				

6/24/11: Per Ilion - TA dirty, sticky, rusty. Replace TA, clean & test fire under BLM - quote. Customer apprvd & paid by check. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/10/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		PV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,RUSTY WILL FOLLOW DOWN
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Vince Diez

1406 Coon trap Rd. ♦ Gonzales, LA 70737
Phone (225) 647-3608 ♦ Fax (225) 647-6801
diezsigns@eatel.net

22
PV6/7
S.S.
.012

6276

June 2, 2011

I am sending this gun in for repairs, it fires when the safety is tuned off.

Shipping & Contact info

Vince Diez
1406 Coontrap Rd
Gonzales, LA 70737

225-647-3608 Phone
225-907-4045 Cell

Fires, Unintentionly

Serial
Number:

A6773927

Model: 700



RE00233321

T. A. dirty, sticky, rusty.
Replace TPA, clean & test fire
under BCP for \$20.00 + ship

Quote

RECEIVED
JUN 22 2011

BY:.....









