

Remington Arms Co., Inc.
Product Service
Legal Case #:6221

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
231999	5/20/2011	5/23/2011	5/23/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Jeffery	Hines	152 Legacy Ln.	Benson	NC	27504		H 919-894-7107 E jdhines@embarqmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C FBC				

Customer sent rifle in with our repair form. He stated that he wanted the bolt lock modification done. He stated a relative borrowed the rifle about 20 yrs ago & reportedly had a FBC with it. He dismissed it as improper handling but has since read some information that makes him think what happened was possible. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	B6374518	LC	2/25/1982
Date Purchased	Where Purchased	Accessories	Original Owner			
	JC PENNY STATESVILLE N C	TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	6/2/2011				

6/2/11: Per Ilion - Could not duplicate concern. TA dirty, set screws altered. Replace TA, clean & test fire under BLM - quote. Customer aprvd. quote & paid. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/23/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		LC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Like new; Functioning	BINDS,STICKY
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	MUZZLE BRAKE IN BBL
	Stock Condition	Slightly Worn; Functioning	SCRATCHES,MARS,DENTS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Test Fired	False	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

6221

221
LC 2/82
4#
1012

Model Number: 700		Serial Number: B6374518	
Name: Jeffery D. Nines		Date of Purchase: Approximately 1985	
Address (no PO Boxes): 152 Legacy Lane			
City: Benson		State: NC	Zip: 27504
Phone (Daytime): 919-894-7107		Fax:	
E-mail Address: jdhines@embarqmail.com			
Please describe your problem: Returning the firearms in response to Remington's Bolt Lock Safety Program and prefer to have the bolt lock removed and receive the safety certificate. NOTE - a relative borrowed this rifle from me and reported a discharge upon chambering a round. This occurred about 20 years ago and I have always dismissed it as improper handling since it has never happened to me. After reading some of the information available, I now think it is possible that it did happen as described. <i>could not duplicate concern T.A. DIRTY set screws altered. Rep me JPA, clean + rest fire under BLP Ron 20.00+ ship.</i> 24 characters left <i>Quide</i>			

contact the Repair Center for services
nated repair time.

Serial Number:

B6374518

Model: 700



RE00231999

IF OR SPENT SHELLS IN YOUR
(WITH THE FIREARM. **THIS IS A** ;
(YOU FEEL YOU MUST SEND SPENT
SEPARATE PACKAGE AND INCLUDE
E), TELEPHONE AND MODEL AND
OF YOUR FIREARM.

your firearm before sending it.

- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset

RECEIVED
MAY 31 2011

BY: _____









