۰. س ٠

Remington Arms Co., Inc. Product Service Legal Case #:6226

Case Infor	mation										
RE#	Date (Opened	Date Openeo	I(PS) Date	Closed	Incid	lent Dat	e	Pre Lit	Lit	Obsolete
232112	5/23	/2011	5/24/201	1 5/24	4/2011						
Customer	Information										
Туре	Business	First Name	Last Name	Street	C	ity	State	Zip	Age	C	ontact
Incident		George	Porter	279 Crimson Ln.	Max M	leadows	VA	24360			-637-3150 d@aol.com
Incident In	formation										
Cla	aims		Codes		Repai	r Est.	Medi	cal Tre	atment	Mee	lical Status
PI											
PD		Cause:	4015 Imprope	er Maintenance			1	Unknow	-		
S		Concer	n:1008 Fired or	Bolt Closing			,	UIIKIIOW	/11		
C FBO	C & FSR										
				He stated rifle will f the last 10 yrs. df	ire when loc	king bolt	down &	rifle w	ill fire wl	hen safet	y thumbed
Firearm In	formation										

ricarin information							
Mfg.	Туре	Model	/Ga. 5	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270	WIN	n/a A	6293230	CI	4/27/1976
Date Purchased	Where Purchased	Access	ories Origin	al Owner			
Ň	ROANOKE CORP ROAN	IOKE VA		Y			
CONCERN: FBC,FSR							
Ammunition Information -	None Defined						
Other Products Information	- None Defined						
Settlement							
		Remington/700/CF/I	ЗА				
Settlement	Release of Claims	Release Date	Reimburseme	nt Cash Settlement	Reim. AP		Cash Date APV
Per Ilion - Quote to repair under BLM							
	Repair/Replacement	Repair/Replacement					
	Cost	Date					
	\$30.40	6/2/2011					
6/2/11: Per Ilion - TA dirty credit card. df	\$30.40	6/2/2011	test fire under BI	.M - quote. Cust	omer appr	rvd que	ote & pd

Examination[Remington/CF/BA]

Part	Sub-Part	Code —	Comment
	Examiner]	B.TRAVIS
	Exam Date]	5/24/2011
Examination	Product Type]	RF
	Action Type]	Α
	Assigned To]	T.NAGLE
Cause	4015	Improper Maintenance	
	Description]	22" 270 WIN
	Date Code]	CI
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
][]	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6226&Type=Case

6/2/2011

.

١

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning]
	Shroud	Slightly Worn; Functioning]
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
for i	Condition	Slightly Worn; Functioning]
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition]
	Fore End Condition	Select]
Receiver	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False]
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,PARTS WORK SLUGGISH WILL FOLLOW DOWN
Trigger	Pull	Select	4#
	Altered	Тгие	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock]

Factory Repair Form			Page 1 of 3 -2^{11}
	- 6 ²	26	CEY
Print		Reset	CB III
Model Number: REM. Model	100	Serial Number: A 6293230	
Are you th	ne original own	ner?: Z YES 🖾 NO	
Name: (JEORGE E F	ORTER	Date of Purchase:	
279 CRIM	Address (no l 150N LAW		
City: MAX MEAD	ow5	State: VA. Zip: Z	4360
Phone (Daytime): 276-637-	3150	Fax:	
E-mail Address:(if e-mail ad be sent) チAィレ	dress is provide oud @ AO	ed, notification of receipt and shi ししょ COM	pment will
L would like to r	E-mail Ac	dress: -mail updates from Remington.	
		m and date of occurrence:	
1-Rifle will	fire whe	N LOCKING BOLT DOWN	
2-Ritle will	five whe	N SAFETY THUMBED OF NL blen Sport Dic SLuggish, lipty LS: SLuggish, lipty LS: Rive ander isc of racters left (F
These pro	blems ha	ve been sportadic	1. 12 anto work
OVER THE 18:	st ten ye	SLuggish, Uphy et T	PA cleAMETEST
	500 char	racters left	enote
	Ammunition In	nformation:	
Manufacturer: REMINGTO)N	Type: 1509R. CORE-LOI	(T SP
Other powder):	(i.e. bullet weig	ght/type, shot size,	
	· · · ·		
	Handload In		
Powder I leed		Powder Weight:	
A6293230	-	Primer Used:	-
Model: 700	1	Reloader Used:	CEIVEN
			AY 3 1 201
	_	BY:	
RE00232112	2	asp	5/17/2011

.

1

	you clean the bore? (Months or Number of
	unds) AFTER EACH USE
	vou clean the action? (Months or Number of unds) AFTER EACH USE
How often do you cl r	ean the trigger assembly? (Months or Number of ounds)
Brand of lubricant u	used: REMINGTON
How often do ye	ou lubricate the bore? (Months or Number of unds) AFTER EACH USE
	u lubricate the action? (Months or Number of unds) AFTEN EACH USE
	ricate the trigger assembly? (Months or Number of ounds)
Have you reviewed the clean in our c	ing and maintenance recommendations on our web site or owners manual? >
When was the last time tha repairman/gur	at your firearm was serviced by a Remington authorized nsmith?) NEUER
performed?)	What were the services
Ship your INSU	RED firearm by either UPS or Parcel Post to:
	Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
THE SAME BOX WITH THE I YOU FEEL YOU MUST SEPARATE PACKAGE A	ID LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF SEND SPENT SHELLS PLEASE SEND THEM IN A AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), DDEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Pack your firearm for safety ship in a firearm t :: Remove all access	rial number of your firearm before sending it. y and to prevent further damage in shipping and handling. Preferably, box. (Note: Original boxes may not be returned.) ories from your firearm to prevent loss or damage. n both the outside and inside the box. Shipments without a proper

- -

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your

Visk 4820 0074 6015 8806 EXP 01/12
For Repairs over \$75.00, you-will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

From: Remington Information <info@remington.com>

To: faybud <faybud@aol.com>

Subject: misfire of remington model 700 .270 cal. [Incident: 110508-000024]

Date: Mon, May 16, 2011 10:23 am

Recently you requested personal assistance from our on-line support center. Below is our response.

We will assume your issue has been resolved if we do not hear from you within 72 hours.

Thank you for allowing us to be of service to you.

To access your question from our support site, click here.

Subject

misfire of remington model 700 .270 cal.

Discussion Thread

Response (Danny)

05/16/2011 10:23 AM

We regret that you are experiencing problems with your firearm. Based on the information you have provided, we suggest that you send your firearm to our Ilion, NY facility.

You can print the factory repair form and instructions at the following section of our site.

http://www.remington.com/pages/support/factory-repair-form.aspx

Or follow these guidelines if in the US:

1. Record the serial number of your firearm before sending it to us.

2. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box, not a hardcase.

3. Remove all accessories from your firearm to prevent loss or damage. This would include scope, slings, or extra choke tubes.

4. Enclose a letter with the firearm detailing the model name or number of your firearm and serial number along with a full description of the problem. Be sure to include your full name and address (P.O. Box and Street Address), including zip code, daytime telephone number, and e-mail address.

5. Ship your firearm by either United Parcel Service (UPS) or Parcel Post (US Post Office). Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Customer is responsible for shipping charges to the factory.

For U.S. repairs only, ship to:

Remington Arms Company, Inc. Attn: Arms Services Division/Repairs

05/08/2011 12:41 PM

14 Hoefler Avenue Ilion, NY 13357

ŧ

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

If you have any questions as to the warranty on Remington firearms, please refer to the following section of our site.

http://www.remington.com/pages/support/firearm-warranty-information.aspx

Customer (1 fbpottier)

I purchased this rifle around 1970 (snA6293230)and had no problems until about ten years ago.

1- rifle will fire when locking bolt down.

2-rifle will fire when safety thumbed to fire position.

Have shot a maximum of 240 rounds in the rifle. Was there a recall for this problem that I missed?

Thank you PLEASE ADVISE

George Porter

279 crimson lane

Max Meadows Va 24360

ph 276 637-3150

Question Reference #110508-000024

Product Level 1: Firearms Date Created: 05/08/2011 12:41 PM Last Updated: 05/16/2011 10:23 AM Status: Waiting

5/17/2011







