

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6233

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
233385/233339	6/9/2011	5/26/2011	6/10/2011	5/24/2011			

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident	Fairborn Police Dept	Bill	Titley	70 West Hebble Ave	Fairborn	OH	45324		C 937-313-5142 E bill.titley@ci.fairborn.oh.us

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired when safety released Concern:1007 Fired on Safe Release			
C				

5/26/11 Per call from Titley, 2 days ago when shooting his dept issued 700 he pulled the trigger while the safety was on. It didn't fire and it was then that he realized he had not removed the safety. When he flipped it to fire, it fired without pulling the trigger. The dept has another 700 with a "Walker" trigger that they want to send and have the trigger replaced. Titley had taken our Armorer's School but would rather send these to the factory after after this incident.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25711	C6862998	LO	2/15/1994
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRY'S SPORT CENTER INC	SCOPE BASE,BOTTOM HALF OF RINGS	U			

CONCERN:FSR

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25711	E6747974	PV	6/6/2001 10:41:08 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	KIESLER POLICE SUPPLY INC	SCOPE BASE,BOTTOM HALF RINGS	U			

CONCERN:FSR

## Ammunition Information - None Defined

## Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Quote to repair both at 1/2 normal cost						

## Repair/Replacement Cost Repair/Replacement Date

5/26/11 Mailing 2 ARS labels to the dept.cm 6/24/11 Per Ilion, serial number ending in 998, could not duplicate concern. Trigger assm pull screw altered. Check over completely, replace TPA with 40X, clean and test fire at 1/2 normal cost. Ser # ending in 339, they could not duplicate concern. Check over completely. Replace TPA with 40X, clean and test fire at 1/2 normal cost. Emailed quotes to Titley.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/10/2011
	Product Type		RF

	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 308 WIN HB
	Date Code		LO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	ACTION DIRTY RIFLE HAS A PAINTED FINISH
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/700 SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.013
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	3#
	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,BOTTOM HALF OF RINGS

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/10/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		26" 308 WIN HB

Barrel	Date Code		PV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	PAINTED FINISH
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		M/700 SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.013
Feeding Test	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Trigger		False	
	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
Non-Remington Components	Sub-Assembly	M/700 Non-Bolt Lock	
	Description		SCOPE BASE,BOTTOM HALF RINGS

26"  
L02/94  
3\*  
.013

6233

May 26, 2011

Fairborn Police Dept  
Attn: Bill Titley  
70 West Hebble Ave  
Fairborn, OH 45324

Subject: #6233

Dear Mr. Titley,

Thank you for your patience. Enclosed are the UPS ground prepaid shipping labels to cover shipment of the firearms for inspection at our factory. Please include a copy of this letter with each firearm. **The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure firearm is logged in correctly.**

I apologize for the inconvenience and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell  
Consumer Affairs Administrator  
Phone: 800-243-9700, ext 8684  
[christy.mitchell@remington.com](mailto:christy.mitchell@remington.com)

could not duplicate concern.  
T.A. per'll screw altered. Check  
over completely, replace TPA (40x)  
clean + test fire AT 1/2 normal  
cost.

Serial  
Number

C6862998

Model: 700



RE00233385

Quote

RECEIVED  
JUN 2 2011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700  
Phone 800-243-9700 • [www.remington.com](http://www.remington.com)

BY:.....

6/2/11

To whom it may concern,

This rifle (# C6862998) is owned and fielded by the Fairborn Police Department as a scope-sighted precision rifle on a regional tactical team. It has been cleaned and maintained by its assigned user after each use or approximately 20 rounds, (whichever comes first) since being put into service by this agency. Its trigger was inspected by a Remington Armorer at Gander Mountain in Huber Heights Ohio. No defects were found, no excessive debris was reported, and no adjustments were made from factory settings.

Please check the trigger in this rifle and replace it with a 40x trigger. This weapon will not be returned to service with the existing one. Additionally, since this rifle has been fielded during tactical operations in inclement weather for a number of years and had several thousand rounds fired thru it, please check the bore, headspace, and throat (for erosion). I can be contacted at the address and phone number below to authorize any repairs not covered by Remington.

Thank you for your dedication to serving those who serve, both abroad and at home.

Respectfully,

Officer Bill Titley  
Fairborn Police Department  
70 W. Hebble Ave.  
Fairborn, Ohio 45324  
(937)313-5142  
bill.titley@ci.fairborn.oh.us

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: <b>700 PSS</b>		Serial Number: <b>C6862998</b>	
Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <b>FPO</b>			
Name: <b>FAIRBORN POLICE DEPT.</b>		Date of Purchase: <b>UNK</b>	
Address (no PO Boxes): <b>70 W. HESBIE AVE</b>			
City: <b>FAIRBORN</b>		State: <b>OH</b>	Zip: <b>45324</b>
Phone (Daytime): <b>937-313 5142</b>		Fax: <b>937-754 3004</b>	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <b>BILL-THLEY @ CS.FAIRBORN.OH.US</b>			
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence:  <b>SEE ATTACHED LETTER</b>			
500 characters left			
Ammunition Information:			
Manufacturer: <b>FEDERAL</b>		Type: <b>BTMP 556000 MATCH</b>	
Other (i.e. bullet weight/type, shot size, powder): <b>165 GR.</b>			
Handload Information: <b>N/A</b>			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	

Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	SNOWBES CR-500
How often do you clean the bore? (Months or Number of rounds)	EACH USE OR 20 RDS
How often do you clean the action? (Months or Number of rounds)	EACH USE OR 20 RDS
How often do you clean the trigger assembly? (Months or Number of rounds)	N/A
Brand of lubricant used:	BREAK FREE
How often do you lubricate the bore? (Months or Number of rounds)	EACH USE OR 20 RDS
How often do you lubricate the action? (Months or Number of rounds)	EACH USE OR 20 RDS
How often do you lubricate the trigger assembly? (Months or Number of rounds)	N/A
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
10/08	
What were the services performed?	
TRIGGER INSPECTED	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
<p><b>ⓈWARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</b></p> <p>:: Record the serial number of your firearm before sending it.</p> <p>:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>:: Remove all accessories from your firearm to prevent loss or damage.</p> <p>:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.</p>	

# Quotation

## REMINGTON ARMS SERVICE

PO Box 700

Madison, NC 27025-0700

# Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

*All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.*

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

<b>Repair Number</b>	<b>Serial Number / Description</b>	<b>Date Received:</b>	06/08/2011
RE00233339	E6747974	<b>Estimate Date:</b>	06/13/2011
	Model 700 Center Fire Caliber: 308 WIN	<b>Date Printed:</b>	06/24/2011

### Customer:

FAIRBORN POLICE DEPT  
ATTN: BILL TITLEY  
70 WEST HEBBLE AVE  
FAIRBORN, OH 45324 US

### Return To:

FAIRBORN POLICE DEPT  
ATTN: BILL TITLEY  
70 WEST HEBBLE AVE  
FAIRBORN, OH 45324 US

Please Circle One:

VISA MC DISCOVER Card No. \_\_\_\_\_ Exp.Date \_\_\_\_\_  
Open Account: R \_\_\_\_\_ PO Number: \_\_\_\_\_

Approval Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Daytime Phone: (\_\_\_\_) \_\_\_\_\_ Time to Call: \_\_\_\_\_

☐ If you desire any change, please use the reverse side for your comments and mark this box.

### Problems

#### Reported

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

#### Found

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

### Technician Comments

could not duplicate concern.check over completely.replace trigger plate asm,clean and test fire at 1/2 normal cost. minor heat checking ahead of chamber,there is some corrosion pitting in bore will quote to replace bbl/rec asm

ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)

Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount
F106644	Part	700 BBL ASSB 308 POL 26"	1	Billable	1	228.00	50	114.00
F27591	Part	40-X POL TRIG ASSB RH	1	Billable	1	125.00	50	62.50
4000114	Service	GR-SHIPING & HANDLING (GUN REPAIR)	1	Billable	1	17.00	0	17.00
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50

Sub Total: 205.00  
Est Sales Tax: 10.25

Total: 215.25



## TRANSMISSION VERIFICATION REPORT

TIME : 06/24/2011 10:38  
NAME :  
FAX : 3365487823  
TEL :  
SER.# : BRO00J148005

DATE, TIME  
FAX NO./NAME  
DURATION  
PAGE(S)  
RESULT  
MODE

06/24 10:37  
19377543004  
00:01:01  
03  
OK  
STANDARD  
ECM

# Remington®

## FACSIMILE TRANSMITTAL SHEET

To: Bill Titley Date: 6/24/11  
Company: Fairborn P.D. From: Christy Mitchell  
Fax No.: 937-754-3004 Fax No.: \_\_\_\_\_  
Phone No.: \_\_\_\_\_ Phone No.: 800-243-9700 x 8684

Number of pages including Cover Sheet: \_\_\_\_\_

## COMMENTS:


P ✓ 26" 6/01  
4#  
013

6233

May 26, 2011

Fairborn Police Dept  
Attn: Bill Titley  
70 West Hebble Ave  
Fairborn, OH 45324

Subject: #6233

Dear Mr. Titley,

Thank you for your patience. Enclosed are the UPS ground prepaid shipping labels to cover shipment of the firearms for inspection at our factory. Please include a copy of this letter with each firearm. **The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure firearm is logged in correctly.**

I apologize for the inconvenience and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell  
Consumer Affairs Administrator  
Phone: 800-243-9700, ext 8684  
[christy.mitchell@remington.com](mailto:christy.mitchell@remington.com)

Serial Number:

E6747974

Model: 700



RE00233339

can't not duplicate concern  
check over completely replace  
TPA, (vol) clean test fire at  
1/2 normal cost.

RECEIVED  
JUN 22 2011

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025  
Phone 800-243-9700 • [www.remington.com](http://www.remington.com)

6/2/11

To whom it may concern,

This rifle (# E6747974) is owned and fielded by the Fairborn Police Department as a scope-sighted precision rifle on a regional tactical team. It has been cleaned and maintained by its assigned user after each use or approximately 20 rounds, (whichever comes first) since being put into service by this agency. Its trigger was inspected by a Remington Armorer at Gander Mountain in Huber Heights Ohio. No defects were found, no excessive debris was reported, and no adjustments were made from factory settings. Trigger pull was measured at 4 lbs. 14 oz.

On May 24<sup>th</sup>, 2011 at approximately 1300hrs this rifle was loaded with Federal 168 Gr. Sierra Match King BTHPs (lot # P21X655) at the Butler County Sheriff's Office outdoor range. After the bolt was closed on a live round, with the safety in "SAFE " position, (which had been set after cleaning the weapon at 1230 hrs) the trigger was pulled. When no round was fired a quick inspection revealed the safety was in the "SAFE" position. Safety was changed to "FIRE" with right index finger. The weapon immediately discharged with nothing touching the trigger. There were two witnesses to this event immediately to the right of the shooter and one standing behind the shooter.

The bolt was run and a new round chambered. The rifle was then unloaded and function checked. It was then subjected to multiple (the count stopped at 100) bolt closures with the safety on "SAFE", a trigger pull, and then safety being switched to "FIRE". There were no additional firing pin releases during this testing. The rifle was then removed from service.

Please check the trigger in this rifle and replace it with a 40x trigger. This weapon will not be returned to service with the existing one. Additionally, since this rifle has been fielded during tactical operations in inclement weather for a number of years and had several thousand rounds fired thru it, please check the bore, headspace, and throat (for erosion). I can be contacted at the address and phone number below to authorize any repairs not covered by Remington.

-----Thank you for your dedication to serving those who serve, both abroad and at home.-----

Respectfully,

Officer Bill Titley  
Fairborn Police Department  
70 W. Hebble Ave.  
Fairborn, Ohio 45324  
(937)313-5142  
[bill.titley@ci.fairborn.oh.us](mailto:bill.titley@ci.fairborn.oh.us)

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 PSS		Serial Number: E6747974	
Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO F.P.O.			
Name: FAIRBORN POLICE DEPT		Date of Purchase: ? UNK	
Address (no PO Boxes): 70 W. HEBBLE AVE.			
City: FAIRBORN		State: OH	Zip: 45324
Phone (Daytime): 937-313-5142		Fax: 937-754-3004	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) bill.eitzley@ci.fairborn.oh.us			
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence:  SEE ATTACHED LETTER			
500 characters left			
Ammunition Information:			
Manufacturer: FEDERAL		Type: B1NP SIGRO MARK	
Other (i.e. bullet weight/type, shot size, powder): 168 GR.			
Handload Information: N/A			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	

Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	SNIPERS CHOICE
How often do you clean the bore? (Months or Number of rounds)	EACH USE OR 20 RDS
How often do you clean the action? (Months or Number of rounds)	SAME
How often do you clean the trigger assembly? (Months or Number of rounds)	N/A
Brand of lubricant used:	BREAK FREE
How often do you lubricate the bore? (Months or Number of rounds)	EACH USE OR 20 RDS
How often do you lubricate the action? (Months or Number of rounds)	" "
How often do you lubricate the trigger assembly? (Months or Number of rounds)	N/A
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
10/08	
What were the services performed?	
GUNNER MIN - NUPER WEIGHTS ON. TRIGGER T-SPEEED	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357	
⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.	

Case #	6233	Date of Call	5/26/11	Date of Incident	5/24/11	PreLit		Lit		Obs	
--------	------	--------------	---------	------------------	---------	--------	--	-----	--	-----	--

Reporter		Incident	Bill Titley Fairborn PD 70 West Hebble Ave. Fairborn OH 45324 937-313-5142
name		Name/Age	
address		address	
contact #'s		contact #'s	
email		email	

Injury	Dec London, OH
--------	----------------

Medical Treatment	
-------------------	--

Alleged cause	
---------------	--

Firearm	Ser #	Cal	DOM	Orig owner?	When/Where purchased			
700	F							

Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot #	Additional info

Other Product	
---------------	--

Notes:	<p>2 days ago, safety on-pulled trigger took safety off</p> <p>Ed O'halley</p> <p>5 has "Walker" trigger 99, 2009</p>
--------	---

Customer's Request	
--------------------	--

My actions/offers	<p>Sending 2 AR5 labels for the 2 owned by Fairborn PD. The other depts can take care of the other 3.</p>
-------------------	---



www.remington.com

Remington Arms Company, Inc.  
870 Remington Drive  
P. O. Box 700  
Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	5/26/2011	REQUESTED BY:	christy
QUANTITY:	2	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE:			
MEDIA COORDINATOR TO MAIL		I WILL MAIL	
		xxx	
DESCRIPTION: 2 x 700 rifles			

## LABEL INFORMATION

MAIL LABEL TO:	Fairborn Police Dept Attn: Bill Titley 70 West Hebble Ave Fairborn, OH 45324 937-313-5142
RETURN ITEM TO:	Rem Prod Serv Case # 6233

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 MAY 26, 2011 ALL CURR USD 1 OF 2  
SVC GND COM ACT WT 10.0 LBS  
TRACKING# 1Z4XX5969066019502  
REF 1:FIRBORN POLICE DEPT/SWP/CHRISTY  
REF 2:700 RIFLE

HANDLING CHARGE 0.00		SVC T/P USD	
SINGLE-PIECE PUB RATE CHRG:			
DV 0.00	COD 0.00	RS 0.50	
DC 0.00	DGD 0.00	SD 0.00	
AH 0.00	PR 0.00	SP 0.00	
TOT PUB CHG 9.04		PUB+HANDLING 9.04	

4XX596 MAY 26, 2011 ALL CURR USD 2 OF 2  
SVC GND COM ACT WT 10.0 LBS  
TRACKING# 1Z4XX5969067773310  
REF 1:FIRBORN POLICE DEPT/SWP/CHRISTY  
REF 2:700 RIFLE

HANDLING CHARGE 0.00		SVC T/P USD	
SINGLE-PIECE PUB RATE CHRG:			
DV 0.00	COD 0.00	RS 0.50	
DC 0.00	DGD 0.00	SD 0.00	
AH 0.00	PR 0.00	SP 0.00	
TOT PUB CHG 9.04		PUB+HANDLING 9.04	