

Remington Arms Co., Inc.
Product Service
Legal Case #:6164

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
230242	5/2/2011	5/3/2011	5/3/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ben	Worst	PO Box 5224 711 Second Ave North	Ketchum	ID	83340		H 208-720-8417 E benworst@cox.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Accidental discharge years ago but may be user error	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

5/12/11 Per note with rifle, the gun has performed well over the years however it did accidentally discharge many years ago however he cannot say that it was not due to user error. There have been no accidental discharges since.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6657288	OX	7/1/1973
Date Purchased	Where Purchased	Accessories	Original Owner			
	BASCHE & SAGE BAKER OREGON	SCOPE BASE	U			

CONCERN:ACCIDENTAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	5/12/2011				

5/12/11 Per Ilion, could not duplicate concern. Trigger assm very dirty. Replace TPA, clean, test fire at BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/3/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	IMPROPER MAINTENENCE
Barrel	Description		22" 3006 SPRG
	Date Code		OX
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	ACTION VERY DIRTY
	Stock Condition	Worn; Functioning	MANY SCRATCHES,MARS,DENTS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.005
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

22"
OK 7/73
4.5#
1005

6164

BEN WORST
P.O. BOX 5224
711 SECOND AVENUE NORTH
KETCHUM, IDAHO 83340

Tel.: (208) 720-8417
Email: benworst@cox.net

REMINGTON ARMS CO., INC.
14 HOEFLER AVENUE
ILION, NEW YORK 13357

ATTN: ARMS SERVICES
SAFETY MODIFICATION PROGRAM

To Whom It May Concern:

I enclose two model 700 Remington rifles, .270 serial no. B6364910 and 30.06 serial no. 6657288. I would like you to perform the following work:

- Replace both the triggers and safeties on both guns. I would like the triggers to be set as low as you recommend for hunting above 3 pounds but ideally below 5 pounds.
- Put cap screws where the iron sites on the .270 have been removed.
- Remove the iron sites on the 30.06, put in cap screws and return the iron sites to me.

Both guns have performed well over the years. The 30.06 accidentally discharged many years ago; however, I cannot say that it was not due to user error. There have been no accidental discharges since.

The trigger on the .270 was adjusted ten years ago by a gunsmith claiming to be a licensed Remington gunsmith; however, his work on a shotgun convinced me that he did not know what he was doing and I do not have confidence in his work.

Please call me with an estimate before you perform the work. (208)720-8417.

Thank you.

[Handwritten Signature]
Ben Worst

could not duplicate concern
T.A. very dirty. replace TPA,
clean + test fire under BLP
for \$ 20.00 + ship.

Quote

Serial Number:

6657288

Model: 700



RE00230242

RECEIVED
MAY 06 2011

BY:.....

20.80
27.00
20.00
67.40
- 37.00
30.40









