Remington Arms Co., Inc. Product Service Legal Case #:6076

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 227602 4/1/2011 4/4/2011 4/4/2011

Customer Information

Last Name Street City State Contact Type Business First Name Zip Age Incident Sylvester Ferrucci 426 Overlook Dr Hillsville 16132 H 724-730-4039

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

ΡI

PD Cause:4015 Improper Maintenance

Concern: 1025 Safety Position

Unknown

Unknown

S recall for unwanted discharge of Concern: 1025 Unexplained Di weapon

С

4/11/11 Per note with rifle, "recall for unwanted discharge of weapon."cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 710/3006 SPRG
 27410
 71073143
 WW 8/8/2002 6:45:13 AM

Date Purchased Where Purchased Accessories Original Owner

WAL-MART DC 6003R-REGULAR SCOPE BASE U

CONCERN: RECALL FOR UNWANTED DISCHARGE

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date APV APV

Replace detent spring no charge

Repair/Replacement Cost Repair/Replacement Date

7.54

4/4/11: Customer called. He only wants the safety detent spring replaced due to recall & the rifle shipped back to him. We haven't received the paperwork from PS in Ilion yet. I emailed Ilion to see if that repair could be done because there is a quote for a new M/770. df 4/11/11 Per Ilion, trigger assm and action rusted and action full of foreign debris. Old style TPA no longer avail. Replacing detent spring only at no charge per request of owner.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		4/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
	4015	Improper Maintenance	COULD NOT DUPLICATE CONCERN. O/S TPA NO LONGER AVAILABLE. UNABLE TO REPAIR, REPLACE ONLY.
	Description		22" 3006 SPRG
	Date Code		WW
	Bore Plugged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6076&Type=Case

4/11/2011

]	Bulged	False	1
Barrel	Fired	False	
	Fired while]	1
	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	RUSTED
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
L	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Missing	
Overall	Exterior Condition	Worn; Functioning	ACTION RUSTED AND FULL OF FORIEGN DEBRIS
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/710 SAFETY (RUSTED)
	Function	Slightly Worn; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Worn; Functioning	RUSTED
	Puli	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	¬



Remington.

Factory Repair Instructions (NOTE: Please print and complete this form, and then include it with your firearm.)				
Model Number: 7/0	Serial Number: 7/0 7.3 / 43			
Are you the original owner?: YES INO	·			
Name: Sylvester & Perrucci	Date of Purchase:			
Address (na PO Boxes):				
426 overlook Drive				
City: 1/1/1/5/1/11/	State: PA Zip: /6/37			
Phone (Daytime): 724 667 1610	Fax:			
E-mail Address: EMT 822@ Yahoo, Wall would like to receive future e-mail updates from F	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Please describe your problem: Remingtor	recall for unwanted			
discharge of weapon	as a state of			
Ammunition Information:				
Manufacturer: Reminston	Type: 180 gr core locked			
Other (i.e. bullet weight/type, shot size, powder):	Mark Mark Mark Mark Mark Mark Mark Mark			
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				
Brand of cleaning solution used: Virginia				
How often do you clean the bore? (Months or Number of	rounds) after use			
How often do you clean the action? (Months or Number	of rounds) after use			
How often do you clean the trigger assembly? (Months of				
	and the same of th			
Brand of lubricant used: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	MEQUES VI			
	APR 0 7 2011			
	77 Will ~ 1 FOIL			

4.54 MWK/02

BY:----

How often do you lubricate the bore? (Months or Number of rounds) How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?

What were the services performed?

Ship your INSURED firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357



N YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE AME, ADDRESS (WITH ZIP CODE), TELEPHONE AND

image in shipping and handling. Preferably, e returned.) oss or damage.

le the box. Shipments without a proper

ost. Remington is not responsible for purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

> T.A. + Action Rusted + Action full of forzeign de bizis. O/s TPA No longer AUDIL. Quote to replace in Exchange At 1/2 Nonana (cost.

SYlvester S. Ferrucci
426 OVER/OOK Drive
Hillsville PA-16132
724 730-4039

148 1,06 27-27.54









