1

Remington Arms Co., Inc. Product Service Legal Case #:6212

Case Information

					-	-	. .	
	Date Opene		Opened(PS)		Incident	Date	Pre L	it Lit Obsolete
231725	5/17/2011	5/	18/2011	5/18/2011				Х
Type	Information Business	First Name	Last Name	Street	City	State	Zip	Age Contact
Incident		Bernard	Soyring	44260 Posteri Beach Ln	^{ty} Waubun	MN :	56585	H 218-734- 2285
Reporter	Reed's Sptg Goods		Reed's Sptg Goo	522 Minneso Ave	ta Walker	MN :	56484	W 800-346- 0019
Incident I	nformation							
Cla	aims		Codes		Repair Est.		dical tment	Medical Status
s _{closir} C	on bolt 1g (Concern	ot Duplicate Bolt Closing s being closed.	cm	Unk	nown	
<u> </u>	nformation							
Mfg.		Гуре	Мо	del/Ga.	SKU	Seria	l Bb	ol. DOM
Remingt		F/BA	710/3	006 SPRG	27410	711375	97 D	9/22/2003
Date Purchas	ed Where Purchased		d Acc	Accessories				[^] 2:23:50 AM
CONCER	6003R-	MART DO REGULA		UNGS,BASE	U			
Other Pro	ion Informati ducts Informa							
Settlemen	L			ngton/710/CF/F	BA			
Settlemen	ll.		Remi	igion//iv/ci/i				
Settlemen Settleme		e of Clain		-	Reimbursen	ient Se	Cash ttlem	LIATA LIATA
	ent Releas	e of Clain		-		^{ient} Se		Date Date

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6212&Type=Case 6/1/2011

remove TPA, clean, test at 1/2 normal cost

Repair/Replacement Repair/Replacement Cost Date

5/31/11 Per Ilion, could not duplicate concern. Trigger assm dirty. Can offer to remove TPA, clean, test at 1/2 normal cost

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date]	5/18/2011
Examination	Product Type]	RF
	Action Type]	Α
	Assigned To]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	NEW TPA NO LONGER AVAILABLE
	Description		22" 3006 SPRG
	Date Code]	DX
	Bore Plugged	False	
Barrel	Bulged	False	
Darter	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6212&Type=Case

6/1/2011

,

1

	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	METAL DIRTY,LITE RUSTING
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/710 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
, <u>, , , , , , , , , , , , , , , ,</u>	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	5#
	Altered	False	
	Sub-Assembly	Other Remington	

Trade	- RETURN - DEFEC		ZIZ CONSIGNMENT KREP	AIR DATE: 12/15/10
MAKE & MODEL: CALIBER: <u>30</u> ACTION: <u>60</u> BARREL: SERIAL #: <u>71/3</u> COST: RETAIL: CALES DUTION S	NEW DUSED LIKE NEW 7597_LOG: FI	W RED NFIRED	B) WARRANTY WORK 1. GUN OWNED BY	CUSTOMER OR REEDS RECEIVED: (circle one) CREDIT REPAIR Y GUNSMITH (N/C):
711375 Model: 710	VE/PROBLEM THE BOLT G CLOSED, I CHTE CONCERN. I CHTE		to these terms the customer must not leave d 1. Once a firearm enters Reeds, it is regulate a FBI background check must be performed original owner, the consignee, In the case of including the owner, must possess a valid ha 2. Use of a firearm is a dangerous activity an of any such use. Consignees, those trading-i- sending in firearms for warranty work agree from any claims, damages, costs or attorneys display and sale of the firearm. 3. Consignments and Trade-Ins. Those consi and warrant the firearm is in good, safe work working order will be returned to the owner of the sale of the firearm to another customer. (harmless Reeds from any claims, damages, c	ity work at Reeds, if a customer does not agree he firearm at Reeds: d the ATF and other governmental laws. Thus, even upon the return of the firearm to its a handgun or AR frame, the recipient, ndgun permit. d any possessor or purchaser assumes the risk in firearms, using gunsmithing services or to indemnify, defend and hold harmless Reeds ' fees incurred relating to the possession, gning or trading-in firearms at Reeds represent ing order. Firearms found to not be in proper or repaired at the owner's expense even after Customer agrees to indemnify, defend and hold osts or attomeys' fees incurred relating to the earm. Customer agrees to hold Reeds harmless lost or otherwise reduced in value while at and sale of a firearm. Display and payment is reasonable from time to time. cing fee will be charged on all firearms at erally-mandated data records. All warranty with the manufacturer. be covered under warranty. If a customer's work, the customer agrees as follows: 1) The s. 2) Only the factory can authorize warranty vise of the likelihood of coverage. es and repairs are only arranged by Reeds th. Reeds facilitates gunsmithing should be smith (Walker, John Ahrends: 218-751-3761; will make every effort to have your firearm eption of warranty work, repair expenses and
NAME: BERNY	1		FORMATION	
NAME: DERNY ADDRESS: <u>4426</u>		-	MER'S STATEMENT OF VE	
		will abide	by the disclaimers in this doc	ument.
CITY:	BUN	SIGNAT	JRE: X	
STATE & ZIP:	56589	SIGNATU		
PHONE: 218 -	734-2285	_ CREDIT (CARD:	DECEIVED
ID:			CARD EXPIRATION DATE:	
EMAIL:		C	REDIT CARD CVV CODE:	ВҮ:
Page 1 - to File		Page 2 - Attach to		Page 3 - to Customer

Print | Close

Subject:	Warranty Return Authorizations
From:	Wayne Schmeling [wayneschmeling@reedssports.com]
То:	peter.verant@remington.com

Date: Mon, 9 May 2011 09:19:11 -0500

Hello Peter,

We currently have three rifles belonging to customers in need of warranty repair, and I could use your assistance in securing following:

- Call Tags
- Return Authorizations

- Shipping Address The rifles include:

231545

- Marlin 308MXLR, (S/N: 91808643) where the receiver and barrel seem to be out of alignment not only on the boresighter, but also to the naked eye. The rifle is impossible to boresight and equally impossible to sight in at the range by the customer. - Remington 710, (S/N: 71137597) where the rifle fires upon closing the bolt. 23/725 - Remington 700 XHR, (S/N: G6847967) where there is a reamer issue with rippling cartridge casings.

231575

Thanks for your help!

Wayne Schmeling Hunting/Firearms Sales Reeds Family Outdoor Outfitters 522 Minnesota Ave NW Walker, MN 56484 Ph: **800-346-0019** Fax: 888-400-1340 email: wayneschmeling@reedssports.com

Need Repair Gun form W/ problem déscription

١

Ship To: BERNARD SOYRING REMINGTON 14 HOEFFLER AVE ILION, NY 13357 Reed's Sporting Goods #1 522 Minnesota Avenue NW Walker, MN 56484 1-800-346-0019

Bill To: BERNARD SOYRING REMINGTON 44260 POSTERITY BEACH LN WAUBUN, MN 56589

Mail #:	Bill To: 218-734-2285 Ship To:					5/12/20	5/12/2011 4:55:57 PM	
Fold Here AR Acct #:	669	PO #:		Order #: 14402	23		Page 1	
Ship Date 5/12/2011	FOB	Ship Via	Terms NO CHARGE	Packages 1	Weight 0	(Clerk # 143	
Item #	Description 1		Style	Order Qty	Ship Qty	Price	Net Sale	
101	USED RIFLE		Log # 1027926	1 Serial # 711	1 37597	0.00	0.00	

Total 1	Units: 1	Subtotal Sales Tax	0.00 0.00
		Total Charge	0.00







