Remington Arms Co., Inc. Product Service Legal Case #:6769

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 10/31/2011 12/5/2011 248348 11/29/2011

Customer Information

Street Contact Type **Business First Name** Last Name City Zip Age 1449 Evangeline Rd Babb Glenmora 71433 H 318-748-6368 Incident Alan

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

PI

PD shot hole in tire and rim Cause: 4015 Improper Maintenance of buggy

Concern:1005 Unexplained Discharge Safe Unknown

S Fired with safety on

10/31/11 Per call from Babb, he was unloading his gun, reached down to pick it up and it discharged. He checked and the safety was on. He shot a hole in he bottom of his "buggy", the tire and rim. He traded for this rifle in 1990.cm

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/270 WIN

SKU 25791 Serial Bbl. DOM

Date Purchased

Accessories

Original Owner

C6575205 OK 7/26/1990

Where Purchased

AMERICAN ROD & GUN

Y

CONCERN:FSO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Release of Claims Settlement

Release Date

Reimbursement

Cash Settlement Reim. Date APV

Cash Date APV

Return as received

> Repair/Replacement Cost

Repair/Replacement Date

10/31/11 Mailing ARS, ltr, SR and box.cm 12/5/11 Per Ilion, trigger assm very dirty and sticky, parts bind and work sluggish. Replace TPA, clean and test fire at 1/2 normal cost.cm 12/15/11 Babb has a local gunsmith that he will have work on it. Return as received. I will send an owner's manual as he bought it from an individual and did not get one.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		11/30/2011	
	Product Type		RF	
	Action Type		A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6769&Type=Case

12/15/2011

	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		OK
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Not Functioning	ACTION VERY DIRTY MARS, SCRATCHES
Overall	Stock Condition	Worn; Functioning	SCRATCHES,MARS,DENTS
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.013
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY,STICKY.PARTS BIND WORK SLUGGISH
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

22" 016 7/9 4.5th

6769

October 31, 2011



Alan Babb 1449 Evangeline Rd Glenmore, LA 71433

Subject: Case # 6769, Model 700, SR# 2455

Dear Mr. Babb,

Please include a copy of this letter with each rifle as well as the Service Request form with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the boxes with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

環C6575205 Model: 700

RE00248348

T.A. very dirty + Sticky, parts == BIND + WORK sluggesh, Rephase TOA, CLEAN + TEST fire At /2 Normal COST.

DEC 0 2 2011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

10/31/2011

10/31/2011

Madison, NC 27025-0700

ATTN: Product Service #6769

Date of Request:

Printed:

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number Serial Number / Description

SR00002455

C6575205

Customer: ALAN BABB

1449 EVANGELINE RD GLEMORA, LA 71433 US

Model 700 RIFLE Caliber; 270

Email:

Arms Services

14 Hoefler Ave

Ilion, NY 13357 US

Destination:

Email: give to Christy

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Discharged with safety on when picking up.

Parts And Service Details

Material

Type

Description

Qty Needed

Warranty

Price

٤,

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00 .00

ARS LABEL REQUEST FORM

10/31/2011	Service Request #	SR00002455
I	WEIGHT PER PACKAGE:	10 LBS
mitchelles	email address:	Christy.Mitchell@remington.com
	Ī	1 WEIGHT PER PACKAGE:

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

ALAN BABB 1449 EVANGELINE RD GLEMORA, LA 71433 US SR00002455

Email: give to Christy

RETURN ITEM TO:

ILN

Arms Services



4XX596 OCT 31, 2011 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS 1 OF 1

REF 1:SR00002455 REF 2:

HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS:

DV 0.00 DC 0.00 SVC T/P USD RS 0.50 0.00 COD DGD AH 0.00 SD 0.00 PR 0.00 TOT PUB CHG 10.27 SP 0.00 PUB+HANDLING 10.27

ATTN: Product Service #6769









