

Remington Arms Co., Inc.
 Product Service
 Legal Case #:6848

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		11/15/2011		11/12/2011			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jeff	Bouse	410 Vine St	Cuba	MO	65453		H 573-259-4830

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	shot hole in car door	Cause:4079 Other - Unexamined		Unknown
S		Concern:1008 Fired on Bolt Closing		
C				

11/15/11 Per call from Bouse, his wife was loading the gun and closed the bolt and it fired and shot a hole in the car door. No injuries. He has 2 .270 700's and 1 710 that he wanted the serial numbers checked for recall. I checked all and see no recalls.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	25771	B6806104		7/29/1986
Date Purchased	Where Purchased	Accessories	Original Owner			
	PEELER HDWE CO		Y			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

11/15/11 Mailing box, ARS, ltr, SR.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

ARS LABEL REQUEST FORM

DATE: 11/15/2011	Service Request #	SR00003835
QUANTITY: 1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY: mitchelcs	email address:	Christy.Mitchell@remington.com

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	JEFF BOUSE 410 VINE ST CUBA, MO 65453 US SR00003835 Email: give to Christy
RETURN ITEM TO:	ILN Arms Services



1 OF 1

4XXS96 NOV 15, 2011 ALL CURR USD
 SVC GNDCOM ACT WT 10.0 LBS
 TRACKING# 1Z4XX5969065138180
 REF 1:SR00003835
 REF 2:

HANDLING CHARGE 0.00		SVC T/P USD
SINGLE-PIECE PUB RATE	CHRG:	RS 0.50
DV 0.00	COD 0.00	SD 0.00
DC 0.00	DGD 0.00	SP 0.00
AH 0.00	PR 0.00	PUB+HANDLING 9.61
TOT PUB CHG 9.61		

ATTN: Product Service # 6848
