

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6774

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
245105	10/31/2011	11/1/2011	1/11/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Muri	Clymer	15800 Washington St	Broomfield	CO	80023		H 303-941-5351

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fired when closing bolt Concern:1008 Fired on Bolt Closing			
C				

11/16/11 Per note with rifle, this rifle has had several owners but after he purchased it he took it to the range, fired it 3 times and on the 4th round it went off as he was closing the bolt.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	A6541040	XO	12/15/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	WHITNEY SPTG DENVER CO	TWO PIECE BASE	N			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.40	11/16/2011				

11/16/11 Per Ilion, trigger assm set screws altered. Replace TPA, clean and test fire at BLSM program price at \$20 + shipping.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/11/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 22-250 REM
	Date Code		XO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN
	Pull	---Select---	1.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Please send me a recommended ~~Er~~  
Lube & Barrel Cleaning Directions (no computer)

# Remington.

6774

## Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: A6541040
Are you the original owner? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Name: Murl Clymer	Date of Purchase: (New?) 9/1/11
Address (no PO Boxes): 15800 Washington St	
City: Broomfield	State: Colorado Zip: 80023 80023
Phone (Daytime): 303945351	Fax: none
E-mail Address: none	
<input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.	
Please describe your problem: I Purchased this Rifle from a friend who purchased from another So can't really tell you much about following questions. I took this firearm to the Range soon after I bought it & fired it 3 times on the forth Round it went off as I was chasing the bolt & scared the hell out of me. Please repair trigger	
Ammunition Information:	
Manufacturer: Remington	Type: 700 22-250
Other (i.e. bullet weight/type, shot size, powder): 50 grain	
Handload Information:	
Powder Used: Factor	Powder Weight: 50 grain
Case/Hull Used: load	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: Gun slick solvent	
How often do you clean the bore? (Months or Number of rounds) 50 To 100 Rounds	
How often do you clean the action? (Months or Number of rounds) every time I use it	
How often do you clean the trigger assembly? (Months or Number of rounds) Very seldom	
Brand of lubricant used: Rem Oil aerosol	

RECEIVED  
NOV - 8 2011

Above is the way I treat all my Firearms

24"  
X012/  
1.5#  
.008

How often do you lubricate the bore? (Months or Number of rounds)	50 To 100 Rounds
How often, do you lubricate the action? (Months or Number of rounds)	Every time used
How often do you lubricate the trigger assembly? (Months or Number of rounds)	When I Lub the action
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	please enclose with firearm
Comments: thank you for your attention	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? ?	
What were the services performed? ?	

no computer

THINGS TO DO TODAY

1. 700 Rem 22-250	Said Customer service a trigger was about \$37.00 It cost much more please Call me. 3039415351 also find my Credit Card # below (Destroy after use)
2. # A6541040	
3.	VISA # REDACTED
4. Phone #	
5.	Return to MURL CLYMER 15800 Washington St Bloomfield Co 80023
6.	
7.	Exp 01/13
8.	
9.	11/13
10.	
11.	1/13
12.	
13.	2
14.	
15.	2
16.	
17.	2
18.	
19.	2
20.	
21.	2
22.	
23.	2
24.	
25.	2
26.	
27.	2
28.	
29.	2
30.	

Serial Number: A6541040  
Model: 700



RE00245105

Post, Remington is not responsible for purchase insurance from your carrier.

delines:

med to you C.O.D. (To avoid C.O.D. Charges, please h. your gun)

time detailing the nature of the repair, applicable taxes ur estimate. Repairs can be paid by check, money order, or VISA). If you wish, you can expedite repairs over billed to your credit card.

T.A. set screws altered.  
Replac TPH, clean & Test  
fire under BLP for \$20.00  
+ ship

(Go ahead w/repair)















