Remington Arms Co., Inc. Product Service Legal Case #:6984

Case Information

RE# **Date Opened** Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete 250942 12/16/2011 12/5/2011 12/19/2011 12/3/2011 Customer Information

Zip Contact Business First Name Last Name Street City State Type Age C 334-685-7051 175 Hamrick Ave Incident Jacob Cotton Ozark AL 36360 E crwiring.jc@gmail.com

Incident Information

Medical Treatment Medical Status Claims Codes Repair Est.

PI recoil tore thumb nail

PD Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release S

N

C FSR

12/5/11: Customer called in. He stated that he had a FSR w/rifle on 12/3/11. He stated the unexpected recoil tore his thumb nail but he did not seek any medical treatmenet. He stated he does not feel safe w/the rifle. He said that he bought the gun used & had it checked & was told the gun was clean & had not been adjusted. df

Firearm Information

DOM Model/Ga. SKU Bhl. Mfg. Type Serial Remington CF/BA 700/3006 SPRG n/a B6388923 EC 10/1/1982 Where Purchased **Original Owner Date Purchased** Accessories

VF GRACE INC ANCHORAGE AK TWO PIECE BASE N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement APV APV Settlement

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

12/5/11: Mailing ARS & forms. Box order# 1280774. df 12/20/11: Per Ilion - Could not duplicate concern. TA dirty & rusty. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. Customer apprvd & pd quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/19/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		EC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6984&Type=Case

1/12/2012

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	16313	False	
	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
Trigger	Pull	Select	3.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

December

³B6388923

Jacob Cotton 175 Hamrick Ave Ozark, AL 36360 Phone: 334-685-7051

Ref: #6984, Model 700, Serial #B6388923



Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure

model 200 30.06 senal # B6388923 could not duplicable concern call for credit card #. Did not want to ship by package to suphratory, CANOPhen to suphratory, CLEANT TUST PINE At 1/2 NORMAL (EOST. À DEC 2 0 2011 Quote

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number Serial Number / Description 12/05/2011 Date of Request: SR00005793 B6388923 Date 12/05/2011 Printed: Model 700 Center Fire Caliber: 3006 Customer: Destination: JACOB COTTON Arms Services 175 HAMRICK AVE 14 Hoefler Ave OZARK, AL 36360 US Ilion, NY 13357 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Product Service # 6984 - FSR

Parts And Service Details

Material

Type

Description

Oty Needed Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

Print	Reset
-------	-------

Number: 700	Serial Number: BLZ84923			
Are you the original owner?: ☐ YES ♣NO				
Name: Jacob Citton	Date of Purchase:			
Address (no PO Boxes): 175 Humrick Ave				
City: Ozurle		Zip: 36360		
Phone (Daytime): (334) 685-705 1	Fax: NA			
E-mail Address:(if e-mail address is provid	ed, notification of rece	ipt and shipment will		
be sent) Clairing JCQC				
E-mail Address: ☐ I would like to receive future e-mail updates from Remington.				
Please describe your problem and date of occurrence:				
Gun fired when safety was pushed to				
off ms. Lon.				
hould like geen cleaned and any repairs needed made. Call with amount and my cord number will be given to you! Thank you.				
500 cha	racters left			
	r			
Manufacturer: Win.				
Other (i.e. bullet weight/type, shot size, powder): /১০ gc.				
Handload Information:				
Powder Used:	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size:	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution used:		
How often do you clean the bore? (Months or Number of rounds)		
How often do you clean the action? (Months or Number of rounds) 3		
How often do you clean the trigger assembly? (Months or Number of rounds) NA TO Like Like Like Like Like Like Like Like		
Brand of lubricant used: Hoppe's Clife		
How often do you lubricate the bore? (Months or Number of rounds)		
How often do you lubricate the action? (Months or Number of rounds)		
How often do you lubricate the trigger assembly? (Months or Number of rounds)		
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? ➤ YES □ NO		
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)		
What were the services performed?)		
Ship your INSURED firearm by either UPS or Parcel Post to:		
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357		
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.		
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper		

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post, Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

DATE:	12/05/2011	Service Request #	SR00005793
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

JACOB COTTON 175 HAMRICK AVE OZARK, AL 36360 US SR00005793

Email:

RETURN ITEM TO:

ILN

Arms Services



DEC 6, 2011 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 4XX596 TRACKING# 124XX5969065118193
REF 1:SR00005793
REF 2: SVC GNDCOM

HANDLING CHARGE 0.00

SVC T/P USD RS 0.50 SD 0.00 SINGLE-PIECE PUB RATE CHRGS: COD 0.00 DGD 0.00 PR 0.00 DV 0.00 DC 0.00 SP 0.00

PUB+HANDLING

9.61

AH 0.00 TOT PUB CHG 9.61

ATTN: Product Service





