

Remington Arms Co., Inc.
Product Service
Legal Case #:6488

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
238655	8/22/2011	8/23/2011	8/23/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Richard	Cox	3327 Rising Rawn Trail	Suwanee	GA	30024		H 678-358-8392

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Fired while applying the safety	Concern:1007 Fired on Safe Release		Unknown
C				

8/26/11 Per note with rifle, this gun was given to me by my father (original owner). It has gone off on him twice while applying the safety on the gun. He would like to get the bolt modification that is in place for this model.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A3201522	LA	2/26/1980
Date Purchased	Where Purchased	Accessories	Original Owner			
	OSHMAN SPTG HOUSTON TX		N			

CONCRN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire under BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
42.40	8/26/2011

8/26/11 Per Ilion, trigger assm has a partially dried lube residue causing parts to work sluggish. Replace TPA, clean and test fire under BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/23/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		LA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DRIED LUBE RESIDUE WILL FOLLOW DOWN
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

6488

22"
LAZ/80
S.S.#
1007

Model Number: 700		Serial Number: A3201522	
Name: Richard Cox		Date of Purchase: 1980 early 1980	
Address (no PO Boxes): 3327 Rising Fawn Trail			
City: Suwanee	State: GA	Zip: 30024	
Phone (Daytime): 678-358-8392		Fax:	
E-mail Address: richcox@gmail.com richard.cox@anthem.com			
<p>Please describe your problem:</p> <p>This gun was given to me by my father (original) owner. It has gone off on him twice while applying the safety on the gun. I would like to get the bolt modification that is in place for this model.</p> <p>: please repair under the safety Modification program</p> <p>Original owner: Johnny V. Cox (father)</p> <p>T.A. HAS A PARTIALLY DRIED LUBE USING EXHAUSTING PARTS TO WORK SLUGGISH. REPLACE TAP, CLEAN + TEST FIRE UNDER DLP FOR \$20.00 + ship</p>			

298 characters left

, contact the Repair Center for services
estimated repair time.

A3201522

Model: 700



RE00238655

IVE OR SPENT SHELLS IN YOUR
X WITH THE FIREARM. THIS IS A
YOU FEEL YOU MUST SEND SPENT
SEPARATE PACKAGE AND INCLUDE
DE), TELEPHONE AND MODEL AND
OF YOUR FIREARM.

- Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
 - :: Remove all accessories from your firearm to prevent loss or damage.
 - :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset

RECEIVED
AUG 26 2011

BY:.....





