

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6979

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
249005	12/2/2011	12/5/2011	12/5/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Advanced Metal Construction, LLC	Keith	Crow	1432 Linwood Dr	Opelousas	LA	70570		W 337-407-0936

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired when taking safety off	Concern:1007 Fired on Safe Release		
C				

12/20/11 Per note with rifle, the rifle was firing when taken off safety.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	25791	B6734501	WF	8/1/1985
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART STORE 0543 70570		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	47.40	12/20/2011				

12/20/11 Per Ilion, trigger assm very dirty. Safety works hard when taken off. Replace TPA, clean, test fire at no charge.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/5/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		WF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Not Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY,HARD OFF SAFETY DID FOLLOW DOWN
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

**Advanced Metal Construction, LLC.**

1432 Linwood Drive, Opelousas, La. 70570

Phone (337) 407-0936

Fax (337) 407-9800

6979

2211  
WFG  
5.5  
.012

Remington Arms  
ATTN: Arms Services  
14 Hoesler Ave  
Illion, NY 13357

The 700 BDL serial # B 673501 was firing when taken off safety. Please repair and check the weapon for any other problems that might arise in the future.

Best Regards

Keith Crow

Serial  
Number:

**B6734501**

Model: **700**



**RE00249005**

RECEIVED  
DEC 06 2011

BY:.....

T. A. very dirty. safety works  
HARD when taken off. Replace  
TPA, clean test fire A + N/C

#230145









