

Remington Arms Co., Inc.
Product Service
Legal Case #:6980

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
249001	12/2/2011	12/5/2011	12/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Hart's Trading Post		Hart's Trading	555 Middleline Rd	Ballston Spa	NY	12020		W 518-885-4867

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
--------	-------	-------------	-------------------	----------------

PI

PD

S

C

Cause:4015 Improper Maintenance

Concern:1008 Fired on Bolt Closing

Unknown

12/20/11 Per note with rifle, it has worked good until this year. The gun fires sometimes while the bolt is being closed whether the safety is on or off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	25818	G6304874	AX	3/19/2003 12:39:04 PM

Date Purchased	Where Purchased	Accessories	Original Owner
	JERRY S SPORT CENTER NORT	TWO PIECE BASE	U

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, offer to replace TPA, clean, test fire at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date
-------------------------	-------------------------

12/20/11 Per Ilion, trigger assm dirty. Trigger binds, not returning properly. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/5/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 308 WIN
	Date Code		AX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

"YOUR EASTERN CONNECTION TO THE OLD WEST"



6980

2211
AK3/6
6#
1011

518-885-GUNS 148671

HART'S TRADING POST, LTD
555 MIDDLELINE ROAD
BALLSTON SPA, NEW YORK 12020

FFL#6-14-091-01-2E-09930

Remington Fire Arms
Arms Services
14 Hoefler Ave.
Ilon, N.Y. 13357

Hart's Trading Post, LTD.
555 Middleline Road
Ballston Spa, New York 12020
PH.# 518-885-4867

Dec.1, 2009

Dear Sirs:

Enclosed please find a model 700 LH Rifle serial #G 6304874 . We sold this rifle on December of 2003. It has worked good until this year, when it developed that dreaded safety problem. The gun fires sometimes while the bolt is being closed weather the safety is on or off for no apparent reason. Please test fire and check the feed and extraction before returning. Thank you for your attention to this matter.

Sincerely,

William S. Hart

William S. Hart

RECEIVED
DEC 06 2011

BY:.....

T.A. Dirty. Trap birds, not returning properly. CAN offer to replace T&A, clean + test fire AT 1/2 normal cost.

Quote

Serial Number:

G6304874

Model: **700**



RE00249001







