

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6622

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
241832	9/27/2011	9/28/2011	9/28/2011				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Houchins	1284 Pulaski-Giles Turnpike	Pearisburg	VA	24134		H 540-921-3184 W 540-639-7831* C 540-239-4429 E houseman4_958@msn.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Customer sent gun in w/note. He stated that his father gave the gun to him. The father had gotten it from a gunsmith who had custom work done to it. Customer said while cleaning it - the gun will discharge when the safety is moved from safe to fire. No damage, No injury. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/2506 REM	n/a	A6284442	CI	4/12/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	OUTDOOR SPTS DAYTON OH	TWO PIECE BASE,RINGS	N			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30.40	10/12/2011				

10/12/11: Per Ilion - TA set screws altered. Trigger works sluggish & not returning properly. Replace TA, clean & test fire under BLM - quote. Left msg for cust to call about quote. Factory returned the \$10 cash he sent in. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/28/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
	Description		22" 2506 REM
	Date Code		CI
	Bore Plugged	False	
	Bulged	False	

Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	HAS BEEN TURNED DOWN, MADE LIGHTER
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG WORKS SLUGGISH NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	6#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,RINGS

6622

22"  
CI 4/71  
6#  
009

Date: 9/22/2011

Subject: Rifle Safety Modification Program

Attention: Remington Arms Co., Inc. / Arms Services

To whom it may concern,

My Dad recently gifted me with a fine Remington Model 700 chambered in the 25-06 caliber. It was sad because he can no longer hunt with it due to his age and health. However, I have come to find out while cleaning the gun it has a VERY SERIOUS problem- the gun will discharge when the safety selector lever is moved from the "Safe" to the "Fire" position, and occasionally when the bolt is operated. Dad has told me the gun belonged to a local gunsmith and the stock has had some custom work done on it. As for the action or trigger, I cannot say it has been "worked", nor can he, because it was purchased from the gunsmith's widow after his death and no technical information was available from her. In any event the gun is unsafe to use in its current state. The rifle was manufactured in 1976 based on the Serial Number # A6284442.

I have called and talked with other Remington Customer support folks and the gentleman at the Madison North Carolina facility gave me this address and said you folks could take care of this under the "Rifle Safety Modification Program" and make the necessary repairs at no cost other than a 20 dollar fee. So I am including a check for that amount along with all the pertinent contact information.

The return address is:

Larry R. Houchins  
1284 Pulaski - Giles Turnpike  
Pearisburg, Va. 24134

Daytime phone: 540-639-7831  
Evening phone: 540-921-3184  
Cell: 540-239-4429

T.A. set screws altered.  
Trig. works sluggish +  
not returning properly.  
Replace TPA, clean + test fire  
under BCP for \$20.00 + ship


10.00 CASH  
RET'D  
RETURNED TO

CUSTOMER  
TH 9/27/11

Please contact me if there are questions or issues to discuss. The cell is the best way to contact me for the most part.

I appreciate your help in this matter, while the rifle looks great aesthetically, I would really like to be able to use it occasionally.

Best Regards,

  
Larry R. Houchins

RECEIVED  
OCT 04 2011

BY: .....

Serial Number  
A6284442  
Model: 700



RE00241832







