

Remington Arms Co., Inc.
Product Service
Legal Case #:7078

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
250438	12/14/2011	12/15/2011	12/15/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Gary	Lain	2 East Rex Beard Rd	Haughton	LA	71037		H 318-949-1200 E al3242@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fired when ejecting shells	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				
1/11/12 Per note with rifle, he was ejecting the shells and it fired.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	A6264553	LI	2/12/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	COTTER & CO DALLAS TX	TWO PIECE BASE	U			
CONCERN: FIRED WHILE EJECTING SHELLS						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	1/11/2012				
1/11/12 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean and test fire at BLSM program price of \$20 + shipping.cm						

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/15/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 308 WIN
	Date Code		LI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	DIRTY
	Pull	---Select---	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

As I was ejecting the shells this rifle fired.

Please check and repair.

Thanks,

Gary Lain
2 East Rex Beard Rd.
Haughton, LA 71037
Phone: 318-949-1200
Email al3242@yahoo.com

On the email it is AL not a one.


7078

22nd
L12/76
3.5th
1008

Serial
Number:

A6264553

Model: 700



RE00250438

could not duplicate concern.
T.A. dirty + set screws altered
replace TOP, clean test fire
under BCP Con #20. + ship

Quote

RECEIVED
DEC 16 2011

BY:.....



