Remington Arms Co., Inc. Product Service Legal Case #:6988

Case Information

Date Opened(PS) **Incident Date** RE# **Date Opened Date Closed** Pre Lit Lit Obsolete 1/11/2012 12/5/2011 1/12/2012 11/12/2011 253528

Customer Information

Type **Business** First Name Last Name Street City State Zip Contact 41 Ichabod Ln Incident Tom Loucks **Ballston Spa** NY 12020 C 518-361-3645

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause: 4015 Improper Maintenance Unknown S Concern:1007 Fired on Safe Release

C FSR

12/5/11: Customer called in. He stated he was using rifle recently & had a FSR. No damage, No injury, No incident date. His father told him he saw something on TV & needed to send the rifle to Remington for exam. df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type CF/BA 700/3006 SPRG 6749212 KY 5/1/1974 Remington n/a

Date Purchased Where Purchased Accessories **Original Owner**

JERRYS SPORT SHOP OLYPHANT PA004300 TWO PIECE BASE N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Release Date Settlement Release of Claims Reimbursement Settlement APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Repair/Replacement Cost Date \$29

12/5/11: Mailing ARS & forms. Box order# 1280851. df 1/16/12: Per Ilion - Could not duplicate concern. TA dirty & sticky, set screws

altered. Replace TA, clean & test fire under BLM - quote. Customer apprvd & pd quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/12/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	APPEARS ACTION UNDER STOCK IS COVERED WITH GREASE, MAKING PARTS SLUGGISH
Barrel	Description		22" 3006 SPRG
	Date Code		KY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6988&Type=Case

1/25/2012

	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	HAS BEEN BEDDED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.006
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	·
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
Trigger	Pull	Select	6#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description	**************************************	TWO PIECE BASE

lemington®

December 5, 2011

Tom Loucks 41 Ichabod Ln. Ballston Spa, NY 12020 Phone: 518-361-3645

Ref: #6988, Model 700, Serial #6749212

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Fax: 336-548-7872

Phone: 1-800-243-9700 press 0 and ask for ext 8686

BY:

enclosure

³6749212 Model:

could not duplicate con T.A. direty asticky setschous altered. ReplaceTPA, clear + Test under BLP Long 20.45hip Quate

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service

12/05/2011

12/05/2011

Date of Request:

Printed:

Madison, NC 27025-0700

ATTN: Product Service

Date

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number Serial Number / Description

SR00005792

6749212

Customer: TOM LOUCKS 41 ICHABOD LN

BALLSTON SPA, NY 12020 US

Model 700 Center Fire Caliber: 3006

Destination: Arms Services 14 Hoefler Ave

llion, NY 13357 US

Email: Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 6988 - FSR

Parts And Service Details

Material

Type

Description

Qty Needed

Warranty

Price Disc

Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

r	٦.	i.	~+	
r	7	Ш	n	٠.

Reset

Number: 700 30%	Serial Number: 67492/2			
Are you the original owner?: ☐ YES ☑ NO				
lame: HAMAS K. Loucks - ? Received as lift				
Address (no PO Boxes):				
City: Bolloston SPA	State: 15 Zip: 12000			
Phone (Daytime): 5/8-36/_3645	Fax:			
E-mail Address:(if e-mail address is provid be sent)	ed, notification of receipt and shipment will			
E-mail Address: I would like to receive future e-mail updates from Remington.				
Please describe your proble	em and date of occurrence:			
Weapon Discharged When Safety remised to unlood Chamber 11-12-11				
500 ch a	racters left			
Ammunition Information:				
Manufacturer:	Туре:			
Other (i.e. bullet weight/type, shot size, powder):				
Handload Information:				
Powder Used: Powder Weight:				
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size: Reloader Used:				
Firearms Care (Cleaning and Lubrication):				

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

DATE:	12/05/2011	Service Request #	SR00005792
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
Rusiness.			

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

TOM LOUCKS 41 ICHABOD LN

BALLSTON SPA, NY 12020 US

SR00005792

Email:

RETURN ITEM TO:

Arms Services



1 OF 1 DEC 6, 2011 ALL CURR USD ACT WT 10.0 LBS 4XX596 DEC 6, 2011 SVC GNDCOM ACT WT TRACKING# 1Z4XX5969065149981

REF 1:SR00005792 REF 2:

HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 COD 0.00 DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 7.94 SD 0.00 0.00 DGD SP 0.00 7.94 0.00 PR PUB+HANDL ING

ATTN: Product Service