

Remington Arms Co., Inc.
Product Service
Legal Case #:7101

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
249579	12/8/2011	12/19/2011	12/19/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Bill	Moodie	1827 224th St SW	Bophell	WA	98021		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired on safety release	Concern:1007 Fired on Safe Release	Unknown	
C				

1/16/12 Per note on repair, fired when taking safety off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM MAUSER	25629	C6471803	XJ	12/15/1989
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at 1/2 normal cost.						

Repair/Replacement Cost	Repair/Replacement Date

1/16/12 Per Ilion, could not duplicate concern. Trigger assm dirty and rusty. Can offer to replace TPA, clean and test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/19/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 7MM MAUSER
	Date Code		XJ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	--Select--	5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Location

frmREInquiry - Repair Inquiry

Repair Number: RE00249579

Serial: C6471803 Model 700 RIFLE 7MM MAUSER
Produced: 12/15/1989 SKU: 25629

Repairman: Charles Swanson

Verify Repair

Status: Estimating 12/16/2011 10:14:05 AM

7101

ADDRESS INFORMATION

Customer		Received from	Return To	Received from
Name:	BILL MOODIE		BILL MOODIE	
Address 1:	1827 224TH ST S.W.		1827 224TH ST S.W.	
Address 2:	PO Box:		PO Box:	
City:	BOPHELL		BOPHELL	
State:	WA Zip Code: 98021 Country: US		WA Zip Code: 98021 Country: US	

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Code	Desc
M240	BOLT LOCK SAFETY MODIFI...

Problems Found

Code	Desc
M123	FORWARD TO PRODUCT SE...

Repair Notes

fired coming off safe

Repairman's Comments

could not duplicate concern
T.A. dirty & rusty. CAN OPEN TO
replace TPA, clean & test fire
AT 1/2 normal cost.

CSR Comments

per consumer gun fired when he flipped the safety off.

Refresh

Close

C6471803

Model: 700



RE00249579

ILASRP11

Monday, Dec 19 2011

3:49 AM





