

Remington Arms Co., Inc.
Product Service
Legal Case #:6926

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
247779	11/23/2011	11/29/2011	11/29/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ben	Ogletree Jr	2815 Israel Rd	Livingston	TX	77351		H 936-328-6978 E benroyden@livingston.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

12/13/11 Per note with rifle, his rifle has a bolt lock and he was checking to be sure it was unloaded before pting it in the gun case and he clicked the safety to fire and the rifle snapped. It was unloaded. He has not been able to replicate firing by trying several more times. Finger was not even close to the trigger when safety was pushed off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6353109	EI	10/1/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH SHREVEPORT LA	SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire under BLSM program						
	Repair/Replacement Cost	Repair/Replacement Date				
	40.62	12/13/2011				

12/13/11 Per Ilion, trigger assm set screws altered. Trigger not returning. Replace TPA, clean, test fire under BLSM program for \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/29/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 270 WIN
	Date Code		EI
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

6926

22"
EI 10/1
2.5*
.006

Model Number: 700LH		Serial Number: A6353109	
Name: Ben R. Ogletree Jr		Date of Purchase: Late 1970s	
Address (no PO Boxes): 2815 Israel Road			
City: Livingston		State: TX	Zip: 77351
Phone (Daytime): 936-328-6978		Fax: 936-329-7501	
E-mail Address: benroyden@livingston.net			
Please describe your problem: <p>Rifle was laying in truck seat. You cannot open the bolt without clicking safety off. I was checking to be sure it was unloaded before putting it in gun case and I clicked safety to "fire" and the rifle snapped. Luckily it was unloaded. Have not been able to get it to replicate firing by trying several more times. Finger was not even close to trigger when safety was pushed off. I am now pretty spooked about the rifle's safety. What do you recommend in the way of service or further checks?</p> <p style="text-align: right;"><i>T.A. set screws altered, trigger not returning. Up to TX, clean + test. One under BLP for \$10.00 + ship</i></p> <p style="text-align: right;"><i>Quote</i></p>			

0 characters left

firearm, contact the Repair Center for estimated repair time.

A6353109

Model: 700



RE00247779

OR SPENT SHELLS IN YOUR
WITH THE FIREARM. **THIS IS A**
IF YOU FEEL YOU MUST SEND
AND THEM IN A SEPARATE
ADDRESS (WITH ZIP CODE),
SERIAL NUMBER OF YOUR
FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss

RECEIVED
DEC 02 2011

BY: _____







