

Remington Arms Co., Inc.
Product Service
Legal Case #:6710

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
243961	10/20/2011	10/21/2011	10/21/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	NJ State Police		NJ State Police	1600 Negron Dr	Hamilton	NJ	08691		W 609-584-5000, x 5115 E lpp5104@gw.njsp.org

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Slam fires Concern:1008 Fired on Bolt Closing			
C				

10/27/11 Per note with rifle, members of their TEAMS unit advised the armorer unit this weapon has slam fired. TEAMS unit also advised it does not slam fire everytime. This weapon is being returned to Remington for repair.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	20000	G6663449	EB	10/1/2007
Date Purchased	Where Purchased	Accessories	Original Owner			
	LAWMEN SUPPLY		U			

CONCERN: SLAM FIRED

Ammunition Information

Mfg.	Type	Cal./Ga.	SKU	UPC	DOM	Mfg. Code
Federal	BTHP/168	308 WIN				
Concern	Other	Factory	Reload			
0:		Y	N			

Gold Medal Match

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
As a gesture of goodwill will replace TPA, clean and test fire at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	47.40	10/27/2011				

10/27/11 Per Ilion, could not duplicate concern. As a gesture of goodwill and to restore confidence in rifle, will replace TPA, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/21/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 308 WIN PSS
	Date Code		EB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700		Serial Number: G6663449	
Are you the original owner? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: New Jersey State Police		Date of Purchase:	
Address (no PO Boxes): 1600 NEGRIN DR			
City: Hamilton		State: NJ	Zip: 08691
Phone (Daytime): 609-584-5000 ext. 5115		Fax:	
E-mail Address: lpp5104@njsp.org			
<input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
Members of our TEAMS Unit advised the Armorer Unit this weapon has stalled fired. TEAMS Unit also advised it does not stall fire everytime. This weapon being returned to Remington Arms for repair.			
Ammunition Information:			
Manufacturer: Federal Premium		Type: 308 Win	
Other (i.e. bullet weight/type, shot size, powder):		Gold Medal Match	
168 GRAIN SIERRA MATCHKING, BTHP			
Handload Information:			
Powder Weight:			
Primer Used:			
Reloader Used:			
could not duplicate concern. As a Good-Will Gesture and to restore confidence in rifle will			
(of rounds) Replace TPA, clean + post fire			
(of rounds) AT N/C			
(of rounds or Number of rounds) # 260974			
Brand of lubricant used:			

Number: G6663449

Model: 700



RE00243961

Contact Person:

Sgt. N. TALIAN #5104
Armorer Unit

RECEIVED
OCT 26 2011

BY:







