

Remington Arms Co., Inc.
Product Service
Legal Case #:7371

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
257255	2/3/2012	2/6/2012	2/6/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Van's Deer Processing	---	Van's Deer Proc	777 Hwy 468	Brandon	MS	39042		W 601-825-9087

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Unexplained Discharge	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

Dealer sent gun in for consumer. Consumer said gun has gone off without trigger being pulled. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	84373	G6890138	WD	8/26/2009 12:48:48 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH LLC	TWO PIECE BASE	U			

CONCERN:GOES OFF WITHOUT PULLING TRIGGER

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

2/9/12: Per Ilion - TA set screws altered. Trigger not returning. Can offer to replace TA, check over & test fire @ 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/6/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 22-250 REM VTR
	Date Code		WD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIGGER NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SET SCREW ALTERED
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE



Specialty - Smoked Link Sausage

Van's Deer Processing & Sporting Goods

777 Hwy 468 • Brandon, MS 39042 • Ph. 601-825-9087

Name: David Thomas

Date: 1-25-12

Phone: (Home) 601-480-3099

(Work) Meridian, MS

QTY.	ITEMS	PRICE
	Remington 700 VTR	7371
	22-250	
	SN: G6890138	
	2 months old	
	* Customer said gun has	
	gone off without	
	trigger being pulled.	
	<i>XP</i>	

Number:

G6890138

Model: 700



RE00257255

№ 039335

RECEIVED
FEB 09 2012

BY: _____

T.A. set screws altered
TRIG. not returning. CAN
offer to replace TPA, check
over + test fire AT 1/2
normal cost.

Quote

7211
WD8/0
2#
1010





