

Remington Arms Co., Inc.
Product Service
Legal Case #:8102

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
287645	10/30/2012	10/31/2012	10/31/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		David	Fielding	999 Beech Pond Rd	Wolfeboro	NH	03894		E davidthumperfielding@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Discharged when closing the bolt Concern:1008 Fired on Bolt Closing		Unknown	
C				

11/9/12 Per letter with rifle, this gun had an accidental discharge when the bolt was closed. Also, check out the throat area. When he reloads he has to seat the bullets shorter for this gun.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	7/7MM08 REM	24786	7740714	BS	1/9/1998
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC		U			

CONCERN: FBC

Ammunition Information

Mfg.	Type	Cal./Ga.	SKU	UPC	DOM	Mfg. Code
Reloads	/					
Concern	Other	Factory	Reload			
0:		N	Y			

Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, to restore confidence in rifle, offer to replace TPA, clean, test at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date

11/9/12 Per Ilion, could not duplicate concern. To restore confidence in rifle, can offer to replace TPA, clean, test at 1/2 normal cost. Will examine chamber and freebore to make sure within SAAMI specs.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/31/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
	Description		18.5" 7MM08 REM

Barrel	Date Code		BS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	SOME BRASS WASH
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	

8102

Oct. 22, 2012

To Remington:

Enclosed you will find a Model seven, ser. # 7740714 in 7MM-08 caliber. This gun had an "accidental discharge" when the bolt was closed. Please check out the trigger, safety ect. to try to determine the cause.

Also I would like you to check out the throat area. We (my 2 sons & I) all have model 7's in 7MM-08. When I reload I have to seat the bullets shorter for this gun. I use a Hornady Lock + Load O.A.L. gage to get the dimensions.

Below is the dimensions for my rifle & this gun. I also sent you a Barnes & a Speer head so you can check for yourself. The Barnes are our hunting heads & the Speer are our practice heads.

My Gun	This Gun
Barnes 2.902	2.870
Speer 2.798	2.712

(over)

BY:.....

Notice, the Barnes O.A.L. are somewhat close .032 but the Speers O.A.L. are $\therefore$.086 apart. Obviously the "fatter" profile of the Speer doesn't allow the lead to enter the throat area to the same degree as the Barnes. At least that's my assumption, that the throat is of a tighter dia. and not as long. The 3rd gun we own is within .010 on both O.A.L. cartridge dimensions. So, can the chamber area be looked at and if it is tighter & shorter, can it be reamed. Please advise via e-mail about the trigger situation and the throat area.

DAVID FIELDING
999 BEECH POND ROAD
WOLFEBORO NH 03894

SHIP TO:

Thank you,
David Fielding

e-mail davidthumperfielding@gmail.com

Serial
Number:

7740714

Model: SEVEN



RE00287645

could not disp. concern
to restore confidence in rifle
can offer to replace TAP
clean & test at 1/2 normal
cost. will examine chamber
& free bore to make sure
within Sammi Specs.

Q





