

Remington Arms Co., Inc.
Product Service
Legal Case #:7449

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
260209	2/28/2012	2/29/2012	2/29/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Stanley H	James	1809 NYS Rte 22	Essex	NY	12936		H 518-572-6308 E stanjames@wildblue.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired unintentionally Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C				

3/12/12 Per note with rifle, evaluate and repair if eligible under the safety recall. This rifle has fired unintentionally.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/308 WIN	n/a	11744	PL	6/1/1964
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE,AFT MKT STK	U			

CONCERN:FIRE UNINTENTIONALLY

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test under recall at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.81	3/12/2012				

3/12/12 Per lition, could not duplicate concern. Replace TPA, clean, test under recall at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/29/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18/5" 308 WIN
	Date Code		PL
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	---Select---	AFT MKT
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	SAFETY WORKS VERY EASILY
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE,AFT MKT STK

7444

Model Number: 600		Serial Number: 11744	
Name: Stanley H. James		Date of Purchase: 2/23/2012	
Address (no PO Boxes): 1809 NYS RTE 22			
City: Essex	State: NY	Zip: 12936	
Phone (Daytime): 518-572-6308		Fax:	
E-mail Address: stanjames@wildblue.net			
Please describe your problem: I would like my Rem 600, 308 win, evaluated and repaired if eligible under the safety recall. This rifle has fired unintentionally. Thank You, Stan James			
346 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM. THIS IS A YOU FEEL YOU MUST SEND SPENT SEPARATE PACKAGE AND INCLUDE (E), TELEPHONE AND MODEL AND OF YOUR FIREARM. your firearm before sending it. prevent further damage in shipping and preferably, ship in a boxes may not be returned.) or firearm to prevent loss or damage. or UPS or Parcel Post. Remington is not damage or loss to purchase insurance from your carrier.			
Print		Reset	

Serial Number:

11744

Model: 600



RE00260209

18.5"
 PLG/64
 4#
 .00Y

could not dup. concern.
 replace TPA, clean + test
 under recall at N/C.

#250145

RECEIVED
 MAR 02 2012

BY:.....





