

Remington Arms Co., Inc.
Product Service
Legal Case #:7712

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
270553	6/5/2012	6/7/2012	6/7/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Vincent W	Nunez	1005 Fig St	Morgan City	LA	70381		H 985-385-1211 E v.w.nunez@juno.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4054 As received Follows Down		Unknown	
S	Fired when closing bolt Concern:1008 Fired on Bolt Closing			
C				

6/14/12 Per Ilion, replace TPA, clean and test under recall at no charge.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/308 WIN	n/a	6010	LL	2/1/1964
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test under recall at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	112.31	6/14/2012				

6/14/12 Per Ilion, replace TPA, clean, test under recall at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/6/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4054	As received Follows Down	TRIGGER PULL IS BELOW SPECS. SET SCREWS DO NOT APPEAR TO BE ALTERED
Barrel	Description		18.5" 308 WIN VT
	Date Code		LL
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cns03an13200/nsaann/PrintDisplay.aspx?ID=7712&Type=Case

6/14/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Missing	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/600 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.003
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	
	Pull	---Select---	2.5#
	Altered	False	
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Model Number: 600		Serial Number: 6010	
Name: Vincent W. Nunez		Date of Purchase: 1974	
Address (no PO Boxes): 7712 1005 Fig Street			
City: Morgan City	State: LA	Zip: 70381	
Phone (Daytime): 985-385-1211		Fax: 985-385-2828	
E-mail Address: v.w.nunez@juno.com			
Please describe your problem:			
<p>Rifle fired when closing bolt. I notice from your website that there was a 1979 recall for this rifle. As this rifle has been in storagr, untilrecently, since 1978 I am sure that there has been no modifications.</p> <p>I am shipping the rifle without stock and with the bolt removed for convenience.</p> <p>Vincent W. Nunez</p> <p>Trigger guard appears to have been broken during shipping.</p> <p>184 characters left</p>			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			

18.5
262/64
25
003

Serial Number:

6010

Model: 600



RE00270553

VE OR SPENT SHELLS IN YOUR
X WITH THE FIREARM. THIS IS A
YOU FEEL YOU MUST SEND SPENT
SEPARATE PACKAGE AND INCLUDE
JE), TELEPHONE AND MODEL AND
OF YOUR FIREARM.

if your firearm before sending it.
prevent further damage in shipping and
ferably, ship in a

al boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Print

Reset

BY: _____

RECEIVED
JUN 14 2012

264

Replace TPA, clean & test
under recall AT N/C

#230145