

Remington Arms Co., Inc.
Product Service
Legal Case #:7618

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
265705	4/25/2012	4/26/2012	4/26/2012				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	McClelland Gun Shop		McClelland Gun	1533 Centerville Rd	Dallas	TX	75228		W 214-321-0231 E mgsw@sbcglobal.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fires on safety release Concern:1007 Fired on Safe Release			
C				

5/10/12 Per note with rifle, gun occasionally slam fires and also when safety is pushed off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	660/243 WIN	n/a	6236599	KS	5/1/1969
Date Purchased	Where Purchased	Accessories	Original Owner			
	SCHOELLKOPF CO DALLAS TEX	SCOPE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/660/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test at no charge under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.81	5/10/2012				

5/10/12 Per Ilion, trigger assm set screws altered, trigger will not return properly. Replace TPA, clean, test at no charge under recall.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/26/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	WILL REPLACE TPA UNDER RECALL
Barrel	Description		20" 243 WIN
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/660 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIGGER NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Factory Repair Report 7618

McClelland Gun Shop

1533 Centerville Rd., Dallas, Texas 75228

Local: 214/321-0231

Toll Free: 888/ GunGuru Fax: 214/328-1246

email: mgs@sbglobal.net

PO Number

Vendor
Contact Name
Address
City State Zip

Quantity	Make	Model	Gauge	Serial No
1	REMINGTON	600	243	6236599

Customer Complaint

RETURN TO FACTORY - GUN OCCASIONALLY SLAM FIRES AND ALSO WHEN SAFETY IS PUSHED OFF. SHIP
WEAVER MOUNTS.

6236599

Model: 660



RE00265705

RECEIVED
MAY 07 2012

BY:.....

Thursday, April 19, 2012

T.A. set screws & tuned TR19
will not return properly.
Replace TPA, clean & test at
N/c under recall.

230145





