Remington Arms Co., Inc. Product Service Legal Case #:8212

Case Information

RE# Date Opened 290249

11/26/2012

Date Opened(PS) 11/28/2012

Date Closed 11/28/2012

Incident Date

Pre Lit Lit

Obsolete

Customer Information

Business First Name Last Name

Street

City

State Zip Age

Repair

Est.

Contact

Incident

James

Lauver

9769 Corbett Circle

VA 20111 Manassas Park

E Jllauver1@verizon.net

Medical

Status

Incident Information

Claims

PΙ

PD

Cause:4063

Sent in for Evaluation

Position

Concern: 1025 Unexplained Discharge - No Mention of Safety

Codes

Unknown

Medical

Treatment

Gun went off by S itself

C

12/11/12 Per note on SR, consumer insists the gun went off by itself.cm

Firearm Information

Mfg. Remington Type

Model/Ga.

SKU

Serial Bbl.

DOM

Date Purchased

CF/BA

710/3006 SPRG

27410

71171046 PY 6/2/2004 5:09:18 AM

Where Purchased JERRY S SPORT CENTER NORT

Accessories SCOPE BASE

U

Original Owner

CONCERN: WENT OFF BY ITSELF

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash

Reim.

Cash Settlement Date APV Date APV

Per Ilion, check over completely, repair as needed at no charge

> Repair/Replacement Repair/Replacement

Cost

Date

28.00

12/11/2012

12/11/12 Per Ilion, trigger pull below minimum specs. Will follow down. Check over completely, repair as needed at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/28/2012
	Product Type		RF
	Action Type]	A
	Assigned To]	J.BALIO
Cause	4063		TRIG HAS MIN SEAR ENGAGEMENT AND DOES NOT APPEAR TO HAVE BEEN ADJUSTED OUTSIDE OF FACTORY
Barrel	Description		22" 3006 SPRG
	Date Code]	PY
	Bore Plugged	False	·
	Bulged	False	
	Fired	False	
	Fired while		

i	Obstructed	1	
	Muzzle/Crown	Slightly Worn;	1
		Functioning	
<u></u>		Slightly Worn;	
Bolt	Firing Pin	Functioning	
	Shroud	Slightly Worn;	
		Functioning	
		Slightly Worn;	
	acc	Functioning	
	Handle	Slightly Worn;	
		Functioning	
	Stop	Slightly Worn;	•
		Functioning	
	Condition	Slightly Worn;	
		Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	MIN SEAR ENGAGEMENT
	Pull	Select	2#
	Altered	False	
	Sub-Assembly	Other Remington	j

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Number SR00035333

Serial Number / Description

71171046

Model 710 RIFLE

Customer:

JAMES LAUVER 9769 CORBETT CIRCLE

MANASSAS PARK, VA 20111 US

Email: jllauver1@verizon.net

Date of Request; 11/16/2012 Date Printed: 11/16/2012

Arms Services

14 Hoefler Ave

Ilion, NY 13357 US

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M238 - CLEAN & INSPECT (SAFETY PROGRAM ONLY)

Service Request Section

CONSUMER INSISTS THE GUN WENT OFF BY ITSELF

Parts And Service Details

Qty Needed

BY:----

T. pull below min specs.

will Collow down check

over completely hypriness

weeded at M/C

#230145

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s)

Sub Total:

Grand Total:

.00 .00

Est Sales Tax:

\$.00

being sent based on the conversation with our representative.







